Register entry, as of 28 October 2026 Listed for sale Record ID a6f76f061b94

2017 Jeep Wrangler Unlimited Sport

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C4	BJWDG	0	H	L	596656
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jeep · FCA US LLC	Wrangler · 3.6 L	Verified	2017	Toledo	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.6 L, 6 cylinders
Make	Jeep	Fuel	Gasoline
Model	Wrangler	Drive	4WD
Trim	Unlimited Sport	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Toledo, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/wrangler/2017

4 recalls listed by Transport Canada for this model year

Powertrain — 2018422 — 9 Aug 2018

Certain vehicles may have been built with a defective powertrain controller. If the powertrain controller fails while driving the engine may stall, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the powertrain controller.

Powertrain — 2018079 — 8 Feb 2018

Certain vehicles may have a malfunctioning brake switch. This could allow the shifter lever to be shifted out of the PARK (P) position while the ignition is in the RUN mode without depressing the brake pedal, resulting in unintended vehicle movement. As a result, the rear lights could also remain illuminated, causing the following road users to be unaware of the driver's intention. These situations could increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the defective brake switch.

Fuel system — 2016582 — 18 Nov 2016

On certain vehicles, the fuel tank control valve may have been improperly manufactured. An inoperative fuel tank control valve may result in debris in the fuel tank, the ability to overfill the fuel tank during refuelling and/or a fuel leak during a vehicle rollover event. A fuel leak during a vehicle rollover event, in the presence of an ignition source, could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect the fuel tank control valve. Vehicles found with an improperly manufactured fuel tank control valve will have the fuel tank assembly and fuel pump module replaced.

Airbag

2016498 11 Oct 2016

On certain vehicles, the headlamps could rotate during a crash, which could cause the wiring to the front impact sensor to detach prior to a signal being recorded by the Occupant Restraint Controller (ORC). This could result in non-deployment of airbags and pretensioners during a crash where deployment is warranted, which could increase the risk of injury to vehicle occupants. Correction: Dealers will modify the front impact sensor wiring harness and re-route and secure it.

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $17,995[5], $2,840 under the median of $20,835[4].



Lowest ask	$9,999
Middle half	$17,374 – $24,224
Median ask	$20,835
This car	$17,995

Same model year · 64 live listings · as of 28 Oct 2026

OTHER 2017 JEEP WRANGLER LISTINGS [5]

Saint-Félicien, QC · 12,500 km	$26,495
Brampton, ON · 162,250 km	$17,995
Woodstock, ON · 48,213 km	$32,995
Baie-Comeau, QC · 12,500 km	$26,495
Kentville, NS · 175,226 km	$13,349
Airdrie, AB · 51,801 km	$22,850

§4 EVENTS

2017	Model year 2017[1] Assembly plant Toledo, Ohio, United States
11 Oct 2016	Transport Canada recall 2016498[2] Issued for the model year · Airbag
18 Nov 2016	Transport Canada recall 2016582[2] Issued for the model year · Fuel system
8 Feb 2018	Transport Canada recall 2018079[2] Issued for the model year · Powertrain
9 Aug 2018	Transport Canada recall 2018422[2] Issued for the model year · Powertrain

27 Oct 2026	Listed for sale, Oakville, ON[5] SOUTH OAKVILLE CHRYSLER · asking $17,995
28 Oct 2026	Listing last updated[5] asking $17,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 64 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.