Register entry, as of 29 October 2026 Listed for sale Record ID 73f21c6bc34f

2019 Jeep Wrangler Unlimited Sport

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C4	HJXDG	6	K	W	544437
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jeep · FCA US LLC	Wrangler · 3.6 L	Verified	2019	Toledo	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.6 L, 6 cylinders
Make	Jeep	Fuel	Gasoline
Model	Wrangler	Drive	4WD
Trim	Unlimited Sport	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Toledo, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/wrangler/2019

7 recalls listed by Transport Canada for this model year

Lights and instruments

2024504 5 Sep 2024

Issue: On certain vehicles, the instrument panel cluster could stop working. As a result, warnings, tell-tales and gauges may not display. Note: This recall only affects vehicles equipped with a 3.5" instrument cluster panel. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the instrument panel cluster.

Powertrain

2023089 23 Feb 2023

Issue: Under certain conditions, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Vehicles repaired under FCA Canada recalls Y01, Y03 and Y07 (Transport Canada recall 2021-035) also require this repair. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and advise you to tale your vehicle to a dealership to replace the clutch assembly. The dealer will also inspect and, if necessary, update the instrument panel cluster and powertrain control module software.

Powertrain

2021035 28 Jan 2021

Issue: In certain circumstances, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others, and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software. This update will reduce the engine power if the clutch overheats.

Seats and restraints

2020456 25 Sep 2020

Issue: On certain vehicles, there could be a problem with the front seat belt retractors. As a result, the seat belts may not work as designed in a crash. Safety Risk: A seat belt that does not work properly could increase the risk of injury in a crash. Corrective Actions: Fiat Chrysler Automobiles will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front seat belts.

Visual system

2020145 6 Apr 2020

Issue: On certain vehicles, the rearview camera image may be displayed even after the transmission is shifted out of reverse. This could cause a possible distraction for the driver. Canadian regulations require the rearview image to turn off within 10 seconds after shifting from reverse gear. Safety Risk: A driver that is distracted could have an increased risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the radio software.

Powertrain

2020083 3 Mar 2020

Issue: On certain vehicles equipped with a manual transmission, the clutch pressure plate could overheat and break. If this happens, there would be a loss of power to the wheels. A broken pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Safety Risk: A sudden of loss power to the wheels could increase the risk of a crash. Additionally, debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others, and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the clutch system, install a protective hose sleeve, reroute a wire harness, and replace components as necessary

1 more on the model-year record, cardog.app/tools/recalls/jeep/wrangler/2019

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $25,996[5], $250 over the median of $25,746[4].

Lowest ask	$20,998
Middle half	$24,999 – $27,665
Median ask	$25,746
This car	$25,996

Same configuration · 14 live listings · as of 29 Oct 2026

OTHER 2019 JEEP WRANGLER LISTINGS [5]

Orangeville, ON · 135,305 km	$19,995
Edmonton, AB · 52,427 km	$35,649
Winnipeg, MB · 52,427 km	$30,999
Regina, SK · 52,427 km	$30,999
Winnipeg, MB · 52,427 km	$30,999
Surrey, BC · 137,900 km	$31,900

§4 EVENTS

2019	Model year 2019[1] Assembly plant Toledo, Ohio, United States
15 Mar 2019	Transport Canada recall 2019138[2] Issued for the model year · Steering
3 Mar 2020	Transport Canada recall 2020083[2] Issued for the model year · Powertrain
6 Apr 2020	Transport Canada recall 2020145[2] Issued for the model year · Visual system
25 Sep 2020	Transport Canada recall 2020456[2] Issued for the model year · Seats and restraints
28 Jan 2021	Transport Canada recall 2021035[2] Issued for the model year · Powertrain
23 Feb 2023	Transport Canada recall 2023089[2] Issued for the model year · Powertrain
5 Sep 2024	Transport Canada recall 2024504[2] Issued for the model year · Lights and instruments
25 Oct 2026	Listed for sale, Innisfil, ON[5] 400 CHRYSLER DODGE JEEP RAM LTD. · asking $25,996
28 Oct 2026	Listing last updated[5] asking $25,996

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 14 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.