Register entry, as of 29 November 2026 Listed for sale Record ID 2ab22aed217b

2018 Jeep Wrangler Unlimited Sport

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C4	HJXDG	7	J	W	196503
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jeep · FCA US LLC	Wrangler · 3.6 L	Verified	2018	Toledo	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.6 L, 6 cylinders
Make	Jeep	Fuel	Gasoline
Model	Wrangler	Drive	4WD
Trim	Unlimited Sport	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Toledo, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/wrangler/2018

10 recalls listed by Transport Canada for this model year

Lights and instruments

2024504 5 Sep 2024

Issue: On certain vehicles, the instrument panel cluster could stop working. As a result, warnings, tell-tales and gauges may not display. Note: This recall only affects vehicles equipped with a 3.5" instrument cluster panel. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the instrument panel cluster.

Powertrain

2023089 23 Feb 2023

Issue: Under certain conditions, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Vehicles repaired under FCA Canada recalls Y01, Y03 and Y07 (Transport Canada recall 2021-035) also require this repair. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and advise you to tale your vehicle to a dealership to replace the clutch assembly. The dealer will also inspect and, if necessary, update the instrument panel cluster and powertrain control module software.

Powertrain

2021035 28 Jan 2021

Issue: In certain circumstances, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others, and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software. This update will reduce the engine power if the clutch overheats.

Powertrain

2020083 3 Mar 2020

Issue: On certain vehicles equipped with a manual transmission, the clutch pressure plate could overheat and break. If this happens, there would be a loss of power to the wheels. A broken pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Safety Risk: A sudden of loss power to the wheels could increase the risk of a crash. Additionally, debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others, and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the clutch system, install a protective hose sleeve, reroute a wire harness, and replace components as necessary

Visual system

2019302 17 Jun 2019

Issue: On certain vehicles, the liftgate glass may have an incorrect marking. Canadian regulations require a marking to identify the type of glass that is used. Safety Risk: This error is unlikely to affect safety. Corrective Action: This is not a recall. This notice is for information only. The company has made changes to ensure that all new vehicles have glass that is marked correctly.

Steering

2018539 28 Sep 2018

Certain vehicles may have been built with an improperly welded front track bar bracket. This could result in the bracket separating from the frame, which would reduce steering response and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and repair the front track bar bracket welds as necessary. Note: Prior to complete separation of the bracket from the frame, a driver may notice a front end noise, an off-center steering wheel position, a “Service Electronic Stability Control” message and/or Electronic Stability control light on in the instrument cluster.


4 more on the model-year record, cardog.app/tools/recalls/jeep/wrangler/2018

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 14 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,988[5], $4,993 over the median of $21,995[4].



Lowest ask	$14,100
Middle half	$17,371 – $26,740
Median ask	$21,995
This car	$26,988

Same configuration · 10 live listings · as of 29 Nov 2026

OTHER 2018 JEEP WRANGLER LISTINGS [5]

London, ON · 0 km	$18,500
St. Catharines, ON · 129,589 km	$21,999
Hamilton, ON · 122,092 km	$22,499
Lloydminster, AB · 73,339 km	$32,990
Victoria, BC · 129,553 km	$25,931
Montréal, QC · 134,813 km	$16,489

§4 EVENTS

2018	Model year 2018[1] Assembly plant Toledo, Ohio, United States
12 Apr 2018	Transport Canada recall 2018181[2] Issued for the model year · Structure
17 May 2018	Transport Canada recall 2018269[2] Issued for the model year · Engine
25 May 2018	Transport Canada recall 2018281[2] Issued for the model year · Steering
9 Aug 2018	Transport Canada recall 2018422[2] Issued for the model year · Powertrain
28 Sep 2018	Transport Canada recall 2018539[2] Issued for the model year · Steering
17 Jun 2019	Transport Canada recall 2019302[2] Issued for the model year · Visual system
3 Mar 2020	Transport Canada recall 2020083[2] Issued for the model year · Powertrain
28 Jan 2021	Transport Canada recall 2021035[2] Issued for the model year · Powertrain
23 Feb 2023	Transport Canada recall 2023089[2] Issued for the model year · Powertrain
5 Sep 2024	Transport Canada recall 2024504[2] Issued for the model year · Lights and instruments
27 Nov 2026	Listed for sale, Strathroy, ON[5] Dale Wurfel Chrysler Dodge Jeep Ltd. · asking $26,988
28 Nov 2026	Listing last updated[5] asking $26,988

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 10 live listings, as of 29 Nov 2026
[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.