

Register entry, as of 28 October 2026

Listed for sale

Record ID 9047d17f2cd1

# 2019 Jeep Wrangler Unlimited Rubicon

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**1C4 HJXFG 0 K W 548755**

WMI 1-3

Jeep · FCA US LLC

DESCRIPTOR 4-8

Wrangler · 3.6 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

Toledo

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                             |
|------------|-----------------------|--------|-----------------------------|
| Model year | 2019                  | Engine | 3.6 L, 6 cylinders          |
| Make       | Jeep                  | Fuel   | Gasoline                    |
| Model      | Wrangler              | Drive  | 4WD                         |
| Trim       | Unlimited Rubicon     | Maker  | FCA US LLC                  |
| Body       | Sport Utility Vehicle | Plant  | Toledo, Ohio, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/jeep/wrangler/2019](https://cardog.app/tools/recalls/jeep/wrangler/2019)

## 7 recalls listed by Transport Canada for this model year

### Lights and instruments

2024504 5 Sep 2024

Issue: On certain vehicles, the instrument panel cluster could stop working. As a result, warnings, tell-tales and gauges may not display. Note: This recall only affects vehicles equipped with a 3.5" instrument cluster panel. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the instrument panel cluster.

### Powertrain

2023089 23 Feb 2023

Issue: Under certain conditions, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Vehicles repaired under FCA Canada recalls Y01, Y03 and Y07 (Transport Canada recall 2021-035) also require this repair. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the clutch assembly. The dealer will also inspect and, if necessary, update the instrument panel cluster and powertrain control module software.

### Powertrain

2021035 28 Jan 2021

Issue: In certain circumstances, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others, and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software. This update will reduce the engine power if the clutch overheats.



## Seats and restraints

2020456 25 Sep 2020

Issue: On certain vehicles, there could be a problem with the front seat belt retractors. As a result, the seat belts may not work as designed in a crash. Safety Risk: A seat belt that does not work properly could increase the risk of injury in a crash. Corrective Actions: Fiat Chrysler Automobiles will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front seat belts.

## Visual system

2020145 6 Apr 2020

Issue: On certain vehicles, the rearview camera image may be displayed even after the transmission is shifted out of reverse. This could cause a possible distraction for the driver. Canadian regulations require the rearview image to turn off within 10 seconds after shifting from reverse gear. Safety Risk: A driver that is distracted could have an increased risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the radio software.

## Powertrain

2020083 3 Mar 2020

Issue: On certain vehicles equipped with a manual transmission, the clutch pressure plate could overheat and break. If this happens, there would be a loss of power to the wheels. A broken pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Additionally, debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others, and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the clutch system, install a protective hose sleeve, reroute a wire harness, and replace components as necessary.

1 more on the model-year record, [cardog.app/tools/recalls/jeep/wrangler/2019](https://cardog.app/tools/recalls/jeep/wrangler/2019)

Listed for the model year, not checked against your VIN. Jeep confirms which apply.

Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.

[www.mopar.com/en-ca/my-vehicle/recalls/search.html](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$25,500<sup>[5]</sup>, \$577 under the median of \$26,077<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$16,995            |
| Middle half | \$23,223 – \$28,997 |
| Median ask  | \$26,077            |
| This car    | \$25,500            |

Same model year · 78 live listings · as of 28 Oct 2026

## OTHER 2019 JEEP WRANGLER LISTINGS [5]

|                              |          |
|------------------------------|----------|
| Orangeville, ON · 135,305 km | \$19,995 |
| Fredericton, NB · 116,257 km | \$27,998 |
| Red Deer, AB · 96,822 km     | \$29,877 |
| Sundridge, ON · 135,305 km   | \$19,995 |
| Burlington, ON · 86,202 km   | \$25,498 |
| Ottawa, ON · 139,286 km      | \$24,599 |



## §4 EVENTS

|             |                                                                                                      |
|-------------|------------------------------------------------------------------------------------------------------|
| 2019        | Model year 2019 <sup>[1]</sup><br>Assembly plant Toledo, Ohio, United States                         |
| 15 Mar 2019 | Transport Canada recall 2019138 <sup>[2]</sup><br>Issued for the model year · Steering               |
| 3 Mar 2020  | Transport Canada recall 2020083 <sup>[2]</sup><br>Issued for the model year · Powertrain             |
| 6 Apr 2020  | Transport Canada recall 2020145 <sup>[2]</sup><br>Issued for the model year · Visual system          |
| 25 Sep 2020 | Transport Canada recall 2020456 <sup>[2]</sup><br>Issued for the model year · Seats and restraints   |
| 28 Jan 2021 | Transport Canada recall 2021035 <sup>[2]</sup><br>Issued for the model year · Powertrain             |
| 23 Feb 2023 | Transport Canada recall 2023089 <sup>[2]</sup><br>Issued for the model year · Powertrain             |
| 5 Sep 2024  | Transport Canada recall 2024504 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 19 Jan 2026 | Listed for sale, Mirabel, QC <sup>[5]</sup><br>St-Jérôme Chrysler Jeep Dodge Ram · asking \$25,500   |
| 14 Sep 2026 | Window sticker collected <sup>[6]</sup><br>Issued by STELLANTIS                                      |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$25,500                                               |

## §5 DOCUMENTS [6]

|                |                                                                                |
|----------------|--------------------------------------------------------------------------------|
| Window sticker | PDF, issued by STELLANTIS, collected 14 Sep 2026<br>VIN not read from the file |
|----------------|--------------------------------------------------------------------------------|

## SOURCES

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 78 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year | [6] Window sticker, issued by STELLANTIS, collected 14 Sep 2026               |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

