Register entry, as of 27 October 2026 Listed for sale Record ID 6b72dd55b5b7

# 2016 Jeep Cherokee Latitude/Longitude/North

3.2 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1C4 | PJMCS | 2 | G | W | 150229 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Jeep · FCA US LLC | Cherokee · 3.2 L | Verified | 2016 | Toledo | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2016 | Engine | 3.2 L, 6 cylinders |
| Make | Jeep | Fuel | Gasoline |
| Model | Cherokee | Drive | 4WD |
| Trim | Latitude/Longitude/North | Maker | FCA US LLC |
| Body | Sport Utility Vehicle | Plant | Toledo, Ohio, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/cherokee/2016

**11** recalls listed by Transport Canada for this model year

### Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Structure

2023282 11 May 2023

Issue: On certain vehicles, water could leak into the power liftgate control module. If this happens, the control module could short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: FCA Canada will notify owners by mail. The corrective actions for this recall are under development. FCA Canada advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

### Powertrain

2023254 27 Apr 2023

Issue: On certain vehicles with a two-speed power transfer unit (PTU), the input splines on the front differential may wear and fail. If this happens, there could be a loss of power to the wheels. In addition, the PARK position may not hold the vehicle in place. This could allow the vehicle to move unexpectedly when parked. Note: This is an expansion of recall W47 (Transport Canada recall 2020-261). Safety Risk: A vehicle that loses power to the wheels or moves unexpectedly could increase the risk of a crash. Corrective Actions: FCA will notify owners by mail and instruct you to take your vehicle to a dealer to update the software for the power transfer unit. This update will maintain vehicle propulsion by engaging rear wheels if the input splines fail. It will also prevent the vehicle from moving unexpectedly when transmission is in PARK by activating the parking brake.

### Powertrain

2020261 12 Jun 2020

Issue: On certain vehicles with a two-speed power transfer unit (PTU), the input splines on the front differential may wear and fail. If this happens, there could be a loss of power to the wheels. In addition, the PARK position may not hold the vehicle in place. This could allow the vehicle to move unexpectedly when parked. Safety Risk: A vehicle that loses power to the wheels or moves unexpectedly could increase the risk of a crash. Corrective Actions: FCA will notify owners by mail and instruct you to take your vehicle to a dealer to update the software for the power transfer unit. This update will maintain vehicle propulsion by engaging rear wheels if the input splines fail. It will also prevent the vehicle from moving unexpectedly when transmission is in PARK by activating the parking brake.

### Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

### Engine

2018269 17 May 2018

On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the Powertrain Control Module (PCM) software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired.

5 more on the model-year record, cardog.app/tools/recalls/jeep/cherokee/2016

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $10,884[5], $1,813 under the median of $12,697[4].




| | |
|---|---|
| Lowest ask | $7,977 |
| Middle half | $10,124 – $13,482 |
| Median ask | $12,697 |
| This car | $10,884 |

Same configuration · 22 live listings · as of 27 Oct 2026

### OTHER 2016 JEEP CHEROKEE LISTINGS [5]

| | |
|---|---|
| Terrebonne, QC · 209,182 km | $7,977 |
| London, ON · 126,611 km | $10,995 |
| Calgary, AB · 98,549 km | $14,995 |
| Burlington, ON · 153,074 km | $11,988 |
| Longueuil, QC · 214,200 km | $4,990 |
| Lévis, QC · 134,000 km | $9,480 |

## §4 EVENTS

| | |
|---|---|
| 2016 | Model year 2016[1]<br>Assembly plant Toledo, Ohio, United States |
| 9 Dec 2015 | Transport Canada recall 2015588[2]<br>Issued for the model year · Accessories |
| 12 May 2016 | Transport Canada recall 2016220[2]<br>Issued for the model year · Powertrain |
| 12 May 2016 | Transport Canada recall 2016219[2]<br>Issued for the model year · Powertrain |
| 10 Aug 2016 | Transport Canada recall 2016393[2]<br>Issued for the model year · Seats and restraints |
| 22 Dec 2017 | Transport Canada recall 2017663[2]<br>Issued for the model year · Accessories |
| 17 May 2018 | Transport Canada recall 2018269[2]<br>Issued for the model year · Engine |
| 21 Aug 2019 | Transport Canada recall 2019420[2]<br>Issued for the model year · Other |
| 12 Jun 2020 | Transport Canada recall 2020261[2]<br>Issued for the model year · Powertrain |
| 27 Apr 2023 | Transport Canada recall 2023254[2]<br>Issued for the model year · Powertrain |
| 11 May 2023 | Transport Canada recall 2023282[2]<br>Issued for the model year · Structure |
| 15 Aug 2024 | Transport Canada recall 2024548[2]<br>Issued for the model year · Label |
| 26 Oct 2026 | Listed for sale, Ottawa, ON[5]<br>Car-On Auto Sales · asking $10,884 |

## §5 DOCUMENTS

Window sticker — We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 22 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.