Register entry, as of 28 October 2026 Listed for sale Record ID 6f3e6eaf45ea

2019 Jeep Cherokee Limited

3.2 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C4	PJMDX	4	K	D	448666
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jeep · FCA US LLC	Cherokee · 3.2 L	Verified	2019	Belvidere	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.2 L, 6 cylinders
Make	Jeep	Fuel	Gasoline
Model	Cherokee	Drive	4WD
Trim	Limited	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Belvidere, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/cherokee/2019

11 recalls listed by Transport Canada for this model year

Powertrain — 2026224 — 7 May 2026

Issue: On certain vehicles, the power transfer unit (PTU) could become damaged and fail. If this happens, there could be a loss of power to the wheels and/or the vehicle could move when it's parked and the parking brake isn't applied. Note: This recall only affects certain vehicles equipped with a two-speed PTU. Safety Risk: A loss of power to the wheels or a parked vehicle that moves suddenly could create the risk of an injury and/or a crash. Corrective Actions: FCA Canada will notify owners in writing. The corrective actions for this recall are under development.

Powertrain — 2025012 — 16 Jan 2025

Issue: On certain vehicles, the input shaft snap ring in the power transfer unit (PTU) may not have been installed properly. As a result, the PTU could become damaged and fail. If this happens, there could be a loss of power to the wheels and/or the vehicle could move when it's parked and the parking brake isn't applied. Note: This recall only affects certain vehicles equipped with a two-speed PTU. Safety Risk: A loss of power to the wheels or a parked vehicle that moves suddenly could create the risk of an injury and/or a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the drivetrain control module and install a diagnostic software that will monitor the PTU and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange for the replacement of the PTU.

Label — 2024548 — 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Visual system

2020145 6 Apr 2020

Issue: On certain vehicles, the rearview camera image may be displayed even after the transmission is shifted out of reverse. This could cause a possible distraction for the driver. Canadian regulations require the rearview image to turn off within 10 seconds after shifting from reverse gear. Safety Risk: A driver that is distracted could have an increased risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the radio software.

Steering

2019440 30 Aug 2019

Issue: Certain vehicles may have been built with a gear in the steering rack that was not properly hardened. As a result, the gear could break and cause a loss of steering. Safety Risk: A loss of steering control could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to replace the steering gear.

Airbag

2019295 14 Jun 2019

Issue: On certain vehicles, a problem with the airbag sensors could cause the airbag system not to properly detect certain types of crashes. This problem could result in the airbags not deploying properly in a crash. Note: This problem would cause the airbag warning light to stay on in the instrument cluster. Safety Risk: Airbags that do not deploy properly in a crash could increase the risk of injury. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the affected sensors. If your airbag warning light stays on, you should contact a local dealership and have your vehicle serviced immediately.

5 more on the model-year record, cardog.app/tools/recalls/jeep/cherokee/2019

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,392[5], $4,603 under the median of $14,995[4].



Lowest ask	$9,588
Middle half	$12,493 – $20,980
Median ask	$14,995
This car	$10,392

Same configuration · 11 live listings · as of 28 Oct 2026

OTHER 2019 JEEP CHEROKEE LISTINGS [5]

Rouyn-Noranda, QC · 170,056 km	$16,995
Kitchener, ON · 154,415 km	$19,879
Kingston, ON · 129,493 km	$15,295
Lévis, QC · 130,000 km	$18,980
Waterloo, ON · 104,000 km	$20,995
Nipawin, SK · 151,786 km	$16,899

§4 EVENTS

2019 Model year 2019[1]
Assembly plant Belvidere, Illinois, United States

25 May 2018	Transport Canada recall 2018282[2] Issued for the model year · Engine
9 Aug 2018	Transport Canada recall 2018422[2] Issued for the model year · Powertrain
9 Aug 2018	Transport Canada recall 2018421[2] Issued for the model year · Brakes
19 Oct 2018	Transport Canada recall 2018573[2] Issued for the model year · Engine
29 Mar 2019	Transport Canada recall 2019160[2] Issued for the model year · Seats and restraints
14 Jun 2019	Transport Canada recall 2019295[2] Issued for the model year · Airbag
30 Aug 2019	Transport Canada recall 2019440[2] Issued for the model year · Steering
6 Apr 2020	Transport Canada recall 2020145[2] Issued for the model year · Visual system
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
16 Jan 2025	Transport Canada recall 2025012[2] Issued for the model year · Powertrain
7 May 2026	Transport Canada recall 2026224[2] Issued for the model year · Powertrain
27 Oct 2026	Listed for sale, Toronto, ON[5] Midtown Honda · asking $10,392
28 Oct 2026	Listing last updated[5] asking $10,392

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 11 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.