Register entry, as of 29 October 2026 Listed for sale Record ID 8591f548480a

# 2026 Jeep Wrangler Rubicon

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1C4 | PJXFN | 2 | T | W | 190070 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Jeep · FCA US LLC | Wrangler · 2.0 L | Verified | 2026 | Toledo | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2026 | Engine | 2.0 L, 4 cylinders |
| Make | Jeep | Fuel | Gasoline |
| Model | Wrangler | Drive | 4WD |
| Trim | Rubicon | Maker | FCA US LLC |
| Body | Sport Utility Vehicle | Plant | Toledo, Ohio, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/wrangler/2026

**3** recalls listed by Transport Canada for this model year

### Visual system

2026396 13 Aug 2026

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall also affects Grand Cherokee L models and Grand Wagoneer L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and send a wireless over-the-air software update to eligible vehicles to update the radio software. Alternatively, you may schedule an appointment to have the update performed at an FCA dealership.

### Wheels

2026346 16 Jul 2026

Issue: On certain vehicles, the steel wheel(s) may not have been manufactured properly. As a result, the wheel(s) could crack and separate, causing a loss of control. Safety Risk: A loss of control could create the risk of a crash. A wheel that separates could create a road hazard for others. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the steel wheel(s) and valve stem(s).

### Seats and restraints

2026178 9 Apr 2026

Issue: On a small number of vehicles, the upper tether anchorage for installing a child car seat may not have been properly welded to the right-hand (passenger side) second-row seatback frame. As a result, the child seat tether strap could detach in a crash. Safety Risk: A child seat that is not properly secured could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the right hand (passenger side) second-row seat back frame.

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $52,684[5], $3,116 under the median of $55,800[4].

| | |
|---|---|
| Lowest ask | $48,995 |
| Middle half | $53,940 – $77,304 |
| Median ask | $55,800 |
| This car | $52,684 |

Same configuration · 64 live listings · as of 29 Oct 2026

### OTHER 2026 JEEP WRANGLER LISTINGS [5]

| | |
|---|---|
| Milton, ON · 11 km | $58,779 |
| Edmonton, AB · 0 km | $98,204 |
| Kingston, ON · 0 km | $64,225 |
| Belleville, ON · 15,889 km | $44,995 |
| Orangeville, ON · 18,733 km | $37,971 |
| Saskatoon, SK · 313 km | $93,881 |

## §4 EVENTS

| | |
|---|---|
| 2026 | Model year 2026[1]<br>Assembly plant Toledo, Ohio, United States |
| 9 Apr 2026 | Transport Canada recall 2026178[2]<br>Issued for the model year · Seats and restraints |
| 16 Jul 2026 | Transport Canada recall 2026346[2]<br>Issued for the model year · Wheels |
| 13 Aug 2026 | Transport Canada recall 2026396[2]<br>Issued for the model year · Visual system |
| 25 Oct 2026 | Listed for sale, Calgary, AB[5]<br>Capital Chevrolet Buick GMC Calgary · asking $52,684 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $52,684 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 64 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.