Register entry, as of 27 October 2026 Listed for sale Record ID 24cc719e6f28

# 2018 Dodge Durango GT

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1C4 | RDJDG | 0 | J | C | 400794 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Dodge · FCA US LLC | Durango · 3.6 L | Verified | 2018 | Detroit | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2018 | Engine | 3.6 L, 6 cylinders |
| Make | Dodge | Fuel | Gasoline |
| Model | Durango | Drive | AWD |
| Trim | GT | Maker | FCA US LLC |
| Body | Sport Utility Vehicle | Plant | Detroit, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/durango/2018

**6** recalls listed by Transport Canada for this model year

### Brakes

2024677 7 Nov 2024

Issue: On certain vehicles, the recall repairs completed by an FCA dealer during recall Z48 (Transport Canada recall no. 2022-305) may not be effective. As a result, a second repair is required. On certain vehicles, a problem inside the hydraulic control unit (HCU) for the antilock brake system (ABS) could cause the ABS and electronic stability control (ESC) system not to work. This could also cause the brake lights to turn on or stay on without pressing the brake pedal, and it may allow the vehicle to be started and the transmission to be shifted out of the Park position (P) without pressing the brake pedal. Safety Risk: An antilock braking system and/or electronic stability control system that doesn't work could increase the risk of a crash. A parked vehicle that moves suddenly could create the risk of an injury or a crash. Brake lights that stay on could cause others not to recognize when the vehicle is braking and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the integrated pressure transducer on the HCU. The dealer will also update the ABS software, if necessary.

### Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Brakes

2022305 9 Jun 2022

Issue: On certain vehicles, there may be a problem inside the hydraulic control unit for the antilock brake system. As a result, it may be possible to start the vehicle and shift the transmission out of the Park position (P) without pressing the brake pedal. If this happens, the vehicle could move suddenly. This problem could also cause the brake lights to turn on or stay on without pressing the brake pedal. Safety Risk: A vehicle that moves suddenly could increase the risk of a crash. Brake lights that stay on could cause others not to recognize when the vehicle is braking, and could also increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail. The corrective actions for this recall are under development.

### Powertrain

2018422 9 Aug 2018

Certain vehicles may have been built with a defective powertrain controller. If the powertrain controller fails while driving the engine may stall, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the powertrain controller.

### Engine

2018269 17 May 2018

On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the Powertrain Control Module (PCM) software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired.

### Powertrain

2018223 1 May 2018

On certain vehicles equipped with an 8-speed transmission, an incorrect park lock rod may have been installed during the transmission assembly process. This could cause the transmission to lose the Park function, which could result in unintended vehicle movement, which would increase the risk of crash causing injury and/or damage to property. Correction: Dealers will replace the park lock rods.

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $21,995[5], $4 under the median of $21,999[4].

| | |
|---|---|
| Lowest ask | $12,980 |
| Middle half | $19,999 – $25,760 |
| Median ask | $21,999 |
| This car | $21,995 |

Same configuration · 17 live listings · as of 27 Oct 2026

### OTHER 2018 DODGE DURANGO LISTINGS [5]

| | |
|---|---|
| Westlock, AB · 200,000 km | $26,987 |
| Cold Lake, AB · 193,123 km | $17,998 |
| Lacombe, AB · 121,725 km | $26,999 |
| Lethbridge, AB · 165,855 km | $24,990 |
| Sherwood Park, AB · 141,851 km | $25,906 |
| Uxbridge, ON · 98,678 km | $25,760 |

## §4 EVENTS

| | |
|---|---|
| 2018 | Model year 2018[1]<br>Assembly plant Detroit, Michigan, United States |
| 1 May 2018 | Transport Canada recall 2018223[2]<br>Issued for the model year · Powertrain |
| 17 May 2018 | Transport Canada recall 2018269[2]<br>Issued for the model year · Engine |
| 9 Aug 2018 | Transport Canada recall 2018422[2]<br>Issued for the model year · Powertrain |
| 9 Jun 2022 | Transport Canada recall 2022305[2]<br>Issued for the model year · Brakes |
| 15 Aug 2024 | Transport Canada recall 2024548[2]<br>Issued for the model year · Label |
| 7 Nov 2024 | Transport Canada recall 2024677[2]<br>Issued for the model year · Brakes |
| 25 Oct 2026 | Listed for sale, Prince George, BC[5]<br>Subaru Of Prince George · asking $21,995 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $21,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 17 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.