Register entry, as of 28 October 2026 Listed for sale Record ID 1f6ee9c11ed3

# 2019 Jeep Grand Cherokee Laredo

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1C4 | RJFAG | 6 | K | C | 822127 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Jeep · FCA US LLC | Grand Cherokee · 3.6 L | Verified | 2019 | Detroit | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 3.6 L, 6 cylinders |
| Make | Jeep | Fuel | Gasoline |
| Model | Grand Cherokee | Drive | 4WD |
| Trim | Laredo | Maker | FCA US LLC |
| Body | Sport Utility Vehicle | Plant | Detroit, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/grand-cherokee/2019

**10** recalls listed by Transport Canada for this model year

### Brakes

2024677 7 Nov 2024

Issue: On certain vehicles, the recall repairs completed by an FCA dealer during recall Z48 (Transport Canada recall no. 2022-305) may not be effective. As a result, a second repair is required. On certain vehicles, a problem inside the hydraulic control unit (HCU) for the antilock brake system (ABS) could cause the ABS and electronic stability control (ESC) system not to work. This could also cause the brake lights to turn on or stay on without pressing the brake pedal, and it may allow the vehicle to be started and the transmission to be shifted out of the Park position (P) without pressing the brake pedal. Safety Risk: An antilock braking system and/or electronic stability control system that doesn't work could increase the risk of a crash. A parked vehicle that moves suddenly could create the risk of an injury or a crash. Brake lights that stay on could cause others not to recognize when the vehicle is braking and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the integrated pressure transducer on the HCU. The dealer will also update the ABS software, if necessary.

### Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Engine

2023338 8 Jun 2023

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Note: Vehicles included in FCA recall W58 (Transport Canada recall 2020-371) are not part of this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

### Brakes

2022305 9 Jun 2022

Issue: On certain vehicles, there may be a problem inside the hydraulic control unit for the antilock brake system. As a result, it may be possible to start the vehicle and shift the transmission out of the Park position (P) without pressing the brake pedal. If this happens, the vehicle could move suddenly. This problem could also cause the brake lights to turn on or stay on without pressing the brake pedal. Safety Risk: A vehicle that moves suddenly could increase the risk of a crash. Brake lights that stay on could cause others not to recognize when the vehicle is braking, and could also increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail. The corrective actions for this recall are under development.

### Fuel system

2022303 9 Jun 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.

### Engine

2020544 12 Nov 2020

Issue: On certain vehicles equipped with a 3.0-L EcoDiesel engine, the exhaust gas recirculation (EGR) cooler could crack internally and leak. If this happens, a driver may notice a low coolant level or a heater that does not work properly. Safety Risk: A cracked EGR cooler could create the risk of an engine fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to replace the EGR cooler. Dealers will also inspect intake manifold and replace it as necessary.

4 more on the model-year record, cardog.app/tools/recalls/jeep/grand-cherokee/2019

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $20,977[5], $1,011 under the median of $21,988[4].

| | |
|---|---|
| Lowest ask | $11,990 |
| Middle half | $19,956 – $23,122 |
| Median ask | $21,988 |
| This car | $20,977 |

Same configuration · 32 live listings · as of 28 Oct 2026

### OTHER 2019 JEEP GRAND CHEROKEE LISTINGS [5]

| | |
|---|---|
| Toronto, ON · 150,526 km | $25,795 |
| Kitchener, ON · 79,924 km | $29,999 |
| Regina, SK · 88,168 km | $25,996 |
| Regina, SK · 88,168 km | $25,996 |

| | |
|---|---|
| Brantford, ON · 172,658 km | $20,900 |
| Vanderhoof, BC · 91,041 km | $26,995 |

## §4 EVENTS

| | |
|---|---|
| 2019 | Model year 2019[1]<br>Assembly plant Detroit, Michigan, United States |
| 21 Aug 2019 | Transport Canada recall 2019420[2]<br>Issued for the model year · Other |
| 27 Mar 2020 | Transport Canada recall 2020132[2]<br>Issued for the model year · Powertrain |
| 6 Apr 2020 | Transport Canada recall 2020145[2]<br>Issued for the model year · Visual system |
| 13 Aug 2020 | Transport Canada recall 2020371[2]<br>Issued for the model year · Engine |
| 12 Nov 2020 | Transport Canada recall 2020544[2]<br>Issued for the model year · Engine |
| 9 Jun 2022 | Transport Canada recall 2022305[2]<br>Issued for the model year · Brakes |
| 9 Jun 2022 | Transport Canada recall 2022303[2]<br>Issued for the model year · Fuel system |
| 8 Jun 2023 | Transport Canada recall 2023338[2]<br>Issued for the model year · Engine |
| 15 Aug 2024 | Transport Canada recall 2024548[2]<br>Issued for the model year · Label |
| 7 Nov 2024 | Transport Canada recall 2024677[2]<br>Issued for the model year · Brakes |
| 20 Aug 2026 | Listed for sale, Calgary, AB[5]<br>Auto Avenue · asking $20,977 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $20,977 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 32 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.