Register entry, as of 29 October 2026 Listed for sale Record ID 67a39f4217ed

2012 Jeep Grand Cherokee Laredo

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Flexible Fuel Vehicle (FFV)

VEHICLE IDENTIFICATION NUMBER [1]

1C4	RJFAG	7	C	C	287259
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jeep · FCA US LLC	Grand Cherokee · 3.6 L	Verified	2012	Detroit	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	3.6 L, 6 cylinders
Make	Jeep	Fuel	Flexible Fuel Vehicle (FFV)
Model	Grand Cherokee	Drive	4WD
Trim	Laredo	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Detroit, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/grand-cherokee/2012

11 recalls listed by Transport Canada for this model year

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Fuel system

2019573 14 Nov 2019

Issue: On certain vehicles, the fuel pump relay could fail. A fuel pump relay failure can result in a no-start condition or cause a sudden loss of engine power while driving. Note: Vehicles that had a fuel pump relay replaced as part of a Transport Canada Recall No. 2014-386 (FCA Recall No. P54) or 2015-085 (R09) require a second repair under this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump relay, mounting bracket and related wiring.

Brakes

2017450 18 Sep 2017

On certain vehicles, a brake booster shield may have been incorrectly installed as part of recall P14/2014-112. An incorrectly installed shield could be less effective in diverting water away from the brake booster, creating the possibility of corrosion allowing water to get inside. In a cold climate, water inside the brake booster could freeze limiting the braking ability of the vehicle, resulting in longer braking distances, increasing the risk of crash causing injury and/or damage to property. Correction: Dealers will inspect the installation of the brake booster shield and perform repairs as necessary.

Electrical

2017341 10 Jul 2017

On certain vehicles equipped with electro-hydraulic power steering ("EHPS"), the alternator may fail suddenly. This could result in the engine stalling, causing a loss of motive power which could increase the risk of a crash as well as disable various vehicle safety systems, and could also cause a fire. Both issues could increase the risk of injury and/or damage to property. Correction: Dealers will inspect the part number on the alternator, and will replace the alternator as necessary. Note: Only specific engine and alternator combinations are affected by this campaign.

Electrical

2015615 22 Dec 2015

On certain vehicles equipped with illuminated sun visor vanity mirrors with 120mm wiring, service repairs requiring removal of the sun visors and/or headliner may cause an electrical short circuit which could increase the risk of a fire causing injury and/or damage to property. Vehicles equipped with 120mm wiring that were previously repaired under recall 2014-275 will require repair under this recall. Correction: Dealers will replace the sun visors and modify the surrounding sheet metal and install vanity lamp wiring guides.

Fuel system

2015085 26 Feb 2015

This recall was replaced by Transport Canada Recall No. 2019-573 (FCA Recall No. V62). On certain vehicles, a fuel pump relay within the Totally Integrated Power Module (TIPM-7) could fail, causing the engine to stall or to fail to start. Engine stalling would result in a loss of motive power, which, in conjunction with driver reactions and traffic conditions, could increase the risk of a crash resulting in injury and/or damage to property. Correction: Dealers will install a revised fuel pump relay external to the TIPM-7.

5 more on the model-year record, cardog.app/tools/recalls/jeep/grand-cherokee/2012

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,995[5], the median[4].



Lowest ask	$5,999
Middle half	$6,995 – $7,980
Median ask	$6,995
This car	$6,995

Same model year · 9 live listings · as of 29 Oct 2026

OTHER 2012 JEEP GRAND CHEROKEE LISTINGS [5]

Vaughan, ON · 221,132 km	$4,898
Calgary, AB · 281,672 km	$6,000
Trois-Rivières, QC · 241,400 km	$6,995
Boisbriand, QC · 187,000 km	$6,995
Montréal Nord, QC · 127,165 km	$9,998
North Vancouver District, BC · 180,520 km	$11,999

§4 EVENTS

2012 **Model year 2012**[1]
Assembly plant Detroit, Michigan, United States

27 Sep 2011	Transport Canada recall 2011351[2] Issued for the model year · Engine
5 Mar 2014	Transport Canada recall 2014070[2] Issued for the model year · Brakes
2 Apr 2014	Transport Canada recall 2014112[2] Issued for the model year · Brakes
3 Jul 2014	Transport Canada recall 2014275[2] Issued for the model year · Electrical
9 Oct 2014	Transport Canada recall 2014446[2] Issued for the model year · Electrical
26 Feb 2015	Transport Canada recall 2015085[2] Issued for the model year · Fuel system
22 Dec 2015	Transport Canada recall 2015615[2] Issued for the model year · Electrical
10 Jul 2017	Transport Canada recall 2017341[2] Issued for the model year · Electrical
18 Sep 2017	Transport Canada recall 2017450[2] Issued for the model year · Brakes
14 Nov 2019	Transport Canada recall 2019573[2] Issued for the model year · Fuel system
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
17 Oct 2026	Listed for sale, Toronto, ON[5] SCARBORO E AUTO LIMITED · asking $6,995
28 Oct 2026	Listing last updated[5] asking $6,995

§5 DOCUMENTS

Window sticker — This VIN reads as model year 1982 or 2012, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 9 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.