Register entry, as of 29 October 2026 Listed for sale Record ID 8026c799cba8

2019 Jeep Grand Cherokee Limited

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C4	RJFBG	7	K	C	645747
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jeep · FCA US LLC	Grand Cherokee · 3.6 L	Verified	2019	Detroit	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.6 L, 6 cylinders
Make	Jeep	Fuel	Gasoline
Model	Grand Cherokee	Drive	4WD
Trim	Limited	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Detroit, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/grand-cherokee/2019

10 recalls listed by Transport Canada for this model year

Brakes

2024677 7 Nov 2024

Issue: On certain vehicles, the recall repairs completed by an FCA dealer during recall Z48 (Transport Canada recall no. 2022-305) may not be effective. As a result, a second repair is required. On certain vehicles, a problem inside the hydraulic control unit (HCU) for the antilock brake system (ABS) could cause the ABS and electronic stability control (ESC) system not to work. This could also cause the brake lights to turn on or stay on without pressing the brake pedal, and it may allow the vehicle to be started and the transmission to be shifted out of the Park position (P) without pressing the brake pedal. Safety Risk: An antilock braking system and/or electronic stability control system that doesn't work could increase the risk of a crash. A parked vehicle that moves suddenly could create the risk of an injury or a crash. Brake lights that stay on could cause others not to recognize when the vehicle is braking and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the integrated pressure transducer on the HCU. The dealer will also update the ABS software, if necessary.

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Engine

2023338 8 Jun 2023

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Note: Vehicles included in FCA recall W58 (Transport Canada recall 2020-371) are not part of this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

Brakes

2022305 9 Jun 2022

Issue: On certain vehicles, there may be a problem inside the hydraulic control unit for the antilock brake system. As a result, it may be possible to start the vehicle and shift the transmission out of the Park position (P) without pressing the brake pedal. If this happens, the vehicle could move suddenly. This problem could also cause the brake lights to turn on or stay on without pressing the brake pedal. Safety Risk: A vehicle that moves suddenly could increase the risk of a crash. Brake lights that stay on could cause others not to recognize when the vehicle is braking, and could also increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail. The corrective actions for this recall are under development.

Fuel system

2022303 9 Jun 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.

Engine

2020544 12 Nov 2020

Issue: On certain vehicles equipped with a 3.0-L EcoDiesel engine, the exhaust gas recirculation (EGR) cooler could crack internally and leak. If this happens, a driver may notice a low coolant level or a heater that does not work properly. Safety Risk: A cracked EGR cooler could create the risk of an engine fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to replace the EGR cooler. Dealers will also inspect intake manifold and replace it as necessary.

4 more on the model-year record, cardog.app/tools/recalls/jeep/grand-cherokee/2019

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $21,419[5], $3,577 under the median of $24,996[4].

Lowest ask	$19,498
Middle half	$21,921 – $26,995
Median ask	$24,996
This car	$21,419

Same configuration · 20 live listings · as of 29 Oct 2026

OTHER 2019 JEEP GRAND CHEROKEE LISTINGS [5]

Sault Sainte Marie, ON · 92,025 km	$26,699
Edmonton, AB · 88,168 km	$25,996
Edmonton, AB · 165,838 km	$25,530
Edmonton, AB · 83,163 km	$29,999

Winnipeg, MB · 88,168 km	$27,785
Winnipeg, MB · 165,838 km	$22,200

§4 EVENTS

2019	Model year 2019[1] Assembly plant Detroit, Michigan, United States
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
27 Mar 2020	Transport Canada recall 2020132[2] Issued for the model year · Powertrain
6 Apr 2020	Transport Canada recall 2020145[2] Issued for the model year · Visual system
13 Aug 2020	Transport Canada recall 2020371[2] Issued for the model year · Engine
12 Nov 2020	Transport Canada recall 2020544[2] Issued for the model year · Engine
9 Jun 2022	Transport Canada recall 2022305[2] Issued for the model year · Brakes
9 Jun 2022	Transport Canada recall 2022303[2] Issued for the model year · Fuel system
8 Jun 2023	Transport Canada recall 2023338[2] Issued for the model year · Engine
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
7 Nov 2024	Transport Canada recall 2024677[2] Issued for the model year · Brakes
26 Oct 2026	Listed for sale, North Bay, ON[5] North Bay Mazda · asking $21,419
29 Oct 2026	Listing last updated[5] asking $21,419

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 20 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.