Register entry, as of 29 October 2026 Listed for sale Record ID 6f2f784b47cc

2014 Jeep Grand Cherokee SRT

6.4 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C4	RJFDJ	7	E	C	482062
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jeep · FCA US LLC	Grand Cherokee · 6.4 L	Verified	2014	Detroit	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	6.4 L, 8 cylinders
Make	Jeep	Fuel	Gasoline
Model	Grand Cherokee	Drive	4WD
Trim	SRT	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Detroit, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/grand-cherokee/2014

19 recalls listed by Transport Canada for this model year

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Engine

2023338 8 Jun 2023

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Note: Vehicles included in FCA recall W58 (Transport Canada recall 2020-371) are not part of this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

Fuel system

2022303 9 Jun 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.

Engine

2020544 12 Nov 2020

Issue: On certain vehicles equipped with a 3.0-L EcoDiesel engine, the exhaust gas recirculation (EGR) cooler could crack internally and leak. If this happens, a driver may notice a low coolant level or a heater that does not work properly. Safety Risk: A cracked EGR cooler could create the risk of an engine fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to replace the EGR cooler. Dealers will also inspect intake manifold and replace it as necessary.

Engine

2020371 13 Aug 2020

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

13 more on the model-year record, cardog.app/tools/recalls/jeep/grand-cherokee/2014

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 19 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $27,570[5], $13,832 over the median of $13,738[4].

Lowest ask	$5,999
Middle half	$11,224 – $15,438
Median ask	$13,738
This car	$27,570

Same model year · 34 live listings · as of 29 Oct 2026

OTHER 2014 JEEP GRAND CHEROKEE LISTINGS [5]

Edmonton, AB · 148,613 km	$14,999
Vaughan, ON · 175,889 km	$12,898
Okotoks, AB · 222,717 km	$14,389
Calgary, AB · 163,671 km	$36,998
Prince George, BC · 121,882 km	$17,909
Vancouver, BC · 176,579 km	$11,998

§4 EVENTS

2014	Model year 2014[1] Assembly plant Detroit, Michigan, United States
4 Jul 2013	Transport Canada recall 2013234[2] Issued for the model year · Lights and instruments
2 Oct 2013	Transport Canada recall 2013343[2] Issued for the model year · Electrical
2 Apr 2014	Transport Canada recall 2014112[2] Issued for the model year · Brakes
4 Jun 2014	Transport Canada recall 2014207[2] Issued for the model year · Accessories
3 Jul 2014	Transport Canada recall 2014275[2] Issued for the model year · Electrical
9 Oct 2014	Transport Canada recall 2014448[2] Issued for the model year · Electrical
9 Oct 2014	Transport Canada recall 2014446[2] Issued for the model year · Electrical
16 Oct 2014	Transport Canada recall 2014457[2] Issued for the model year · Seats and restraints
26 Apr 2016	Transport Canada recall 2016184[2] Issued for the model year · Powertrain
10 Jul 2017	Transport Canada recall 2017341[2] Issued for the model year · Electrical
18 Sep 2017	Transport Canada recall 2017450[2] Issued for the model year · Brakes
22 Nov 2017	Transport Canada recall 2017574[2] Issued for the model year · Electrical
17 May 2018	Transport Canada recall 2018269[2] Issued for the model year · Engine
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
13 Aug 2020	Transport Canada recall 2020371[2] Issued for the model year · Engine
12 Nov 2020	Transport Canada recall 2020544[2] Issued for the model year · Engine
9 Jun 2022	Transport Canada recall 2022303[2] Issued for the model year · Fuel system

8 Jun 2023	Transport Canada recall 2023338[2] Issued for the model year · Engine
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
22 Aug 2026	Listed for sale, Cranbrook, BC[5] Cranbrook Dodge · asking $27,570
28 Oct 2026	Listing last updated[5] asking $27,570

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 34 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.