Register entry, as of 29 October 2026 Listed for sale Record ID 9d33dbe09ef1

2021 Jeep Grand Cherokee Summit

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C4	RJFJG	7	M	C	530991
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jeep · FCA US LLC	Grand Cherokee · 3.6 L	Verified	2021	Detroit	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.6 L, 6 cylinders
Make	Jeep	Fuel	Gasoline
Model	Grand Cherokee	Drive	4WD
Trim	Summit	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Detroit, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/grand-cherokee/2021

17 recalls listed by Transport Canada for this model year

Suspension

2026418 1 Sep 2026

Issue: On certain vehicles, the recall repairs completed by an FCA dealer during recalls 64A and 20D (Transport Canada recall nos. 2023-336 and 2026-037) may not have been done correctly or may not be effective. As a result, another repair is required. On certain vehicles, the rear coil springs may not have been installed correctly. As a result, the spring(s) could detach from the vehicle while driving. Note: This recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: A coil spring that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the rear coil spring lower isolators.

Suspension

2026037 29 Jan 2026

Issue: On certain vehicles, the recall repairs completed by an FCA dealer during recall 64A (Transport Canada recall no. 2023-336) may not have been done correctly. As a result, a second repair is required. On certain vehicles, the rear coil springs may not have been installed correctly. As a result, the spring(s) could detach from the vehicle while driving. Note: This recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: A coil spring that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, repair the rear coil spring assemblies.

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Visual system

2024338 13 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Grand Cherokee model, this recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the radio software.

Suspension

2024116 22 Feb 2024

Issue: On certain vehicles, the bolt(s) for the upper control arm ball joint(s) may have been damaged during production. As a result, the bolt(s) could fail and cause the upper control arm(s) to separate from the knuckle(s). Note: This recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: An upper control arm that separates could cause a loss of control and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the upper control arm bolt(s).

Visual system

2023456 14 Aug 2023

Issue: On certain vehicles, a software problem could cause the rearview camera image to not appear on the display screen. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the central vision processing/park assist module software.

11 more on the model-year record, cardog.app/tools/recalls/jeep/grand-cherokee/2021

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $34,507[5], $2,512 over the median of $31,995[4].

Lowest ask	$22,000
Middle half	$26,342 – $34,253
Median ask	$31,995
This car	$34,507

Same configuration · 19 live listings · as of 29 Oct 2026

OTHER 2021 JEEP GRAND CHEROKEE LISTINGS [5]

Orangeville, ON · 118,640 km	$31,420
Orangeville, ON · 89,568 km	$34,721
Québec, QC · 108,270 km	$23,323
Winnipeg, MB · 67,277 km	$31,890
Edmonton, AB · 77,208 km	$50,429
Edmonton, AB · 176,500 km	$47,149

§4 EVENTS

2021	Model year 2021[1] Assembly plant Detroit, Michigan, United States
11 Jun 2021	Transport Canada recall 2021372[2] Issued for the model year · Lights and instruments
21 Sep 2021	Transport Canada recall 2021576[2] Issued for the model year · Visual system
14 Oct 2021	Transport Canada recall 2021630[2] Issued for the model year · Lights and instruments
12 Nov 2021	Transport Canada recall 2021690[2] Issued for the model year · Airbag
10 Dec 2021	Transport Canada recall 2021747[2] Issued for the model year · Lights and instruments
14 Mar 2022	Transport Canada recall 2022113[2] Issued for the model year · Steering
24 Mar 2022	Transport Canada recall 2022136[2] Issued for the model year · Seats and restraints
28 Apr 2022	Transport Canada recall 2022217[2] Issued for the model year · Engine
28 Jul 2022	Transport Canada recall 2022408[2] Issued for the model year · Lights and instruments
18 May 2023	Transport Canada recall 2023292[2] Issued for the model year · Steering
8 Jun 2023	Transport Canada recall 2023336[2] Issued for the model year · Suspension
14 Aug 2023	Transport Canada recall 2023456[2] Issued for the model year · Visual system
22 Feb 2024	Transport Canada recall 2024116[2] Issued for the model year · Suspension
13 Jun 2024	Transport Canada recall 2024338[2] Issued for the model year · Visual system
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
29 Jan 2026	Transport Canada recall 2026037[2] Issued for the model year · Suspension
1 Sep 2026	Transport Canada recall 2026418[2] Issued for the model year · Suspension

28 Oct 2026	Listed for sale, Sherwood Park, AB[5] Sherwood Park Volkswagen · asking $34,507
29 Oct 2026	Listing last updated[5] asking $34,507

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 19 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.