Register entry, as of 27 October 2026 Listed for sale Record ID 37d7bcb1b368

# 2022 Dodge Durango R/T

5.7 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1C4 | SDJCT | 7 | N | C | 195044 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Dodge · FCA US LLC | Durango · 5.7 L | Verified | 2022 | Detroit | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 5.7 L, 8 cylinders |
| Make | Dodge | Fuel | Gasoline |
| Model | Durango | Drive | AWD |
| Trim | R/T | Maker | FCA US LLC |
| Body | Sport Utility Vehicle | Plant | Detroit, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/durango/2022

**8** recalls listed by Transport Canada for this model year

### Structure

2026392 13 Aug 2026

Issue: On certain vehicles, the recall repairs completed by an FCA dealer during recalls Y73 and 20A (Transport Canada recall nos. 2021-663 and 2023-090) may not be effective. As a result, another repair is required. On certain vehicles, the rear spoiler could hit the body when opening and closing the liftgate. This could damage the spoiler and cause it to detach from the vehicle. Safety Risk: A spoiler that detaches from the vehicle could create a road hazard for others. Corrective Actions: FCA Canada will notify owners in writing. The corrective actions for this recall are under development.

### Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Visual system

2024338 13 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Grand Cherokee model, this recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the radio software.

### Brakes
2024328 6 Jun 2024

Issue: On certain vehicles, a software problem could cause the electronic stability control (ESC) system not to work. As a result, the vehicles may not meet certain requirements of Canadian regulations. Note: This problem would cause a warning light to display on the instrument panel. Safety Risk: An electronic stability control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the antilock braking system (ABS) control module software.

### Structure
2023090 23 Feb 2023

Issue: On certain vehicles, the rear spoiler could hit the body when opening and closing the liftgate. This could damage the spoiler and cause it to detach from the vehicle. Note: This is an expansion of Transport Canada Recall 2021-663. Safety Risk: A spoiler that detaches from the vehicle could create a road hazard for others. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace the rear spoiler.

### Powertrain
2022673 23 Nov 2022

Issue: On certain police vehicles, the transmission shifter could slip out of the Drive position while driving. If this happens, there could be a sudden loss of power to the wheels. Safety Risks: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the shifter assembly.

2 more on the model-year record, cardog.app/tools/recalls/dodge/durango/2022

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $49,995[5], $9,000 over the median of $40,995[4].




| | |
|---|---|
| Lowest ask | $30,209 |
| Middle half | $38,888 – $44,986 |
| Median ask | $40,995 |
| This car | $49,995 |

Same configuration · 25 live listings · as of 27 Oct 2026

OTHER 2022 DODGE DURANGO LISTINGS [5]

| | |
|---|---|
| Meaford, ON · 126,460 km | $35,500 |
| Woodstock, ON · 99,945 km | $55,995 |
| Haliburton, ON · 139,699 km | $30,160 |
| Fort Frances, ON · 45,294 km | $46,480 |
| Mississauga, ON · 80,697 km | $36,995 |
| Airdrie, AB · 165,185 km | $33,500 |

## §4 EVENTS

2022 Model year 2022[1]
Assembly plant Detroit, Michigan, United States

| | |
|---|---|
| 11 Mar 2022 | Transport Canada recall 2022108[2]<br>Issued for the model year · Brakes |
| 14 Mar 2022 | Transport Canada recall 2022113[2]<br>Issued for the model year · Steering |
| 23 Nov 2022 | Transport Canada recall 2022673[2]<br>Issued for the model year · Powertrain |
| 23 Feb 2023 | Transport Canada recall 2023090[2]<br>Issued for the model year · Structure |
| 6 Jun 2024 | Transport Canada recall 2024328[2]<br>Issued for the model year · Brakes |
| 13 Jun 2024 | Transport Canada recall 2024338[2]<br>Issued for the model year · Visual system |
| 15 Aug 2024 | Transport Canada recall 2024548[2]<br>Issued for the model year · Label |
| 16 Dec 2025 | Listed for sale, Dartmouth, NS[5]<br>Auto Loan Nova Scotia · asking $49,995 |
| 13 Aug 2026 | Transport Canada recall 2026392[2]<br>Issued for the model year · Structure |
| 14 Sep 2026 | Window sticker collected[6]<br>Issued by STELLANTIS |
| 24 Oct 2026 | Listing last updated[5]<br>asking $49,995 |

## §5 DOCUMENTS [6]

| | |
|---|---|
| Window sticker | PDF, issued by STELLANTIS, collected 14 Sep 2026<br>VIN not read from the file |

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 25 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026
[6] Window sticker, issued by STELLANTIS, collected 14 Sep 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.