Register entry, as of 29 October 2026 Listed for sale Record ID e97c76f76a8b

# 2024 Jeep Wagoneer Series II

3.0 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1C4 | SJVBP | 1 | R | S | 132988 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Jeep · FCA US LLC | Wagoneer · 3.0 L | Verified | 2024 | Warren | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2024 | Engine | 3.0 L, 6 cylinders |
| Make | Jeep | Fuel | Gasoline |
| Model | Wagoneer | Drive | 4WD |
| Trim | Series II | Maker | FCA US LLC |
| Body | Sport Utility Vehicle | Plant | Warren, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/wagoneer/2024

**8** recalls listed by Transport Canada for this model year

### Accessories — 2026433 — 10 Sep 2026

Issue : On certain vehicles, the pivot bolt(s) securing the roof crossbars may not have been tightened properly. As a result, the crossbar(s) could detach from the vehicle. Note: This recall also affects certain 2023-2026 Wagoneer L models and Grand Wagoneer L models. Safety Risk: A crossbar that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to inspect and secure the roof crossbar(s), as necessary.

### Structure — 2025506 — 25 Sep 2025

Issue: On certain vehicles, the left and right rear quarter glass trims may not have been secured properly. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing. The corrective actions for this recall are under development.

### Structure — 2025467 — 11 Sep 2025

Issue: On certain vehicles, the window trims on the front doors may not have been secured properly. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the window trim(s).

### Powertrain

2025450 4 Sep 2025

Issue: On a small number of vehicles, the parking pawl return spring in the electric drive module may not have been installed correctly. As a result, when the transmission is shifted to Park, the vehicle could move if the parking brake isn't applied. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, FCA Canada recommends that you should always use the parking brake when you park. FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the electric drive module.

### Visual system

2024766 19 Dec 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Grand Cherokee model, this recall affects both Grand Cherokee and Grand Cherokee L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the rearview camera module software.

### Airbag

2024170 14 Mar 2024

Issue: On certain vehicles, the steering column control module may not have been manufactured properly. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that is turned off could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the steering column control module.

2 more on the model-year record, cardog.app/tools/recalls/jeep/wagoneer/2024

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $41,995[5], $5,993 under the median of $47,988[4].

| | |
|---|---|
| Lowest ask | $40,995 |
| Middle half | $44,950 – $49,998 |
| Median ask | $47,988 |
| This car | $41,995 |

Same configuration · 46 live listings · as of 29 Oct 2026

### OTHER 2024 JEEP WAGONEER LISTINGS [5]

| | |
|---|---|
| Edmonton, AB · 117,180 km | $54,999 |
| Winnipeg, MB · 117,180 km | $47,995 |
| Regina, SK · 117,180 km | $47,995 |
| Winnipeg, MB · 117,180 km | $47,995 |
| Embrun, ON · 102,431 km | $45,997 |
| Edmonton, AB · 103,025 km | $47,988 |

## §4 EVENTS

| | |
|---|---|
| 2024 | Model year 2024[1]<br>Assembly plant Warren, Michigan, United States |
| 14 Aug 2023 | Transport Canada recall 2023456[2]<br>Issued for the model year · Visual system |
| 26 Oct 2023 | Transport Canada recall 2023577[2]<br>Issued for the model year · Seats and restraints |
| 14 Mar 2024 | Transport Canada recall 2024170[2]<br>Issued for the model year · Airbag |
| 19 Dec 2024 | Transport Canada recall 2024766[2]<br>Issued for the model year · Visual system |
| 4 Sep 2025 | Transport Canada recall 2025450[2]<br>Issued for the model year · Powertrain |
| 11 Sep 2025 | Transport Canada recall 2025467[2]<br>Issued for the model year · Structure |
| 25 Sep 2025 | Transport Canada recall 2025506[2]<br>Issued for the model year · Structure |
| 10 Sep 2026 | Transport Canada recall 2026433[2]<br>Issued for the model year · Accessories |
| 27 Oct 2026 | Listed for sale, Woodstock, ON[5]<br>WOODSTOCK CHRYSLER · asking $41,995 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $41,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 46 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.