Register entry, as of 27 October 2026 Listed for sale Record ID d0e4c31b9c71

2023 Jeep Gladiator Sport

3.6 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C6	JJTAG	4	P	L	533466
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jeep · FCA US LLC	Gladiator · 3.6 L	Verified	2023	Toledo	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	3.6 L, 6 cylinders
Make	Jeep	Fuel	Gasoline
Model	Gladiator	Drive	4WD
Trim	Sport	Maker	FCA US LLC
Body	Pickup	Plant	Toledo, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/gladiator/2023

6 recalls listed by Transport Canada for this model year

Steering

2026271 4 Jun 2026

Issue: On certain vehicles, the connection for the electric hydraulic power steering pump (EHPSP) could become loose. If this happens, the EHPSP connection could overheat and melt. Safety Risk: Wiring that overheats and melts can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, FCA recommends that you should park your vehicle outside and away from other vehicles or buildings until the recall repairs are completed. FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, repair or replace the affected part(s).

Lights and instruments

2024504 5 Sep 2024

Issue: On certain vehicles, the instrument panel cluster could stop working. As a result, warnings, tell-tales and gauges may not display. Note: This recall only affects vehicles equipped with a 3.5" instrument cluster panel. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the instrument panel cluster.

Airbag

2024170 14 Mar 2024

Issue: On certain vehicles, the steering column control module may not have been manufactured properly. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that is turned off could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the steering column control module.

Lights and instruments

2023514 18 Sep 2023

Issue: On certain vehicles equipped with a manual transmission, a problem with the gear sensor (AGS) could cause the rearview camera not to work and the backup lamps not to turn on when backing up. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. Additionally, backup lamps that don't turn on could cause a person not to recognize that the vehicle is backing. Both issues could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the all gear sensor (AGS).

Fuel system

2023218 13 Apr 2023

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.

Powertrain

2023089 23 Feb 2023

Issue: Under certain conditions, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Vehicles repaired under FCA Canada recalls Y01, Y03 and Y07 (Transport Canada recall 2021-035) also require this repair. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and advise you to tale your vehicle to a dealership to replace the clutch assembly. The dealer will also inspect and, if necessary, update the instrument panel cluster and powertrain control module software.

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $41,259[5], $3,407 under the median of $44,666[4].



Lowest ask	$33,595
Middle half	$40,714 – $47,895
Median ask	$44,666
This car	$41,259

Same model year · 66 live listings · as of 27 Oct 2026

OTHER 2023 JEEP GLADIATOR LISTINGS [5]

Toronto, ON · 66,000 km	$45,595
Welland, ON · 47,827 km	$41,900
Barrie, ON · 53,243 km	$45,995
Mississauga, ON · 67,060 km	$47,995
Burlington, ON · 67,772 km	$42,988
Hamilton, ON · 33,144 km	$49,475

§4 EVENTS

2023	Model year 2023[1] Assembly plant Toledo, Ohio, United States
23 Feb 2023	Transport Canada recall 2023089[2] Issued for the model year · Powertrain
13 Apr 2023	Transport Canada recall 2023218[2] Issued for the model year · Fuel system
18 Sep 2023	Transport Canada recall 2023514[2] Issued for the model year · Lights and instruments
14 Mar 2024	Transport Canada recall 2024170[2] Issued for the model year · Airbag
5 Sep 2024	Transport Canada recall 2024504[2] Issued for the model year · Lights and instruments
4 Jun 2026	Transport Canada recall 2026271[2] Issued for the model year · Steering
21 Sep 2026	Listed for sale, Nanaimo, BC[5] Galaxy Motors Nanaimo · asking $41,259
26 Oct 2026	Listing last updated[5] asking $41,259

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 66 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.