Register entry, as of 26 October 2026 Listed for sale Record ID 56fca993edfd

2023 Ram 1500 Tradesman

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C6	RR7KT	8	P	S	582352
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ram · FCA US LLC	1500 · 5.7 L	Verified	2023	Warren	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	5.7 L, 8 cylinders
Make	Ram	Fuel	Gasoline
Model	1500	Drive	4WD
Trim	Tradesman	Maker	FCA US LLC
Body	Pickup	Plant	Warren, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2023

11 recalls listed by Transport Canada for this model year

Seats and restraints

2026371 30 Jul 2026

Issue: On certain trucks, the second-row seat belt anchors may not be properly attached. As a result, the seat belt(s) could detach in a crash. Safety Risk: A seat belt that detaches could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to inspect and, if necessary, secure the second-row seat belt buckle(s) to the body.

Visual system

2026347 16 Jul 2026

Issue: On certain trucks, the passenger-side mirror glass may not be attached properly. As a result, the mirror glass could fall off. Note: This recall only affects certain trucks equipped with a heated trailer tow mirror. Safety Risk: A missing mirror will reduce rear visibility and could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the passenger side mirror glass.

Visual system

2024596 10 Oct 2024

Issue: On certain trucks, the driver's side mirror glass may not be attached properly. As a result, the mirror glass could fall off. Note: This recall only affects certain trucks equipped with a heated trailer tow mirror. Safety Risk: A missing mirror will reduce rear visibility and could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to replace the driver side mirror glass.

Lights and instruments

2024576 1 Oct 2024

Issue: On certain trucks, a problem with the steering column control module could cause a turn signal not to turn off after signaling and completing a turn. Safety Risk: Turn signals that stay on after making a turn or changing lanes could create confusion for others and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to inspect and, if necessary, replace the steering column control module.

Brakes

2024503 5 Sep 2024

Issue: On certain trucks, a software problem could cause the electronic stability control (ESC) system not to work. As a result, the vehicles may not meet certain requirements of Canadian regulations. Note: This problem would cause warning lights for the antilock braking system (ABS), ESC, adaptive cruise control (ACC), and forward collision warning (FCW) to appear on the instrument panel. Safety Risk: An electronic stability control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to update the antilock braking system (ABS) control module software.

Powertrain

2024325 6 Jun 2024

Issue: On certain vehicles, the transmission control unit (TCU) may not be sealed properly. As a result, transmission fluid could leak into the unit. If this happens, there could be a loss of power to the wheels. Additionally, if the vehicle is parked and the parking brake isn't applied, the vehicle could roll away. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the valve body and control unit.

5 more on the model-year record, cardog.app/tools/recalls/ram/1500/2023

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $43,995[5], $5,596 over the median of $38,399[4].



Lowest ask	$19,995
Middle half	$35,999 – $41,980
Median ask	$38,399
This car	$43,995

Same configuration · 21 live listings · as of 26 Oct 2026

OTHER 2023 RAM 1500 LISTINGS [5]

Hamilton, ON · 2,331 km	$58,975
Trois-Rivieres-Ouest, QC · 56,510 km	$49,499
Parksville, BC · 56,828 km	$51,998
Parksville, BC · 77,864 km	$51,998
Scarborough, ON · 141,222 km	$34,990
Surrey, BC · 46,000 km	$125,885

§4 EVENTS

2023	Model year 2023[1] Assembly plant Warren, Michigan, United States
9 Feb 2023	Transport Canada recall 2023047[2] Issued for the model year · Visual system
13 Apr 2023	Transport Canada recall 2023218[2] Issued for the model year · Fuel system
28 Sep 2023	Transport Canada recall 2023533[2] Issued for the model year · Visual system
28 Nov 2023	Transport Canada recall 2023636[2] Issued for the model year · Lights and instruments
14 Mar 2024	Transport Canada recall 2024170[2] Issued for the model year · Airbag
6 Jun 2024	Transport Canada recall 2024325[2] Issued for the model year · Powertrain
5 Sep 2024	Transport Canada recall 2024503[2] Issued for the model year · Brakes
1 Oct 2024	Transport Canada recall 2024576[2] Issued for the model year · Lights and instruments
10 Oct 2024	Transport Canada recall 2024596[2] Issued for the model year · Visual system
16 Jul 2026	Transport Canada recall 2026347[2] Issued for the model year · Visual system
30 Jul 2026	Transport Canada recall 2026371[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Spring Brook, ON[5] McKeown Chrysler Dodge Jeep Ram · asking $43,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 21 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.