Register entry, as of 29 October 2026 Listed for sale Record ID 58409f483f59

2018 Ram 1500 SLT

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C6	RR7LT	6	J	S	130468
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Ram · FCA US LLC	1500 · 5.7 L	Verified	2018	Warren	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	5.7 L, 8 cylinders
Make	Ram	Fuel	Gasoline
Model	1500	Drive	4WD
Trim	SLT	Maker	FCA US LLC
Body	Pickup	Plant	Warren, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2018

16 recalls listed by Transport Canada for this model year

Airbag

2025468 11 Sep 2025

Issue: On certain trucks, the side curtain airbag inflators may be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Note: This is an expansion of Transport Canada recall 2025-013. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the affected side curtain airbag(s).

Airbag

2025013 16 Jan 2025

Issue: On certain trucks, the side curtain airbag inflators may be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Note: This recall also affects certain 2016 model year RAM 3500 chassis cab incomplete vehicles. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the affected side curtain airbag(s).

Engine

2023338 8 Jun 2023

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Note: Vehicles included in FCA recall W58 (Transport Canada recall 2020-371) are not part of this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

Fuel system

2022303 9 Jun 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.

Engine

2020371 13 Aug 2020

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

Engine

2019535 25 Oct 2019

Issue: On certain trucks equipped with a 3.0-L EcoDiesel engine, the exhaust gas recirculation (EGR) cooler could crack internally and leak. If this happens, a driver may notice a low coolant level or a heater that does not work properly. Safety Risk: A cracked EGR cooler could create the risk of an engine fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to replace the EGR cooler. Dealers will also inspect intake manifold and replace it as necessary.

10 more on the model-year record, cardog.app/tools/recalls/ram/1500/2018

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 15 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $28,995[5], $10,115 over the median of $18,880[4].

Lowest ask	$11,910
Middle half	$16,402 – $19,999
Median ask	$18,880
This car	$28,995

Same configuration · 14 live listings · as of 29 Oct 2026

OTHER 2018 RAM 1500 LISTINGS [5]

Welland, ON · 331,258 km	$7,000
Brantford, ON · 331,258 km	$7,000
Québec, QC · 87,719 km	$25,697
Chicoutimi, QC · 160,696 km	$16,495
Hamilton, ON · 331,258 km	$7,000
Edmonton, AB · 143,303 km	$34,499

§4 EVENTS

2018	Model year 2018[1] Assembly plant Warren, Michigan, United States
8 Feb 2018	Transport Canada recall 2018081[2] Issued for the model year · Powertrain
17 May 2018	Transport Canada recall 2018269[2] Issued for the model year · Engine
15 Jun 2018	Transport Canada recall 2018324[2] Issued for the model year · Other
9 Aug 2018	Transport Canada recall 2018422[2] Issued for the model year · Powertrain
23 Aug 2018	Transport Canada recall 2018447[2] Issued for the model year · Powertrain
26 Apr 2019	Transport Canada recall 2019206[2] Issued for the model year · Powertrain
10 May 2019	Transport Canada recall 2019221[2] Issued for the model year · Structure
25 Jul 2019	Transport Canada recall 2019365[2] Issued for the model year · Lights and instruments
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
30 Aug 2019	Transport Canada recall 2019441[2] Issued for the model year · Structure
25 Oct 2019	Transport Canada recall 2019535[2] Issued for the model year · Engine
13 Aug 2020	Transport Canada recall 2020371[2] Issued for the model year · Engine
9 Jun 2022	Transport Canada recall 2022303[2] Issued for the model year · Fuel system
8 Jun 2023	Transport Canada recall 2023338[2] Issued for the model year · Engine
16 Jan 2025	Transport Canada recall 2025013[2] Issued for the model year · Airbag
11 Sep 2025	Transport Canada recall 2025468[2] Issued for the model year · Airbag
29 Oct 2026	Listed for sale, Vernon, BC[5] Vernon Dodge Jeep · asking $28,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 14 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.