

Register entry, as of 27 October 2026

Listed for sale

Record ID 6d630422b42c

2025 Ram 1500 Big Horn/Lonestar

3.0 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C6 SRFFP 6 S N 599361

WMI 1-3

Ram · FCA US LLC

DESCRIPTOR 4-8

1500 · 3.0 L

CHECK 9

Verified

YEAR 10

2025

PLANT 11

Sterling Heights

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	3.0 L, 6 cylinders
Make	Ram	Fuel	Gasoline
Model	1500	Drive	4WD
Trim	Big Horn/Lonestar	Maker	FCA US LLC
Body	Pickup	Plant	Sterling Heights, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2025

9

 recalls listed by Transport Canada for this model year

Visual system

2026416 1 Sep 2026

Issue: On certain vehicles, a software problem could cause the rearview camera not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the radio software.

Lights and instruments

2026406 24 Aug 2026

Issue: On certain trucks, the daytime running lamps (DRLs) may turn off when the turn signals are activated. Canadian regulations require the DRLs to remain on when the turn signals are activated. Safety Risk: This is a technical non-compliance and doesn't affect vehicle safety. Corrective Actions: This is not a recall. FCA Canada has made changes to ensure that all new vehicles meet Canadian regulations.

Seats and restraints

2026371 30 Jul 2026

Issue: On certain trucks, the second-row seat belt anchors may not be properly attached. As a result, the seat belt(s) could detach in a crash. Safety Risk: A seat belt that detaches could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to inspect and, if necessary, secure the second-row seat belt buckle(s) to the body.



Visual system

2026179 9 Apr 2026

Issue: On certain vehicles, a software problem could cause the instrument panel cluster screen not to display when starting the vehicle or while driving. If this happens, you may not be able to see certain information about the vehicle, including the gear selection, warnings, and tell-tales. Note: This recall only affects vehicles equipped with a 3.5" instrument panel cluster. This recall also affects certain RAM 3500, 4500 and 5500 chassis cab incomplete vehicles. Safety Risk: Warnings, tell-tales and gear selection indicators that don't display could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the instrument panel cluster software.

Electrical

2026043 2 Feb 2026

Issue: On certain vehicles, the trailer tow module could fail. As a result, the trailer lights may not work when towing a trailer. This problem could also cause the trailer brakes not to work. Note: This recall also affects certain RAM 3500, 4500 and 5500 chassis cab incomplete vehicles. Safety Risk: Trailer lights that don't work could make the vehicle less visible and cause following drivers not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a loss of trailer brakes could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the trailer tow module.

Visual system

2025659 1 Dec 2025

Issue: On certain vehicles, a software problem could cause the instrument panel cluster screen not to display when starting the vehicle or while driving. If this happens, you may not be able to see certain information about the vehicle, including the gear selection, warnings, and tell-tales. Note: This recall only affects vehicles equipped with a 12" instrument panel cluster. This recall also affects certain RAM 3500, 4500 and 5500 chassis cab incomplete vehicles. Safety Risk: Warnings, tell-tales and gear selection indicators that don't display could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update or replace the instrument panel cluster, as necessary.

3 more on the model-year record, cardog.app/tools/recalls/ram/1500/2025

Listed for the model year, not checked against your VIN. Ram confirms which apply.


Check your VIN with Mopar Canada or call a Ram dealer with your VIN.

www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$50,899^[5], \$4,100 under the median of \$54,999^[4].



Lowest ask	\$44,999
Middle half	\$50,995 – \$57,495
Median ask	\$54,999
This car	\$50,899

Same configuration · 35 live listings · as of 27 Oct 2026

OTHER 2025 RAM 1500 LISTINGS ^[5]

London, ON · 72,076 km	\$51,607
Cranbrook, BC · 37,103 km	\$46,999
Brantford, ON · 100 km	\$55,300
Brantford, ON · 64,309 km	\$59,300
Chilliwack, BC · 46,276 km	\$58,995
Mississauga, ON · 65,245 km	\$52,995



§4 EVENTS

2025	Model year 2025 ^[1] Assembly plant Sterling Heights, Michigan, United States
17 Oct 2024	Transport Canada recall 2024638 ^[2] Issued for the model year · Suspension
19 Dec 2024	Transport Canada recall 2024765 ^[2] Issued for the model year · Lights and instruments
13 Mar 2025	Listed for sale, Innisfail, AB ^[5] Innisfail Chrysler Dodge Jeep Ram · asking \$50,899
10 Apr 2025	Transport Canada recall 2025192 ^[2] Issued for the model year · Visual system
1 Dec 2025	Transport Canada recall 2025659 ^[2] Issued for the model year · Visual system
2 Feb 2026	Transport Canada recall 2026043 ^[2] Issued for the model year · Electrical
9 Apr 2026	Transport Canada recall 2026179 ^[2] Issued for the model year · Visual system
30 Jul 2026	Transport Canada recall 2026371 ^[2] Issued for the model year · Seats and restraints
24 Aug 2026	Transport Canada recall 2026406 ^[2] Issued for the model year · Lights and instruments
1 Sep 2026	Transport Canada recall 2026416 ^[2] Issued for the model year · Visual system
14 Sep 2026	Window sticker collected ^[6] Issued by STELLANTIS
26 Oct 2026	Listing last updated ^[5] asking \$50,899

§5 DOCUMENTS [6]

Window sticker	PDF, issued by STELLANTIS, collected 14 Sep 2026 VIN not read from the file
----------------	--

SOURCES

[1]	Cardog identity register, decoded from the VIN	[4]	Cardog market quote, same configuration, 35 live listings, as of 27 Oct 2026
[2]	Transport Canada recall database, listed for the model year	[5]	Live public dealer listings on Cardog, as of 27 Oct 2026
[3]	NHTSA recall records (United States), listed for the model year	[6]	Window sticker, issued by STELLANTIS, collected 14 Sep 2026



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

