Register entry, as of 28 November 2026 Listed for sale Record ID f8d2db0eade5

# 2019 Ram 1500 Rebel, Sport 2TL Pkg, Rebel 2TW Pkg

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1C6 | SRFLT | 5 | K | N | 853272 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ram · FCA US LLC | 1500 · 5.7 L | Verified | 2019 | Sterling Heights | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 5.7 L, 8 cylinders |
| Make | Ram | Fuel | Gasoline |
| Model | 1500 | Drive | 4WD |
| Trim | Rebel, Sport 2TL Pkg, Rebel 2TW Pkg | Maker | FCA US LLC |
| Body | Pickup | Plant | Sterling Heights, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2019

**21** recalls listed by Transport Canada for this model year

### Seats and restraints

2026371 30 Jul 2026

Issue: On certain trucks, the second-row seat belt anchors may not be properly attached. As a result, the seat belt(s) could detach in a crash. Safety Risk: A seat belt that detaches could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to inspect and, if necessary, secure the second-row seat belt buckle(s) to the body.

### Airbag

2025658 1 Dec 2025

Issue: On certain trucks, the side curtain airbag inflators may be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Note: This is an expansion of Transport Canada recall 2025-013. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the affected side curtain airbag(s).

### Airbag

2025013 16 Jan 2025

Issue: On certain trucks, the side curtain airbag inflators may be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Note: This recall also affects certain 2016 model year RAM 3500 chassis cab incomplete vehicles. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the affected side curtain airbag(s).

### Brakes

2024503 5 Sep 2024

Issue: On certain trucks, a software problem could cause the electronic stability control (ESC) system not to work. As a result, the vehicles may not meet certain requirements of Canadian regulations. Note: This problem would cause warning lights for the antilock braking system (ABS), ESC, adaptive cruise control (ACC), and forward collision warning (FCW) to appear on the instrument panel. Safety Risk: An electronic stability control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to update the antilock braking system (ABS) control module software.

### Engine

2023338 8 Jun 2023

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Note: Vehicles included in FCA recall W58 (Transport Canada recall 2020-371) are not part of this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

### Structure

2022699 8 Dec 2022

Issue: On certain trucks, the tailgate could unlatch and open while driving. If this happens, cargo that is not secured could fall out of the truck bed and onto the road. Safety Risk: Cargo that falls from the truck bed could create a road hazard for others. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your truck to a dealership to inspect the alignment of the tailgate strikers, and adjust them if necessary.

15 more on the model-year record, cardog.app/tools/recalls/ram/1500/2019

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 30 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $37,988[5], $5,075 over the median of $32,913[4].




| | |
|---|---|
| Lowest ask | $23,900 |
| Middle half | $28,995 – $36,984 |
| Median ask | $32,913 |
| This car | $37,988 |

Same configuration · 71 live listings · as of 28 Nov 2026

### OTHER 2019 RAM 1500 LISTINGS [5]

| | |
|---|---|
| New Westminster, BC · 132,017 km | $24,995 |
| Orillia, ON · 128,807 km | $28,988 |
| Sundridge, ON · 72,951 km | $38,999 |
| Orillia, ON · 156,002 km | $29,978 |
| Amherst, NS · 190,435 km | $24,975 |
| Calgary, AB · 241,814 km | $14,995 |

## §4 EVENTS

| | |
|---|---|
| 2019 | Model year 2019[1]<br>Assembly plant Sterling Heights, Michigan, United States |
| 17 May 2018 | Transport Canada recall 2018269[2]<br>Issued for the model year · Engine |
| 24 Jan 2019 | Transport Canada recall 2019033[2]<br>Issued for the model year · Steering |
| 6 Feb 2019 | Transport Canada recall 2019050[2]<br>Issued for the model year · Brakes |
| 15 Mar 2019 | Transport Canada recall 2019138[2]<br>Issued for the model year · Steering |
| 26 Apr 2019 | Transport Canada recall 2019206[2]<br>Issued for the model year · Powertrain |
| 3 Jun 2019 | Transport Canada recall 2019263[2]<br>Issued for the model year · Airbag |
| 25 Jul 2019 | Transport Canada recall 2019365[2]<br>Issued for the model year · Lights and instruments |
| 25 Oct 2019 | Transport Canada recall 2019535[2]<br>Issued for the model year · Engine |
| 14 Nov 2019 | Transport Canada recall 2019574[2]<br>Issued for the model year · Steering |
| 6 Apr 2020 | Transport Canada recall 2020145[2]<br>Issued for the model year · Visual system |
| 9 Apr 2020 | Transport Canada recall 2020154[2]<br>Issued for the model year · Visual system |
| 28 Aug 2020 | Transport Canada recall 2020401[2]<br>Issued for the model year · Powertrain |
| 25 Sep 2020 | Transport Canada recall 2020456[2]<br>Issued for the model year · Seats and restraints |
| 12 Aug 2021 | Transport Canada recall 2021511[2]<br>Issued for the model year · Airbag |
| 9 Jun 2022 | Transport Canada recall 2022303[2]<br>Issued for the model year · Fuel system |
| 8 Dec 2022 | Transport Canada recall 2022699[2]<br>Issued for the model year · Structure |
| 8 Jun 2023 | Transport Canada recall 2023338[2]<br>Issued for the model year · Engine |

| | |
|---|---|
| 5 Sep 2024 | Transport Canada recall 2024503[2]<br>Issued for the model year · Brakes |
| 16 Jan 2025 | Transport Canada recall 2025013[2]<br>Issued for the model year · Airbag |
| 1 Dec 2025 | Transport Canada recall 2025658[2]<br>Issued for the model year · Airbag |
| 29 Jul 2026 | Listed for sale, Sundridge, ON[5]<br>MAC LANG · asking $37,988 |
| 30 Jul 2026 | Transport Canada recall 2026371[2]<br>Issued for the model year · Seats and restraints |
| 28 Nov 2026 | Listing last updated[5]<br>asking $37,988 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 71 live listings, as of 28 Nov 2026

[5] Live public dealer listings on Cardog, as of 28 Nov 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.