Register entry, as of 26 October 2026 Listed for sale Record ID a2828caa29aa

# 2022 Ram 1500 Rebel, Sport 2TL Pkg/Rebel 2TW Pkg

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1C6 | SRFLT | 5 | N | N | 188992 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ram · FCA US LLC | 1500 · 5.7 L | Verified | 2022 | Sterling Heights | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 5.7 L, 8 cylinders |
| Make | Ram | Fuel | Gasoline |
| Model | 1500 | Drive | 4WD |
| Trim | Rebel, Sport 2TL Pkg/Rebel 2TW Pkg | Maker | FCA US LLC |
| Body | Pickup | Plant | Sterling Heights, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2022

**13** recalls listed by Transport Canada for this model year

### Seats and restraints

2026371 30 Jul 2026

Issue: On certain trucks, the second-row seat belt anchors may not be properly attached. As a result, the seat belt(s) could detach in a crash. Safety Risk: A seat belt that detaches could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to inspect and, if necessary, secure the second-row seat belt buckle(s) to the body.

### Visual system

2026347 16 Jul 2026

Issue: On certain trucks, the passenger-side mirror glass may not be attached properly. As a result, the mirror glass could fall off. Note: This recall only affects certain trucks equipped with a heated trailer tow mirror. Safety Risk: A missing mirror will reduce rear visibility and could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the passenger side mirror glass.

### Airbag

2025613 6 Nov 2025

Issue: On a small number of vehicles, the steering column control module may not have been manufactured properly. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that is turned off could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the steering column control module.

### Visual system

2024596 10 Oct 2024

Issue: On certain trucks, the driver's side mirror glass may not be attached properly. As a result, the mirror glass could fall off. Note: This recall only affects certain trucks equipped with a heated trailer tow mirror. Safety Risk: A missing mirror will reduce rear visibility and could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to replace the driver side mirror glass.

### Brakes

2024503 5 Sep 2024

Issue: On certain trucks, a software problem could cause the electronic stability control (ESC) system not to work. As a result, the vehicles may not meet certain requirements of Canadian regulations. Note: This problem would cause warning lights for the antilock braking system (ABS), ESC, adaptive cruise control (ACC), and forward collision warning (FCW) to appear on the instrument panel. Safety Risk: An electronic stability control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to update the antilock braking system (ABS) control module software.

### Visual system

2024338 13 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Grand Cherokee model, this recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the radio software.

7 more on the model-year record, cardog.app/tools/recalls/ram/1500/2022

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 16 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $47,995[5], $2,305 over the median of $45,690[4].

| | |
|---|---|
| Lowest ask | $29,459 |
| Middle half | $41,899 – $48,990 |
| Median ask | $45,690 |
| This car | $47,995 |

Same configuration · 73 live listings · as of 26 Oct 2026

### OTHER 2022 RAM 1500 LISTINGS [5]

| | |
|---|---|
| Kelowna, BC · 77,632 km | $49,904 |
| Kelowna, BC · 40,541 km | $46,904 |
| Kelowna, BC · 134,001 km | $42,904 |
| Sudbury, ON · 26,706 km | $57,995 |
| Thunder Bay, ON · 40,587 km | $44,000 |
| Georgetown, ON · 95,783 km | $54,989 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Sterling Heights, Michigan, United States |
| 16 Mar 2021 | Transport Canada recall 2021156[2]<br>Issued for the model year · Brakes |
| 9 Jun 2022 | Transport Canada recall 2022304[2]<br>Issued for the model year · Visual system |
| 14 Oct 2022 | Transport Canada recall 2022584[2]<br>Issued for the model year · Engine |
| 9 Feb 2023 | Transport Canada recall 2023047[2]<br>Issued for the model year · Visual system |
| 13 Apr 2023 | Transport Canada recall 2023218[2]<br>Issued for the model year · Fuel system |
| 12 May 2023 | Transport Canada recall 2023283[2]<br>Issued for the model year · Visual system |
| 28 Sep 2023 | Transport Canada recall 2023533[2]<br>Issued for the model year · Visual system |
| 13 Jun 2024 | Transport Canada recall 2024338[2]<br>Issued for the model year · Visual system |
| 5 Sep 2024 | Transport Canada recall 2024503[2]<br>Issued for the model year · Brakes |
| 10 Oct 2024 | Transport Canada recall 2024596[2]<br>Issued for the model year · Visual system |
| 6 Nov 2025 | Transport Canada recall 2025613[2]<br>Issued for the model year · Airbag |
| 16 Jul 2026 | Transport Canada recall 2026347[2]<br>Issued for the model year · Visual system |
| 30 Jul 2026 | Transport Canada recall 2026371[2]<br>Issued for the model year · Seats and restraints |
| 16 Sep 2026 | Listed for sale, Gander, NL[5]<br>Hickman Nissan - Gander · asking $47,995 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $47,995 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

## SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 73 live listings, as of 26 Oct 2026

[5] Live public dealer listings on Cardog, as of 26 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.