Register entry, as of 29 October 2026 Listed for sale Record ID 509a4f37fcfb

2005 Dodge Ram

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1D7	HU18D	0	5	J	536040
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dodge · FCA US LLC	Ram · 5.7 L	Verified	2005	Fenton	Build sequence

§1 IDENTITY [1]

Model year	2005	Engine	5.7 L, 8 cylinders
Make	Dodge	Fuel	Gasoline
Model	Ram	Drive	4WD
Trim	Not in the decode	Maker	FCA US LLC
Body	Pickup	Plant	Fenton, Missouri, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/ram/2005

11 recalls listed by Transport Canada for this model year

Airbag

2016265 27 May 2016

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Airbag

2015228 27 May 2015

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Note: This recall supersedes special service campaign 2015-003. Correction: Dealers will replace airbag inflators. All vehicles having received a replacement inflator as part of the previous special service campaign will have a replacement inflator installed.

Airbag

2015094 3 Mar 2015

Fiat Chrysler Automobiles (FCA) Canada is conducting a voluntary Safety Improvement Program involving Takata passenger airbag inflators installed in certain vehicles that were originally sold or ever registered in certain high humidity areas of the United States. Fiat Chrysler Automobiles (FCA) will replace the passenger inflator on affected vehicles. Owners who believe their vehicles may have been originally purchased or registered in Florida, Hawaii, Puerto Rico, U.S. Virgin Islands, Texas, Mississippi, Alabama, Louisiana, Georgia, Guam, American Samoa and Saipan should contact a Fiat Chrysler Automobile (FCA) dealer. This action is not being conducted under the requirements of the Motor Vehicle Safety Act. Note: This Safety Improvement Campaign is superseded by recall 2016-265 (FCA Recall S43). Please see recall 2016265 for more information.

Airbag

2015093 3 Mar 2015

Fiat Chrysler Automobiles (FCA) Canada is conducting a voluntary Safety Improvement Program involving Takata driver and/or passenger airbag inflators installed in certain vehicles that were originally sold or ever registered in certain high humidity areas of the United States. Fiat Chrysler Automobiles (FCA) will replace the driver and/or passenger inflator on affected vehicles, depending on the vehicle involved. Owners who believe their vehicles may have been originally purchased or registered in Florida, Hawaii, Puerto Rico, and the U.S. Virgin Islands should contact a Fiat Chrysler Automobile (FCA) dealer. This action is not being conducted under the requirements of the Motor Vehicle Safety Act. Note: For the 2003 model year Dodge RAM, only the passenger side inflator would need replacement. Additional Note: This special service campaign was replaced by recalls 2015094 and 2015228. Please see these recalls for more information: Click here for more information on the 2015094 recall Click here for more information on the 2015228 recall

Airbag

2015003 6 Jan 2015

Chrysler Canada is conducting a voluntary Safety Improvement Campaign concerning the driver's airbag inflator on certain vehicles equipped with Takata airbags. Chrysler Canada will replace the driver's inflator on affected vehicles. This action is not being conducted under the requirements of the Motor Vehicle Safety Act. Note: This special service campaign was replaced by recall 2015228. Please see recall 2015228 for more information: Click here for more information

Powertrain

2014582 19 Dec 2014

On certain vehicles, the rear axle pinion nut could loosen and allow the rear driveshaft to detach from the axle, or fully detach from the vehicle. Pinion nut separation could also cause the rear axle differential to fail suddenly, causing rear wheel lockup. These issues could result in loss of propulsion, danger to other road users, loss of vehicle control and possible crash causing property damage and/or personal injury. Correction: Dealers will install a pinion nut retainer.

5 more on the model-year record, cardog.app/tools/recalls/dodge/ram/2005

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 16 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,999[5], $5,445 under the median of $15,444[4].

Lowest ask	$9,999
Middle half	$11,459 – $34,473
Median ask	$15,444
This car	$9,999

Same model year · 6 live listings · as of 29 Oct 2026

OTHER 2005 DODGE RAM LISTINGS [5]

Saskatoon, SK · 80,583 km	$39,997

§4 EVENTS

2005	Model year 2005[1] Assembly plant Fenton, Missouri, United States
12 Oct 2005	Transport Canada recall 2005307[2] Issued for the model year · Other
21 Jan 2009	Transport Canada recall 2009019[2] Issued for the model year · Steering
11 Mar 2009	Transport Canada recall 2009081[2] Issued for the model year · Electrical
14 Jul 2011	Transport Canada recall 2011253[2] Issued for the model year · Steering
7 Nov 2013	Transport Canada recall 2013395[2] Issued for the model year · Steering
19 Dec 2014	Transport Canada recall 2014582[2] Issued for the model year · Powertrain
6 Jan 2015	Transport Canada recall 2015003[2] Issued for the model year · Airbag
3 Mar 2015	Transport Canada recall 2015094[2] Issued for the model year · Airbag
3 Mar 2015	Transport Canada recall 2015093[2] Issued for the model year · Airbag
27 May 2015	Transport Canada recall 2015228[2] Issued for the model year · Airbag
27 May 2016	Transport Canada recall 2016265[2] Issued for the model year · Airbag

8 Jul 2026	Listed for sale, Fergus, ON[5] MELITA AUTO SALES · asking $9,999
28 Oct 2026	Listing last updated[5] asking $9,999

§5 DOCUMENTS

Window sticker — This VIN reads as model year 2005, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 6 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.