Register entry, as of 27 October 2026 Listed for sale Record ID 65f9a00ae86c

2007 Dodge Nitro SXT

3.7 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1D8	GU28K	X	7	W	653612
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dodge · FCA US LLC	Nitro · 3.7 L	Verified	2007	Toledo	Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	3.7 L, 6 cylinders
Make	Dodge	Fuel	Gasoline
Model	Nitro	Drive	4WD
Trim	SXT	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Toledo, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/nitro/2007

8 recalls listed by Transport Canada for this model year

Airbag

2020311 8 Jul 2020

Issue: On certain vehicles, the emblem on the steering wheel could become loose. If this happens, the emblem or its retainers could become projectiles when the airbag inflates in a crash. Safety Risk: Loose parts that are projected toward the occupants when an airbag deploys could increase the risk of an injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to replace the airbag cover on the steering wheel.

Powertrain

2013102 5 Apr 2013

On certain vehicles, the tunnel heat shield may drop down and rub on the drive shaft, which could eventually result in the drive shaft breaking and loss of motive power. In conjunction with traffic and road conditions and driver reactions, this could increase the risk of a crash. A broken drive shaft could also impact the tunnel with sufficient force to cause airbag deployment. Unintended airbag deployment, in a non-warranted (non-impact) situation could startle the driver which could result in a vehicle crash causing property damage and/or personal injury. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will install a heat shield support bracket.

Other

2009324 12 Nov 2009

On certain vehicles, high usage of the variable pause windshield wiper function (delay mode) may eventually affect primary wiper function, rendering the wiper system inoperable. Should this occur during a rainy/snowy day, it could increase the risk of a crash, causing property damage, personal injury or death. Correction: Dealers will add an external relay and update the wiper control software.

Other
2008372 10 Oct 2008

On certain vehicles equipped with a manual transmission, the park brake lever clutch drum may distort and reduce the effectiveness of the park brake system. This could allow the vehicle to move inadvertently and cause a crash without any warning. Correction: Dealers will replace the park brake lever assembly.

Brakes
2007305 17 Sep 2007

On certain vehicles, software programmed into the Antilock Brake System (ABS) electronic control module may allow a momentary delay in braking when coasting up a hill during certain conditions. This could cause a crash without warning. Correction: Dealers will reprogram the ABS electronic control module with updated software.

Other
2007221 5 Jul 2007

On certain vehicles, the Totally Integrated Power Module (TIPM) was programmed with software that may allow the engine to stall under certain operating conditions. This could cause a crash without warning. Correction: Dealers will reprogram the TIPM.

2 more on the model-year record, cardog.app/tools/recalls/dodge/nitro/2007

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $5,880[5], $2,440 over the median of $3,440[4].

Lowest ask	$5,880
Middle half	$2,220 – $4,660
Median ask	$3,440
This car	$5,880

Same model year · 2 live listings · as of 27 Oct 2026

OTHER 2007 DODGE NITRO LISTINGS [5]

Ottawa, ON · 340,000 km	$1,000

§4 EVENTS

2007	Model year 2007[1] Assembly plant Toledo, Ohio, United States
8 Sep 2006	Transport Canada recall 2006218[2] Issued for the model year · Powertrain
27 Dec 2006	Transport Canada recall 2006373[2] Issued for the model year · Brakes
5 Jul 2007	Transport Canada recall 2007221[2] Issued for the model year · Other

17 Sep 2007	Transport Canada recall 2007305[2] Issued for the model year · Brakes
10 Oct 2008	Transport Canada recall 2008372[2] Issued for the model year · Other
12 Nov 2009	Transport Canada recall 2009324[2] Issued for the model year · Other
5 Apr 2013	Transport Canada recall 2013102[2] Issued for the model year · Powertrain
8 Jul 2020	Transport Canada recall 2020311[2] Issued for the model year · Airbag
30 Sep 2026	Listed for sale, Coquitlam, BC[5] Zagros Auto Sales · asking $5,880
27 Oct 2026	Listing last updated[5] asking $5,880

§5 DOCUMENTS

Window sticker This VIN reads as model year 2007, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.