Register entry, as of 29 October 2026 Listed for sale Record ID 0100935bf256

2024 Ford Mustang GT

5.0 L, 8 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FA	6P8CF	0	R	5	426362
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company	Mustang · 5.0 L	Verified	2024	Flat Rock	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	5.0 L, 8 cylinders
Make	Ford	Fuel	Gasoline
Model	Mustang	Drive	Not in the decode
Trim	GT	Maker	FORD MOTOR COMPANY
Body	Coupe	Plant	Flat Rock, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/mustang/2024

10 recalls listed by Transport Canada for this model year

Electrical

2026408 25 Aug 2026

Issue: On certain vehicles, the engine wiring harness could become damaged. As a result, there could be a loss of power to the wheels, one or both headlamps could stop working, the windshield washer fluid pump may not work, and/or the engine cooling fan may not work. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. A loss of headlamps and/or a windshield that is not properly cleared could reduce visibility and could also increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine compartment wiring harness ground terminals.

Visual system

2026319 30 Jun 2026

Issue: On certain vehicles, a problem with the windshield wiper motor could cause it not to work properly in cold temperatures. If this happens, the windshield wipers may only operate at their high-speed setting and the windshield washing system may not work. Safety Risk: Windshield wipers and a windshield washing system that don't work properly can reduce visibility and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the windshield wiper motor.

Engine

2025549 11 Oct 2025

Issue: This recall is for supercharger upgrade kits that were installed before delivery or purchased from a dealer as an aftermarket accessory. Under certain conditions, the upgrade kit's powertrain control module (PCM) software may not work properly and could turn off certain safety features. If this happens, the vehicle could move and/or accelerate unexpectedly. Note: This recall only affects vehicles equipped with a 5.0 L engine. This problem could cause a malfunction indicator light or a wrench light to turn on in the instrument cluster. Safety Risk: A vehicle that moves and/or accelerates suddenly could create the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the PCM software.

Lights and instruments

2025434 22 Aug 2025

Issue: On certain vehicles, the body seams may not have been sealed properly. As a result, water could leak into the body control module (BCM). If this happens, the front and rear side marker lights, taillights and license plate lights may not work and/or flicker. Safety Risk: Exterior lights that don't work and/or flicker could make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect the body seams for proper sealing. The dealer will also inspect and, if necessary, replace the BCM.

Visual system

2025360 27 Jun 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the SYNC software.

Visual system

2025260 9 May 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display or to freeze when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the SYNC software. Alternatively, you may schedule an appointment to have the update performed at a Ford dealership.

4 more on the model-year record, cardog.app/tools/recalls/ford/mustang/2024

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $49,835[5], $4,036 under the median of $53,871[4].



Lowest ask	$43,978
Middle half	$50,633 – $59,990
Median ask	$53,871
This car	$49,835

Same configuration · 21 live listings · as of 29 Oct 2026

OTHER 2024 FORD MUSTANG LISTINGS [5]

Tillsonburg, ON · 21,000 km	$69,998
Tillsonburg, ON · 36,623 km	$51,995
Tillsonburg, ON · 6,526 km	$89,999
Calgary, AB · 5,500 km	$76,990
Spruce Grove, AB · 9,858 km	$76,488
Lévis,QC, QC · 22,756 km	$66,995

§4 EVENTS

2024	Model year 2024[1] Assembly plant Flat Rock, Michigan, United States
23 Mar 2024	Transport Canada recall 2024191[2] Issued for the model year · Fuel system
4 Jun 2024	Transport Canada recall 2024317[2] Issued for the model year · Powertrain
12 Aug 2024	Transport Canada recall 2024459[2] Issued for the model year · Suspension
25 Oct 2024	Transport Canada recall 2024645[2] Issued for the model year · Visual system
9 May 2025	Transport Canada recall 2025260[2] Issued for the model year · Visual system
27 Jun 2025	Transport Canada recall 2025360[2] Issued for the model year · Visual system
22 Aug 2025	Transport Canada recall 2025434[2] Issued for the model year · Lights and instruments
11 Oct 2025	Transport Canada recall 2025549[2] Issued for the model year · Engine
30 Jun 2026	Transport Canada recall 2026319[2] Issued for the model year · Visual system
25 Aug 2026	Transport Canada recall 2026408[2] Issued for the model year · Electrical
25 Oct 2026	Listed for sale, Winnipeg, MB[5] Capital Ford Lincoln Winnipeg · asking $49,835
29 Oct 2026	Listing last updated[5] asking $49,835

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 21 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.