Register entry, as of 28 October 2026 Listed for sale Record ID 78805787963c

2016 Ford Mustang GT Coupe

5.0 L, 8 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FA	6P8CF	6	G	5	308491
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company	Mustang · 5.0 L	Verified	2016	Flat Rock	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	5.0 L, 8 cylinders
Make	Ford	Fuel	Gasoline
Model	Mustang	Drive	Not in the decode
Trim	GT Coupe	Maker	FORD MOTOR COMPANY
Body	Coupe	Plant	Flat Rock, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/mustang/2016

7 recalls listed by Transport Canada for this model year

Seats and restraints — 2025484 — 12 Sep 2025

Issue: On certain vehicles, the driver and passenger-front seat belt pretensioner cable could corrode over time. As a result, the cable could break and the seat belt may not hold a person during a crash. Safety Risk: A seat belt that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the seat belt(s). The dealer will also modify the floor covering around the seat belt anchor pretensioner cables.

Visual system — 2025449 — 3 Sep 2025

Issue: On certain vehicles, there could be a problem with the connections inside the rearview camera. As a result, the rearview camera image may not display correctly or at all when the transmission is shifted into reverse. Note: For certain models, this recall also affects incomplete vehicles. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the rearview camera.

Seats and restraints — 2024605 — 11 Oct 2024

Issue: Ford Motor Company of Canada is conducting a parts recovery campaign targeting a random sample of 2015-2017 Ford Mustang vehicles in the Montreal area built between February 11, 2014 and October 2, 2017. The driver and front passenger seat belt assemblies are being recovered to aid in Ford's analysis in support of Transport Canada defect investigation file no. 3280-38-20. Note: This action is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: No safety defect has been identified with these seat belts. Corrective Actions: Ford will notify select owners by mail and advise them to take their vehicle to a dealership to replace the driver and front passenger seat belts at no charge.

Visual system

2022070 16 Feb 2022

Issue: On certain vehicles, opening and closing the trunk lid could damage the wiring for the rearview camera. If this happens, the rearview camera image may not display properly when you shift to reverse. Also, there could be a problem with the connections inside the rearview camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rearview camera and/or inspect and repair the decklid wiring.

Brakes

2020647 7 Dec 2020

This equipment recall is for replacement parts that were sold or installed by Ford dealerships between October 2019 and August 2020. This recall is not being conducted under the requirements of the Motor Vehicle Safety Act. Issue: On certain cars, the brake pedal and bracket assembly could fracture if rapid and forceful pressure is applied to the brake pedal, as typically seen during track and competition driving. If this happens, there could be a loss of braking. Note: This equipment recall only affects the following brake pedal and bracket assembly part numbers: FR3Z-2455-AA FR3Z-2455-AB Safety Risk: A loss of brakes can create the risk of a crash. Corrective Actions: Ford will notify its dealers of this recall. While dealers will attempt to contact people who may have purchased a part affected by this recall, if you have had the brake pedal and bracket assembly replaced on your car, you should contact the dealer that sold or installed it to find out if it is affected by this recall. Any part that is affected by this recall will be replaced, free of charge.

Engine

2016527 25 Oct 2016

On certain vehicles equipped with 5.2 litre V8 engines, the engine oil cooler tube assembly may have insufficient crimps. This could lead to a hose separating, which would cause an oil leak. The sudden loss of engine oil could result in an engine failure causing a loss of motive power, and an oil leak, in the presence of an ignition source could result in a fire. Both of these conditions could increase the risk of injury and/or property damage. Correction: Dealers will replace the engine oil cooler tube assembly.

1 more on the model-year record, cardog.app/tools/recalls/ford/mustang/2016

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $42,000[5], $7,010 over the median of $34,990[4].



Lowest ask	$15,480
Middle half	$21,054 – $76,492
Median ask	$34,990
This car	$42,000

Same model year · 27 live listings · as of 28 Oct 2026

OTHER 2016 FORD MUSTANG LISTINGS [5]

St-Rémi, QC · 18,977 km	$114,995
Notre-Dame-Des-Prairies, QC · 68,151 km	$33,795
Pitt Meadows, BC · 51,953 km	$23,500
Shawinigan, QC · 15,304 km	$109,995
Lévis, QC · 151,000 km	$16,450

§4 EVENTS

2016	Model year 2016[1] Assembly plant Flat Rock, Michigan, United States
27 Oct 2015	Transport Canada recall 2015508[2] Issued for the model year · Seats and restraints
25 Oct 2016	Transport Canada recall 2016527[2] Issued for the model year · Engine
7 Dec 2020	Transport Canada recall 2020647[2] Issued for the model year · Brakes
16 Feb 2022	Transport Canada recall 2022070[2] Issued for the model year · Visual system
11 Oct 2024	Transport Canada recall 2024605[2] Issued for the model year · Seats and restraints
3 Sep 2025	Transport Canada recall 2025449[2] Issued for the model year · Visual system
12 Sep 2025	Transport Canada recall 2025484[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Edmonton, AB[5] Freedom Ford Sales · asking $42,000
28 Oct 2026	Listing last updated[5] asking $42,000

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 27 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.