

Register entry, as of 28 October 2026

Listed for sale

Record ID d184b877b46e

2021 Ford Mustang I4 Coupe

2.3 L, 4 cylinders · RWD · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FA 6P8TD 1 M 5 127745

WMI 1-3

Ford Motor Company

DESCRIPTOR 4-8

Mustang · 2.3 L

CHECK 9

Verified

YEAR 10

2021

PLANT 11

Flatrock

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.3 L, 4 cylinders
Make	Ford	Fuel	Gasoline
Model	Mustang	Drive	RWD
Trim	I4 Coupe	Maker	FORD MOTOR COMPANY
Body	Coupe	Plant	Flatrock, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/mustang/2021

5 recalls listed by Transport Canada for this model year

Lights and instruments

2025703 18 Dec 2025

Issue: On certain vehicles, the recall repairs completed by a Ford dealer during recall 23C35 (Transport Canada recall no. 2023-587) may not have been done correctly. As a result, a second repair is required. On certain vehicles, a software problem could cause the low brake fluid warning lamp not to turn on if the brake fluid level gets too low. A low brake fluid level can cause reduced braking. Safety Risk: A driver that isn't aware of a low brake fluid level could experience reduced braking and an increased risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module software (BCM).

Fuel system

2025366 8 Jul 2025

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module software. For Super Duty models, the dealer will replace the fuel pump.

Lights and instruments

2023587 31 Oct 2023

Issue: On certain vehicles, a software problem could cause the low brake fluid warning lamp not to turn on if the brake fluid level gets too low. A low brake fluid level can cause reduced braking. Safety Risk: A driver that isn't aware of a low brake fluid level could experience reduced braking and an increased risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module software (BCM).



Airbag

2022075 17 Feb 2022

Issue: On a small number of vehicles, there may be a weld problem with the front passenger knee airbag. As a result, the knee airbag may not inflate properly in a crash. Safety Risk: An airbag that does not inflate properly could increase the risk of injury in a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front passenger knee airbag.

Airbag

2021769 17 Dec 2021


Issue: On a small number of vehicles, there may be a problem with the side curtain airbag inflators. As a result, the side curtain airbags may not inflate properly in a crash. Safety Risk: A side curtain airbag that does not inflate properly could increase the risk of injury in a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealer to replace the side curtain airbags.

Listed for the model year, not checked against your VIN. Ford confirms which apply.
Check your VIN with Ford Canada or call a Ford dealer with your VIN.
www.ford.ca/support/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$35,999^[5], \$6,996 under the median of \$42,995^[4].



Lowest ask	\$24,634
Middle half	\$34,699 – \$54,992
Median ask	\$42,995
This car	\$35,999

Same model year · 47 live listings · as of 28 Oct 2026

OTHER 2021 FORD MUSTANG LISTINGS ^[5]

Kitchener, ON · 69,509 km	\$46,575
Airdrie, AB · 47,056 km	\$39,373
London, ON · 69,509 km	\$46,575
Orangeville, ON · 39,409 km	\$48,999
Kirkland, QC · 567 km	\$199,500
Smiths Falls, ON · 77,000 km	\$24,634

§4 EVENTS

2021	Model year 2021 ^[1] Assembly plant Flatrock, Michigan, United States
17 Dec 2021	Transport Canada recall 2021769 ^[2] Issued for the model year · Airbag
17 Feb 2022	Transport Canada recall 2022075 ^[2] Issued for the model year · Airbag
31 Oct 2023	Transport Canada recall 2023587 ^[2] Issued for the model year · Lights and instruments



8 Jul 2025	Transport Canada recall 2025366 ^[2] Issued for the model year · Fuel system
24 Nov 2025	Listed for sale, Ontario, ON ^[5] Nawab Motors · asking \$35,999
18 Dec 2025	Transport Canada recall 2025703 ^[2] Issued for the model year · Lights and instruments
28 Oct 2026	Listing last updated ^[5] asking \$35,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 47 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

