Register entry, as of 27 October 2026 Listed for sale Record ID 8dd6bad70605

2025 Ford Mustang I4

2.3 L, 4 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FA	6P8TH	5	S	5	113847
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company	Mustang · 2.3 L	Verified	2025	Flat Rock	Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	2.3 L, 4 cylinders
Make	Ford	Fuel	Gasoline
Model	Mustang	Drive	Not in the decode
Trim	I4	Maker	FORD MOTOR COMPANY
Body	Coupe	Plant	Flat Rock, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/mustang/2025

6 recalls listed by Transport Canada for this model year

Electrical

2026408 25 Aug 2026

Issue: On certain vehicles, the engine wiring harness could become damaged. As a result, there could be a loss of power to the wheels, one or both headlamps could stop working, the windshield washer fluid pump may not work, and/or the engine cooling fan may not work. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. A loss of headlamps and/or a windshield that is not properly cleared could reduce visibility and could also increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine compartment wiring harness ground terminals.

Visual system

2026319 30 Jun 2026

Issue: On certain vehicles, a problem with the windshield wiper motor could cause it not to work properly in cold temperatures. If this happens, the windshield wipers may only operate at their high-speed setting and the windshield washing system may not work. Safety Risk: Windshield wipers and a windshield washing system that don't work properly can reduce visibility and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the windshield wiper motor.

Engine

2026094 3 Mar 2026

Issue: On certain vehicles, the exhaust gas recirculation (EGR) valve may not have been manufactured properly. As a result, the EGR valve could fail and cause a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 1.5 L engine, 2.0 L gas or hybrid engine or 2.3 L engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

Engine

2025549 11 Oct 2025

Issue: This recall is for supercharger upgrade kits that were installed before delivery or purchased from a dealer as an aftermarket accessory. Under certain conditions, the upgrade kit's powertrain control module (PCM) software may not work properly and could turn off certain safety features. If this happens, the vehicle could move and/or accelerate unexpectedly. Note: This recall only affects vehicles equipped with a 5.0 L engine. This problem could cause a malfunction indicator light or a wrench light to turn on in the instrument cluster. Safety Risk: A vehicle that moves and/or accelerates suddenly could create the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the PCM software.

Lights and instruments

2025434 22 Aug 2025

Issue: On certain vehicles, the body seams may not have been sealed properly. As a result, water could leak into the body control module (BCM). If this happens, the front and rear side marker lights, taillights and license plate lights may not work and/or flicker. Safety Risk: Exterior lights that don't work and/or flicker could make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect the body seams for proper sealing. The dealer will also inspect and, if necessary, replace the BCM.

Lights and instruments

2025417 8 Aug 2025

Issue: On certain vehicles, the light emitting diode (LED) driver module in the headlight assemblies could fail. If this happens, the high and low beam headlights, parking lights, daytime running lights and turn signal lights may not work. For Nautilus models, this could also cause the rear tail lights, turn signals and parking lights not to work. Note: This problem would cause an "Advanced Front Lighting Feature Temporarily Unavailable" warning message to be displayed and the turn signal telltale to flash at the same speed as when a turn signal bulb fails. Safety Risk: Headlights and/or exterior lights that don't work properly could cause reduce visibility and/or make the vehicle less visible to others. Turn signals that don't work properly may cause a person not to recognize when a driver intends to turn or change lanes. These issues could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the LED driver module.

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $34,488[5], $9,657 under the median of $44,145[4].

Lowest ask	$34,488
Middle half	$41,990 – $44,889
Median ask	$44,145
This car	$34,488

Same configuration · 9 live listings · as of 27 Oct 2026

OTHER 2025 FORD MUSTANG LISTINGS [5]

Montréal Nord, QC · 4,000 km	$58,895
Surrey, BC · 29,400 km	$38,885
Toronto, ON · 17,788 km	$47,988
Calgary, AB · 9,047 km	$41,990
Watford, ON · 4,268 km	$60,577
Courtenay, BC · 15,160 km	$39,895

§4 EVENTS

2025	Model year 2025[1] Assembly plant Flat Rock, Michigan, United States
8 Aug 2025	Transport Canada recall 2025417[2] Issued for the model year · Lights and instruments
22 Aug 2025	Transport Canada recall 2025434[2] Issued for the model year · Lights and instruments
11 Oct 2025	Transport Canada recall 2025549[2] Issued for the model year · Engine
3 Mar 2026	Transport Canada recall 2026094[2] Issued for the model year · Engine
30 Jun 2026	Transport Canada recall 2026319[2] Issued for the model year · Visual system
25 Aug 2026	Transport Canada recall 2026408[2] Issued for the model year · Electrical
7 Oct 2026	Listed for sale, Mississauga, ON[5] B Town Auto Sales · asking $34,488
27 Oct 2026	Listing last updated[5] asking $34,488

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 9 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.