

Register entry, as of 27 October 2026

Listed for sale

Record ID ac583edc1d8c

1999 Ford Taurus LX

3.0 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FA FP52U 3 X G 190533

WMI 1-3

Ford Motor Company

DESCRIPTOR 4-8

Taurus · 3.0 L

CHECK 9

Verified

YEAR 10

1999

PLANT 11

Chicago

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	1999	Engine	3.0 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Taurus	Drive	Not in the decode
Trim	LX	Maker	FORD MOTOR COMPANY
Body	Sedan	Plant	Chicago, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/taurus/1999

4 recalls listed by Transport Canada for this model year

Suspension

2004252 19 Jul 2004

On certain vehicles, the front coil springs may fracture when operated in high corrosion areas (where salt is used on the roadways in winter). The potential for corrosion causing a spring to fracture increases with the number of kilometres and years in service on the vehicle. A fractured spring could move past the spring seat and contact a front tire causing a rupture resulting in a rapid air loss. Correction: For vehicles sold in or are currently registered in the provinces of Ontario, Quebec, New Brunswick, Prince Edward Island, Nova Scotia, Newfoundland and Labrador, dealers will install protective spring shields as specified in recall campaign 04S17. In addition, Ford will notify nationwide all 1999 to 2001 Taurus and Sable owners of a Customer Satisfaction Program 04M04 in which Ford will provide additional repair coverage for replacement of fractured front coil springs for a period of 10 years from the original date of sale of the vehicle, or up to 240 000 kilometres, whichever occurs first.

Seats and restraints

1999176 19 Oct 1999

On certain vehicles, the seat belt retractor in certain seating positions may have a pin shaft in the switchable ELR/ALR(emergency locking retractor/automatic locking retractor) mechanism that is incorrectly formed. In some circumstances, the switching mechanism could become non-functional, which could prevent the seat belt webbing from being extracted from the retractor. Correction: Affected vehicles will be inspected and suspect lap and shoulder belt assemblies will be replaced.

Structure

1998182 18 Sep 1998

THE DASH INSULATOR RETAINER MAY NOT HAVE BEEN FULLY ENGAGED. THE RETAINER MAY DISENGAGE, AND IN SOME CASES IT COULD BECOME LODGED ABOVE THE ACCELERATOR PEDAL PIVOT. THIS COULD PREVENT THE ENGINE FROM FULLY RETURNING TO IDLE. CORRECTION: VEHICLES WILL BE INSPECTED FOR PROPER INSTALLATION OF THE DASH INSULATOR RETAINER AND RE-INSTALL IF REQUIRED.



Seats and restraints

1998173 28 Aug 1998

THESE VEHICLES MAY HAVE A FRONT SEAT BELT BUCKLE ATTACHING STUD THAT MAY HAVE BEEN IMPROPERLY HEAT TREATED. THIS HEAT TREATING MAY HAVE RESULTED IN CRACKS DEVELOPING IN THE STUD. IF THE STUD IS CRACKED, THERE IS THE POTENTIAL FOR LESS THAN THE INTENDED LEVEL OF OCCUPANT RESTRAINT IN THE EVENT OF A VEHICLE CRASH. CORRECTION: SEAT BELT BUCKLE MOUNTING BRACKET AND STUD ASSEMBLY WILL BE REPLACED ON AFFECTED VEHICLES.

Listed for the model year, not checked against your VIN. Ford confirms which apply.
Check your VIN with Ford Canada or call a Ford dealer with your VIN.
www.ford.ca/support/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$2,995^[5], the median^[4].



Lowest ask	\$2,995
Middle half	\$2,995 – \$2,995
Median ask	\$2,995
This car	\$2,995

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

1999	Model year 1999 ^[1] Assembly plant Chicago, Illinois, United States
28 Aug 1998	Transport Canada recall 1998173 ^[2] Issued for the model year · Seats and restraints
18 Sep 1998	Transport Canada recall 1998182 ^[2] Issued for the model year · Structure
19 Oct 1999	Transport Canada recall 1999176 ^[2] Issued for the model year · Seats and restraints
19 Jul 2004	Transport Canada recall 2004252 ^[2] Issued for the model year · Suspension
7 Oct 2026	Listed for sale, Burnaby, BC ^[5] HANIN MOTORS · asking \$2,995
26 Oct 2026	Listing last updated ^[5] asking \$2,995



§5 DOCUMENTS

Window sticker This VIN reads as model year 1999, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

