

Register entry, as of 26 October 2026

Listed for sale

Record ID fb72540310bd

2002 Ford Taurus SE

3.0 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FA FP53U 8 2 G 273172

WMI 1-3

Ford Motor Company

DESCRIPTOR 4-8

Taurus · 3.0 L

CHECK 9

Verified

YEAR 10

2002

PLANT 11

Chicago

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2002	Engine	3.0 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Taurus	Drive	Not in the decode
Trim	SE	Maker	FORD MOTOR COMPANY
Body	Sedan	Plant	Chicago, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/taurus/2002

2 recalls listed by Transport Canada for this model year

Lights and instruments

2004092 12 Mar 2004

On certain vehicles, a malfunctioning stop lamp switch and/or associated wiring may render the stop lamps inoperable or cause them to stay on all the time. If the switch and/or wiring fail in the open position, the brake lights will not activate and the driver will not be able to shift the vehicle out of park. If they fail in the closed position, the brake lights will remain on, which will not allow the speed control to be activated. This could also cause the battery to discharge. Correction: Dealer will install a newly designed stop lamp switch and wire assembly.

Other

2002187 11 Oct 2002

On certain vehicles equipped with adjustable pedals, the manufacturing process of the subject Taurus adjustable pedal assembly resulted in variability in lateral pedal spacing ranging from 41mm to 85mm. Discussions with drivers of vehicles with adjustable pedals disclosed that some were unfamiliar with the feature. Decreased brake to accelerator pedal spacing may increase the risk of simultaneous application of the brake and accelerator pedals which may cause a collision, injuries or death. Correction: Owners will be instructed as to the proper way to set the position of the pedals and to take their vehicles to a dealer to have the spacing between the brake and accelerator pedal measured. If the spacing is found to be less than 50mm, the dealer will adjust the pedals to increase the distance between them to greater than 50mm.

Listed for the model year, not checked against your VIN. Ford confirms which apply.

Check your VIN with Ford Canada or call a Ford dealer with your VIN.


www.ford.ca/support/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing. [3]



§3 VALUE [4]

This car asks \$4,589^[5], the median^[4].



Lowest ask	\$4,589
Middle half	\$4,589 – \$4,589
Median ask	\$4,589
This car	\$4,589

Same model year · 1 live listings · as of 26 Oct 2026

§4 EVENTS

2002	Model year 2002 ^[1] Assembly plant Chicago, Illinois, United States
11 Oct 2002	Transport Canada recall 2002187 ^[2] Issued for the model year · Other
12 Mar 2004	Transport Canada recall 2004092 ^[2] Issued for the model year · Lights and instruments
22 Aug 2026	Listed for sale, Castlegar, BC ^[5] Glacier Honda · asking \$4,589
26 Oct 2026	Listing last updated ^[5] asking \$4,589

§5 DOCUMENTS

Window sticker This VIN reads as model year 2002, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 1 live listings, as of 26 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 26 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

