Register entry, as of 29 October 2026 Listed for sale Record ID 3280373ad956

2018 Ford Explorer XLT

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FM	5K8D8	9	J	G	B20379
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company	Explorer · 3.5 L	Verified	2018	Chicago	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Explorer	Drive	4WD
Trim	XLT	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Chicago, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/explorer/2018

8 recalls listed by Transport Canada for this model year

Structure

2026341 14 Jul 2026

Issue: On certain vehicles, the repairs completed by a Ford dealer during customer satisfaction program 20N11 may not be effective. As a result, a second repair is required. On certain vehicles, the roof rail covers could become loose and detach while driving. Note: This recall is an expansion of Transport Canada recall no. 2021-267. Vehicles repaired under that recall don't require this repair. Safety Risk: A roof rail cover that detaches while driving could create a hazard for other road users and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, secure the roof rail covers.

Suspension

2026080 20 Feb 2026

Issue: On certain vehicles, the outer ball joint for the rear suspension toe link(s) may seize. If this happens, the toe link(s) could break while driving. This could cause a sudden loss of vehicle stability. Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the rear suspension toe links.

Electrical

2026005 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall replaces Transport Canada recall no. 2025-554. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

Electrical

2025554 10 Oct 2025

This recall was replaced by Transport Canada recall no. 2026-005. Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater.

Structure

2024026 22 Jan 2024

Issue: On certain vehicles, the exterior A-pillar trim on either side of the windshield may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the A-pillar trim.

Structure

2021267 6 May 2021

Issue: On certain vehicles, the roof rail covers could detach. If this happens while driving, the roof rail cover could separate from the vehicle. Note: This recall only affects vehicles with painted roof rail covers. Safety Risk: A roof rail cover that detaches while driving could create a hazard for other drivers and nearby people, and could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealer to secure the roof rail covers.

2 more on the model-year record, cardog.app/tools/recalls/ford/explorer/2018

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $13,795[5], $3,700 under the median of $17,495[4].



Lowest ask	$6,900
Middle half	$13,991 – $18,995
Median ask	$17,495
This car	$13,795

Same configuration · 29 live listings · as of 29 Oct 2026

OTHER 2018 FORD EXPLORER LISTINGS [5]

Laval, QC · 147,674 km	$13,991
Toronto, ON · 108,952 km	$22,995
Hearst, ON · 68,490 km	$22,500
Blainville, QC · 64,630 km	$20,987
Edmonton, AB · 145,106 km	$21,849

§4 EVENTS

2018 Model year 2018[1]
Assembly plant Chicago, Illinois, United States

26 Jul 2019	Transport Canada recall 2019368[2] Issued for the model year · Electrical
29 Aug 2019	Transport Canada recall 2019437[2] Issued for the model year · Seats and restraints
6 May 2021	Transport Canada recall 2021267[2] Issued for the model year · Structure
22 Jan 2024	Transport Canada recall 2024026[2] Issued for the model year · Structure
10 Oct 2025	Transport Canada recall 2025554[2] Issued for the model year · Electrical
9 Jan 2026	Transport Canada recall 2026005[2] Issued for the model year · Electrical
20 Feb 2026	Transport Canada recall 2026080[2] Issued for the model year · Suspension
14 Jul 2026	Transport Canada recall 2026341[2] Issued for the model year · Structure
27 Oct 2026	Listed for sale, Hamilton, ON[5] Airport Ford - Hamilton · asking $13,795
29 Oct 2026	Listing last updated[5] asking $13,795

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 29 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.