

Register entry, as of 27 October 2026

Listed for sale

Record ID 2de650651e25

2016 Ford Explorer Limited

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FM 5K8F8 1 G G B37487

WMI 1-3

Ford Motor Company

DESCRIPTOR 4-8

Explorer · 3.5 L

CHECK 9

Verified

YEAR 10

2016

PLANT 11

Chicago

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Explorer	Drive	4WD
Trim	Limited	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Chicago, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/explorer/2016

16 recalls listed by Transport Canada for this model year

Structure

2026341 14 Jul 2026

Issue: On certain vehicles, the repairs completed by a Ford dealer during customer satisfaction program 20N11 may not be effective. As a result, a second repair is required. On certain vehicles, the roof rail covers could become loose and detach while driving. Note: This recall is an expansion of Transport Canada recall no. 2021-267. Vehicles repaired under that recall don't require this repair. Safety Risk: A roof rail cover that detaches while driving could create a hazard for other road users and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, secure the roof rail covers.

Electrical

2026005 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall replaces Transport Canada recall no. 2025-554. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

Electrical

2025554 10 Oct 2025

This recall was replaced by Transport Canada recall no. 2026-005. Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater.



Structure

2025282 23 May 2025

Issue: On certain vehicles, the exterior B-pillar trims on the driver and front passenger doors may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, secure the B-pillar trims.

Structure

2024026 22 Jan 2024

Issue: On certain vehicles, the exterior A-pillar trim on either side of the windshield may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the A-pillar trim.

Suspension

2021438 16 Jul 2021

Issue: On certain vehicles, the outer ball joint for the rear suspension toe link may seize. If this happens, the toe link could break while driving. This could cause a sudden loss of vehicle stability. Note: This recall only affects vehicles equipped with a rear ball joint manufactured by ZF. Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear suspension toe links and inspect the ball joints. If a ball joint requires replacement, the dealer will replace the rear suspension knuckle.

10 more on the model-year record, cardog.app/tools/recalls/ford/explorer/2016

Listed for the model year, not checked against your VIN. Ford confirms which apply.

Check your VIN with Ford Canada or call a Ford dealer with your VIN.

www.ford.ca/support/recalls/

United States: 15 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$19,980^[5], \$6,137 over the median of \$13,843^[4].



Lowest ask	\$10,295
Middle half	\$11,997 – \$17,496
Median ask	\$13,843
This car	\$19,980

Same configuration · 8 live listings · as of 27 Oct 2026

OTHER 2016 FORD EXPLORER LISTINGS [5]

Oakville, ON · 217,079 km	\$10,995
Harriston, ON · 194,000 km	\$10,000
Kingston, ON · 178,295 km	\$14,888
Fort McMurray, AB · 142,012 km	\$14,693
Kingston, ON · 172,106 km	\$13,888
Lethbridge, AB · 154,826 km	\$16,990



§4 EVENTS

2016	Model year 2016 ^[1] Assembly plant Chicago, Illinois, United States
21 Jul 2015	Transport Canada recall 2015321 ^[2] Issued for the model year · Brakes
29 Sep 2015	Transport Canada recall 2015436 ^[2] Issued for the model year · Fuel system
31 Mar 2016	Transport Canada recall 2016138 ^[2] Issued for the model year · Engine
28 Jun 2016	Transport Canada recall 2016329 ^[2] Issued for the model year · Seats and restraints
25 Apr 2017	Transport Canada recall 2017224 ^[2] Issued for the model year · Suspension
30 Nov 2017	Transport Canada recall 2017593 ^[2] Issued for the model year · Seats and restraints
11 Jun 2019	Transport Canada recall 2019280 ^[2] Issued for the model year · Suspension
3 Nov 2020	Transport Canada recall 2020524 ^[2] Issued for the model year · Suspension
11 Nov 2020	Transport Canada recall 2020536 ^[2] Issued for the model year · Powertrain
6 May 2021	Transport Canada recall 2021267 ^[2] Issued for the model year · Structure
16 Jul 2021	Transport Canada recall 2021438 ^[2] Issued for the model year · Suspension
22 Jan 2024	Transport Canada recall 2024026 ^[2] Issued for the model year · Structure
23 May 2025	Transport Canada recall 2025282 ^[2] Issued for the model year · Structure
10 Oct 2025	Transport Canada recall 2025554 ^[2] Issued for the model year · Electrical
9 Jan 2026	Transport Canada recall 2026005 ^[2] Issued for the model year · Electrical
14 Jul 2026	Transport Canada recall 2026341 ^[2] Issued for the model year · Structure
26 Oct 2026	Listed for sale, Victoria, BC ^[5] Wheaton Chevrolet Buick Cadillac GMC · asking \$19,980



27 Oct 2026 Listing last updated^[5]
asking \$19,980

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 8 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

