Register entry, as of 28 October 2026 Listed for sale Record ID dd3e3000d2f0

2013 Ford Escape SE

1.6 L, 4 cylinders · 4x2 · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FM	CU0GX	3	D	U	A27496
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company	Escape · 1.6 L	Verified	2013	Louisville	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	1.6 L, 4 cylinders
Make	Ford	Fuel	Gasoline
Model	Escape	Drive	4x2
Trim	SE	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Louisville, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/escape/2013

16 recalls listed by Transport Canada for this model year

Electrical

2026004 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall only affects certain vehicles equipped with a 2.0 L engine. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

Powertrain

2022311 13 Jun 2022

Issue: On certain vehicles, the shift cable may detach from the transmission. This could cause the transmission not to shift gears when the shifter is moved. As a result, the transmission could be in a different gear than the gear shifter indicates. If a driver attempts to exit the vehicle while the transmission is not in Park, and the parking brake is not applied, the vehicle could move suddenly. Safety Risk: Sudden and unexpected movement of the vehicle could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealership to replace the transmission shifter cable bushing and install a protective service cap. Ford advises that you should apply the parking brake each time the vehicle is parked.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Powertrain

2018379 17 Jul 2018

On certain vehicles, the bushing that attaches the shift cable to the transmission may degrade over time and could detach. This could allow the transmission to be in a gear state different than the gear shift position selected by the driver. This condition could also allow the driver to move the shifter to Park and remove the ignition key while the transmission gear may not be in Park. If the parking brake is not applied, this could result in unintended vehicle movement, which would increase the risk of crash causing injury and/or damage to property. Correction: Dealers will replace the shifter cable bushing.

Structure

2016432 6 Sep 2016

On certain vehicles, the pawl spring tab in the side door latch could break. This condition typically will prevent the door from latching. In certain situations where the door is able to be closed, the door may be partially latched and could unlatch while driving. This could increase the risk of injury to a vehicle occupant seated next to the door, or result in damage to property. Correction: If a door will not latch, dealers will replace all four door latches with a more robust part. Note: A door that is partially latched can cause the courtesy light to remain on, set a door ajar message in the instrument cluster and sound a door ajar chime to alert the driver that there is a door latch problem.

Seats and restraints

2014427 30 Sep 2014

On certain vehicles, sealant applied to the restraints control module could fail, allowing moisture to enter the module circuit board. This could cause corrosion to form, which will illuminate the airbag warning light and could affect restraint system function, potentially disabling airbags or other safety systems. This could increase the risk of injury to vehicle occupants in a crash where airbag deployment is warranted. Correction: Dealers will replace the restraints control module.

10 more on the model-year record, cardog.app/tools/recalls/ford/escape/2013

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 18 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,900[5], $1,901 over the median of $5,999[4].

Lowest ask	$2,799
Middle half	$3,300 – $7,995
Median ask	$5,999
This car	$7,900

Same configuration · 9 live listings · as of 28 Oct 2026

OTHER 2013 FORD ESCAPE LISTINGS [5]

Sundridge, ON · 245,346 km	$5,995
London, ON · 247,478 km	$3,022
Wetaskiwin, AB · 268,800 km	$5,999

Fernie, BC · 120,119 km	$13,488
London, ON · 247,478 km	$4,000
Moose Jaw, SK · 154,917 km	$10,992

§4 EVENTS

2013	Model year 2013[1] Assembly plant Louisville, Kentucky, United States
4 Jul 2012	Transport Canada recall 2012197[2] Issued for the model year · Brakes
18 Jul 2012	Transport Canada recall 2012218[2] Issued for the model year · Fuel system
4 Sep 2012	Transport Canada recall 2012298[2] Issued for the model year · Engine
30 Nov 2012	Transport Canada recall 2012399[2] Issued for the model year · Engine
6 Mar 2013	Transport Canada recall 2013075[2] Issued for the model year · Structure
27 Nov 2013	Transport Canada recall 2013424[2] Issued for the model year · Fuel system
2 Apr 2014	Transport Canada recall 2014109[2] Issued for the model year · Seats and restraints
7 May 2014	Transport Canada recall 2014164[2] Issued for the model year · Airbag
7 May 2014	Transport Canada recall 2014163[2] Issued for the model year · Structure
12 Aug 2014	Transport Canada recall 2014349[2] Issued for the model year · Electrical
30 Sep 2014	Transport Canada recall 2014427[2] Issued for the model year · Seats and restraints
6 Sep 2016	Transport Canada recall 2016432[2] Issued for the model year · Structure
17 Jul 2018	Transport Canada recall 2018379[2] Issued for the model year · Powertrain
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
13 Jun 2022	Transport Canada recall 2022311[2] Issued for the model year · Powertrain

9 Jan 2026	Transport Canada recall 2026004[2] Issued for the model year · Electrical
25 Oct 2026	Listed for sale, St Jacobs, ON[5] Mose Martins Garage Limited · asking $7,900

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.