Register entry, as of 27 October 2026 Listed for sale Record ID d96b294367bd

# 2020 Ford Escape Titanium

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1FM | CU9J9 | 0 | L | U | C42914 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ford Motor Company | Escape · 2.0 L | Verified | 2020 | Louisville | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 2.0 L, 4 cylinders |
| Make | Ford | Fuel | Gasoline |
| Model | Escape | Drive | 4WD |
| Trim | Titanium | Maker | FORD MOTOR COMPANY |
| Body | Sport Utility Vehicle | Plant | Louisville, Kentucky, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/escape/2020

**23** recalls listed by Transport Canada for this model year

### Visual system — 2026100 — 5 Mar 2026

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display properly when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

### Visual system — 2026098 — 3 Mar 2026

Issue: On certain vehicles, the windshield wiper motor may not have been manufactured properly. As a result, the motor could fail and cause the windshield wipers not to work. Safety Risk: Windshield wipers that don't work could reduce visibility and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the windshield wiper motor.

### Engine — 2026072 — 18 Feb 2026

Issue: On a small number of vehicles, the recall repairs completed by a Ford dealer during recall 25S54 (Transport Canada recall no. 2025-283) may not have been done correctly. As a result, another repair is required. On certain vehicles equipped with a 2.5 L HEV or PHEV engine, a manufacturing problem could lead to an engine failure. In some cases, an engine failure can create the risk of a fire. Safety Risk: An engine failure could cause a fire. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module (PCM) software. To reduce the safety risk, Ford recommends that you should shut off the engine as soon as possible if you hear unusual engine noises, see smoke from the engine compartment, or notice reduced engine power.

### High voltage

2026070 18 Feb 2026

Issue: On certain vehicles, the software update installed by a Ford dealer during recall 24S79 (Transport Canada recall no. 2024-781) may not be effective. As a result, a second repair is required. On certain vehicles, a problem inside the high-voltage battery could cause a short circuit. If this happens, there could be a loss of power to the wheels and/or the high-voltage battery could overheat. Note: This recall replaces Transport Canada recall no. 2025-628. This recall only affects certain plug-in hybrid vehicles (PHEV) equipped with a 2.5 L engine. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A battery that overheats can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, Ford advises that you set the maximum charge setting of your vehicle at 80% and to only use normal EV mode until the recall repairs have been completed. Ford will notify owners by mail. The corrective actions for this recall are under development.

### Electrical

2026005 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall replaces Transport Canada recall no. 2025-554. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

### Structure

2025665 1 Dec 2025

Issue: On certain vehicles, the hinge covers for the liftgate may not have been properly attached. As a result, the cover(s) could loosen and detach from the vehicle. Safety Risk: Parts that detach from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and secure or replace the liftgate hinge covers, as necessary.

17 more on the model-year record, cardog.app/tools/recalls/ford/escape/2020

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 25 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $18,787[5], $3,449 under the median of $22,236[4].

| | |
|---|---|
| Lowest ask | $18,787 |
| Middle half | $21,993 – $22,986 |
| Median ask | $22,236 |
| This car | $18,787 |

Same configuration · 8 live listings · as of 27 Oct 2026

OTHER 2020 FORD ESCAPE LISTINGS [5]

| | |
|---|---|
| Rouyn Noranda, QC · 130,000 km | $18,995 |
| Regina, SK · 101,320 km | $18,995 |
| Airdrie, AB · 110,507 km | $22,477 |
| Duncan, BC · 50,848 km | $19,999 |
| Saint-Hyacinthe, QC · 87,498 km | $15,791 |
| Barrie, ON · 189,326 km | $14,998 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant Louisville, Kentucky, United States |
| 24 Sep 2020 | Transport Canada recall 2020454[2]<br>Issued for the model year · Visual system |
| 15 Oct 2020 | Transport Canada recall 2020483[2]<br>Issued for the model year · Electrical |
| 18 Jan 2021 | Transport Canada recall 2021011[2]<br>Issued for the model year · Powertrain |
| 29 Mar 2022 | Transport Canada recall 2022152[2]<br>Issued for the model year · Engine |
| 16 May 2022 | Transport Canada recall 2022253[2]<br>Issued for the model year · High voltage |
| 7 Jul 2022 | Transport Canada recall 2022366[2]<br>Issued for the model year · Engine |
| 19 Nov 2022 | Transport Canada recall 2022658[2]<br>Issued for the model year · Fuel system |
| 29 May 2023 | Transport Canada recall 2023309[2]<br>Issued for the model year · Engine |
| 10 May 2024 | Transport Canada recall 2024270[2]<br>Issued for the model year · Powertrain |
| 20 Dec 2024 | Transport Canada recall 2024781[2]<br>Issued for the model year · High voltage |
| 14 Mar 2025 | Transport Canada recall 2025134[2]<br>Issued for the model year · Engine |
| 23 May 2025 | Transport Canada recall 2025283[2]<br>Issued for the model year · Engine |
| 27 Jun 2025 | Transport Canada recall 2025360[2]<br>Issued for the model year · Visual system |
| 14 Jul 2025 | Transport Canada recall 2025376[2]<br>Issued for the model year · Engine |
| 10 Oct 2025 | Transport Canada recall 2025554[2]<br>Issued for the model year · Electrical |
| 11 Oct 2025 | Transport Canada recall 2025553[2]<br>Issued for the model year · Brakes |
| 14 Nov 2025 | Transport Canada recall 2025628[2]<br>Issued for the model year · High voltage |

| | |
|---|---|
| 1 Dec 2025 | Transport Canada recall 2025665[2]<br>Issued for the model year · Structure |
| 9 Jan 2026 | Transport Canada recall 2026005[2]<br>Issued for the model year · Electrical |
| 18 Feb 2026 | Transport Canada recall 2026072[2]<br>Issued for the model year · Engine |
| 18 Feb 2026 | Transport Canada recall 2026070[2]<br>Issued for the model year · High voltage |
| 3 Mar 2026 | Transport Canada recall 2026098[2]<br>Issued for the model year · Visual system |
| 5 Mar 2026 | Transport Canada recall 2026100[2]<br>Issued for the model year · Visual system |
| 26 Oct 2026 | Listed for sale, Lévis, QC[5]<br>normautos.com · asking $18,787 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 8 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.