Register entry, as of 29 November 2026 Listed for sale Record ID 0e019dc79033

# 2025 Ford Bronco Big Bend

2.3 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1FM | DE7BH | 8 | S | L | A59230 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ford Motor Company | Bronco · 2.3 L | Verified | 2025 | Wayne | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 2.3 L, 4 cylinders |
| Make | Ford | Fuel | Gasoline |
| Model | Bronco | Drive | 4WD |
| Trim | Big Bend | Maker | FORD MOTOR COMPANY |
| Body | Sport Utility Vehicle | Plant | Wayne, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/bronco/2025

**12** recalls listed by Transport Canada for this model year

### Electrical — 2026356 — 20 Jul 2026

Issue: On certain vehicles, the engine wiring harness may not have enough protection and could become damaged by contact with surrounding components. As a result, the wiring harness could short circuit. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to install additional protection on the engine wiring harness. The dealer will also repair or replace the engine wiring harness, as necessary.

### Accessories — 2026310 — 24 Jun 2026

Issue: On certain vehicles, the fender flare(s) may not be properly attached. As a result, the fender flare(s) could loosen and separate from the vehicle. Note: This recall only affects Bronco Raptor models. Safety Risk: A fender flare that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and repair or replace the fender flares, as necessary.

### Engine — 2026258 — 27 May 2026

Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, the engine could fail and cause a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 2.3 L engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine.

### Seats and restraints

2026211 28 Apr 2026

Issue: On certain vehicles, the pivot bolts in the height adjuster assembly for the front seats may not have been manufactured properly. As a result, the bolt(s) could loosen and detach. If this happens, the seat(s) could move in a crash. Safety Risk: A seat that moves in a crash could increase the risk of injury. Corrective Action: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the height-adjust link(s) and pivot bolts.

### Powertrain

2026188 15 Apr 2026

Issue: On certain vehicles, the transmission may not have been reassembled properly after service. As a result, the transmission output shaft splines and/or the transfer case input splines could wear and fail. If this happens, there could be a loss of power to the wheels, or the vehicle could move when it's parked and the parking brake isn't used. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the transmission and transfer case.

### Engine

2026094 3 Mar 2026

Issue: On certain vehicles, the exhaust gas recirculation (EGR) valve may not have been manufactured properly. As a result, the EGR valve could fail and cause a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 1.5 L engine, 2.0 L gas or hybrid engine or 2.3 L engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

6 more on the model-year record, cardog.app/tools/recalls/ford/bronco/2025

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 19 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $46,399[5], $855 under the median of $47,254[4].




| | |
|---|---|
| Lowest ask | $44,796 |
| Middle half | $45,992 – $49,838 |
| Median ask | $47,254 |
| This car | $46,399 |

Same configuration · 22 live listings · as of 28 Nov 2026

### OTHER 2025 FORD BRONCO LISTINGS [5]

| | |
|---|---|
| Campbell River, BC · 6,095 km | $64,880 |
| Richmond, BC · 44,736 km | $43,997 |
| Richmond, BC · 33,976 km | $44,997 |
| Lloydminster, AB · 34,772 km | $63,585 |
| Toronto, ON · 31,132 km | $65,130 |
| Toronto, ON · 52,616 km | $80,875 |

## §4 EVENTS

| | |
|---|---|
| 2025 | Model year 2025[1]<br>Assembly plant Wayne, Michigan, United States |
| 13 Jun 2025 | Transport Canada recall 2025325[2]<br>Issued for the model year · Structure |
| 13 Jun 2025 | Transport Canada recall 2025323[2]<br>Issued for the model year · Airbag |
| 25 Jul 2025 | Transport Canada recall 2025392[2]<br>Issued for the model year · Brakes |
| 14 Nov 2025 | Transport Canada recall 2025627[2]<br>Issued for the model year · Visual system |
| 1 Dec 2025 | Transport Canada recall 2025663[2]<br>Issued for the model year · Brakes |
| 3 Mar 2026 | Transport Canada recall 2026094[2]<br>Issued for the model year · Engine |
| 3 Mar 2026 | Transport Canada recall 2026093[2]<br>Issued for the model year · Visual system |
| 15 Apr 2026 | Transport Canada recall 2026188[2]<br>Issued for the model year · Powertrain |
| 28 Apr 2026 | Transport Canada recall 2026211[2]<br>Issued for the model year · Seats and restraints |
| 27 May 2026 | Transport Canada recall 2026258[2]<br>Issued for the model year · Engine |
| 24 Jun 2026 | Transport Canada recall 2026310[2]<br>Issued for the model year · Accessories |
| 20 Jul 2026 | Transport Canada recall 2026356[2]<br>Issued for the model year · Electrical |
| 28 Nov 2026 | Listed for sale, St. Catharines, ON[5]<br>ED LEARN FORD · asking $46,399 |
| 29 Nov 2026 | Listing last updated[5]<br>asking $46,399 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 22 live listings, as of 28 Nov 2026
[5] Live public dealer listings on Cardog, as of 29 Nov 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.