

Register entry, as of 28 October 2026

Listed for sale

Record ID 07aaa83edf1c

2023 Ford Bronco Base, Big Bend, Black Diamond, Outer Banks, Badlands, Wildtrak, Everglades

2.7 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FM EE5DP 2 P L B66813

WMI 1-3

Ford Motor Company

DESCRIPTOR 4-8

Bronco · 2.7 L

CHECK 9

Verified

YEAR 10

2023

PLANT 11

Wayne

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.7 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Bronco	Drive	AWD
Trim	Base, Big Bend, Black Diamond, Outer Banks, Badlands, Wildtrak, Everglades	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Wayne, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/bronco/2023

18 recalls listed by Transport Canada for this model year

Electrical

2026356 20 Jul 2026

Issue: On certain vehicles, the engine wiring harness may not have enough protection and could become damaged by contact with surrounding components. As a result, the wiring harness could short circuit. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to install additional protection on the engine wiring harness. The dealer will also repair or replace the engine wiring harness, as necessary.

Accessories

2026310 24 Jun 2026

Issue: On certain vehicles, the fender flare(s) may not be properly attached. As a result, the fender flare(s) could loosen and separate from the vehicle. Note: This recall only affects Bronco Raptor models. Safety Risk: A fender flare that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and repair or replace the fender flares, as necessary.



Powertrain

2026188 15 Apr 2026

Issue: On certain vehicles, the transmission may not have been reassembled properly after service. As a result, the transmission output shaft splines and/or the transfer case input splines could wear and fail. If this happens, there could be a loss of power to the wheels, or the vehicle could move when it's parked and the parking brake isn't used. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the transmission and transfer case.

Visual system

2026093 3 Mar 2026

Issue: Under certain conditions, the infotainment system could overheat. As a result, the rearview camera image may not display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the accessory protocol image module (APIM) software.

Electrical

2026005 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall replaces Transport Canada recall no. 2025-554. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

Seats and restraints

2025585 24 Oct 2025

Issue: On certain vehicles, the pivot bolts in the height adjuster assembly for the front seats may not have been manufactured properly. As a result, the bolt(s) could loosen and detach. If this happens, the seat(s) could move in a crash. Safety Risk: A seat that moves in a crash could increase the risk of injury. Corrective Action: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the height-adjust link(s) and pivot bolts.

12 more on the model-year record, cardog.app/tools/recalls/ford/bronco/2023

Listed for the model year, not checked against your VIN. Ford confirms which apply.
Check your VIN with Ford Canada or call a Ford dealer with your VIN.
www.ford.ca/support/recalls/

United States: 18 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$54,770^[5], \$108 under the median of \$54,878^[4].



Lowest ask	\$42,995
Middle half	\$50,116 – \$56,984
Median ask	\$54,878
This car	\$54,770

Same configuration · 38 live listings · as of 28 Oct 2026

OTHER 2023 FORD BRONCO LISTINGS ^[5]

Joliette, QC · 89,495 km	\$44,995
Mississauga, ON · 44,898 km	\$53,888
Mississauga, ON · 74,987 km	\$52,990
Mississauga, ON · 44,000 km	\$51,700
Mississauga, ON · 49,528 km	\$46,994



Halifax, NS · 47,939 km

\$26,689

§4 EVENTS

2023	Model year 2023 ^[1] Assembly plant Wayne, Michigan, United States
13 Feb 2023	Transport Canada recall 2023057 ^[2] Issued for the model year · Powertrain
21 Apr 2023	Transport Canada recall 2023243 ^[2] Issued for the model year · Wheels
19 May 2023	Transport Canada recall 2023294 ^[2] Issued for the model year · Seats and restraints
29 May 2023	Transport Canada recall 2023308 ^[2] Issued for the model year · Label
23 Feb 2024	Transport Canada recall 2024123 ^[2] Issued for the model year · Structure
11 Mar 2024	Transport Canada recall 2024157 ^[2] Issued for the model year · Structure
26 Apr 2024	Transport Canada recall 2024248 ^[2] Issued for the model year · Structure
17 Jan 2025	Transport Canada recall 2025020 ^[2] Issued for the model year · Suspension
24 Apr 2025	Transport Canada recall 2025223 ^[2] Issued for the model year · Visual system
9 May 2025	Transport Canada recall 2025260 ^[2] Issued for the model year · Visual system
9 May 2025	Transport Canada recall 2025253 ^[2] Issued for the model year · Structure
10 Oct 2025	Transport Canada recall 2025554 ^[2] Issued for the model year · Electrical
24 Oct 2025	Transport Canada recall 2025585 ^[2] Issued for the model year · Seats and restraints
9 Jan 2026	Transport Canada recall 2026005 ^[2] Issued for the model year · Electrical
3 Mar 2026	Transport Canada recall 2026093 ^[2] Issued for the model year · Visual system
15 Apr 2026	Transport Canada recall 2026188 ^[2] Issued for the model year · Powertrain



24 Jun 2026	Transport Canada recall 2026310 ^[2] Issued for the model year · Accessories
20 Jul 2026	Transport Canada recall 2026356 ^[2] Issued for the model year · Electrical
14 Sep 2026	Window sticker collected ^[6] Issued by FORD
26 Oct 2026	Listed for sale, Toronto, ON ^[5] Midtown Honda · asking \$54,770
27 Oct 2026	Listing last updated ^[5] asking \$54,770

§5 DOCUMENTS ^[6]

Window sticker	PDF, issued by FORD, collected 14 Sep 2026 VIN not read from the file
----------------	--

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 38 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | [6] Window sticker, issued by FORD, collected 14 Sep 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

