Register entry, as of 29 October 2026 Listed for sale Record ID 781499884785

2018 Ford Expedition XL

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FM	JU1GT	3	J	E	A31077
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company	Expedition · 3.5 L	Verified	2018	Jefferson County	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Expedition	Drive	4WD
Trim	XL	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Jefferson County, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/expedition/2018

11 recalls listed by Transport Canada for this model year

Powertrain

2026311 24 Jun 2026

Issue: On certain vehicles, a problem in the transmission could cause the parking pawl to become damaged. As a result, when the transmission is shifted to Park, the vehicle could move if the parking brake is not applied. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Ford recommends that you should always use the parking brake when you park until the recall repairs are completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module (PCM) software. The dealer will also inspect and, if necessary, replace any damaged transmission components.

Other

2026279 9 Jun 2026

Issue: On certain vehicles, the chrome plating on the center console could bubble and peel. If this happens, sharp edges can be created. Safety Risk: Exposed sharp edges can increase the risk of injury. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the center console.

Seats and restraints

2026257 27 May 2026

Issue: On certain vehicles, there could be a problem with the driver and/or front passenger seatbelt pretensioner(s). As a result, the airbag warning light could turn on, and the seatbelt pretensioners could deploy without a crash. Note: This recall replaces Transport Canada recall nos. 2024-084 and 2025-164. Vehicles that were repaired under those recalls also require this inspection or repair. Safety Risk: Seat belt pretensioners that don't work properly could create an increased risk of injury. Additionally, seat belt pretensioners that deploy without a crash could startle the driver and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the driver and front passenger seatbelt retractors.

Brakes

2025198 11 Apr 2025

Issue: On certain vehicles, brake fluid could leak from the brake master cylinder into the brake booster. If this happens, there could be reduced braking. Note: This problem may cause a warning chime to sound and a red brake warning indicator to display in the instrument cluster. This recall only affects certain vehicles equipped with a 3.5 L Ecoboost engine. This is an expansion of recall 22S11 (Transport Canada recall no. 2022-115). Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the brake master cylinder. The dealer will also inspect and, if necessary, replace the brake booster.

Seats and restraints

2025164 28 Mar 2025

This recall was replaced by Transport Canada recall no. 2026-257. Issue: On certain vehicles, there could be a problem with the driver and/or front passenger seatbelt pretensioner(s). As a result, the airbag warning light could turn on, and the seatbelt pretensioners could deploy without a crash. Note: This recall is an expansion Transport Canada recall no. 2024-084. Certain vehicles repaired under that recall also require this repair. Safety Risk: Seat belt pretensioners that don't work properly could create an increased risk of injury. Additionally, seat belt pretensioners that deploy without a crash could startle the driver and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver and front passenger seatbelt retractors.

Seats and restraints

2024084 11 Feb 2024

This recall was replaced by Transport Canada recall no. 2026-257. Issue: On certain vehicles, there could be a problem with the driver and/or front passenger seatbelt pretensioner(s). As a result, the airbag warning light could turn on, and the seatbelt pretensioners could deploy without a crash. Safety Risk: Seat belt pretensioners that do not work properly could create an increased risk of injury. Additionally, seat belt pretensioners that deploy without a crash could startle the driver and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver and front passenger seatbelt retractors. Additionally, the dealer will install a heating, ventilation and air conditioning (HVAC) drain tube if necessary.

5 more on the model-year record, cardog.app/tools/recalls/ford/expedition/2018

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 14 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

Median ask $29,995[4] for same model year.

Lowest ask	$14,999
Middle half	$22,497 – $33,997
Median ask	$29,995
This car	US$37,999

Same model year · 3 live listings · as of 29 Oct 2026

OTHER 2018 FORD EXPEDITION LISTINGS [5]

Regina, SK · 187,630 km	$29,995
Edmonton, AB · 219,079 km	$29,500
Calgary, AB · 74,556 km	$39,999
Kitchener, ON · 214,458 km	$14,999

§4 EVENTS

2018	Model year 2018[1] Assembly plant Jefferson County, Kentucky, United States
30 Nov 2017	Transport Canada recall 2017592[2] Issued for the model year · Seats and restraints
17 Jan 2018	Transport Canada recall 2018034[2] Issued for the model year · Structure
13 Jun 2018	Transport Canada recall 2018310[2] Issued for the model year · Fuel system
15 Nov 2018	Transport Canada recall 2018629[2] Issued for the model year · Structure
9 Jun 2023	Transport Canada recall 2023341[2] Issued for the model year · Seats and restraints
11 Feb 2024	Transport Canada recall 2024084[2] Issued for the model year · Seats and restraints
28 Mar 2025	Transport Canada recall 2025164[2] Issued for the model year · Seats and restraints
11 Apr 2025	Transport Canada recall 2025198[2] Issued for the model year · Brakes
27 May 2026	Transport Canada recall 2026257[2] Issued for the model year · Seats and restraints
9 Jun 2026	Transport Canada recall 2026279[2] Issued for the model year · Other
24 Jun 2026	Transport Canada recall 2026311[2] Issued for the model year · Powertrain
22 Oct 2026	Listed for sale, Red Deer, AB[5] Red Deer Motors · asking US$37,999
29 Oct 2026	Listing last updated[5] asking US$37,999

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 3 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.