

2023 Ford Expedition Timberline

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Flexible Fuel Vehicle (FFV)

VEHICLE IDENTIFICATION NUMBER [1]

1FMJU1RG5PEA41084

WMI 1-3

Ford Motor Company

DESCRIPTOR 4-8

Expedition · 3.5 L

CHECK 9

Verified

YEAR 10

2023

PLANT 11

Jefferson County

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Flexible Fuel Vehicle (FFV)
Model	Expedition	Drive	4WD
Trim	Timberline	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Jefferson County, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/expedition/2023

6 recalls listed by Transport Canada for this model year

Other 2026279 9 Jun 2026

Issue: On certain vehicles, the chrome plating on the center console could bubble and peel. If this happens, sharp edges can be created. Safety Risk: Exposed sharp edges can increase the risk of injury. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the center console.

Visual system 2026161 1 Apr 2026

Issue: On certain trucks, the windshield wiper arms may not have been manufactured correctly. As a result, the wiper arm(s) could break or become detached and may not wipe the windshield properly. Safety Risk: Windshield wipers that do not work properly could affect a driver's visibility. Windshield wiper(s) that detach from the vehicle could create a road hazard for others. Both issues could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

Lights and instruments 2026079 20 Feb 2026

Issue: On certain vehicles, a software problem with the integrated trailer module (ITRM) may cause the trailer lights not to work when towing. This problem could also cause the trailer brakes not to work on certain vehicles. Note: This problem would cause a "Trailer brake module fault" message to be displayed and turn signal telltale to flash rapidly. This recall also affects certain Super Duty incomplete vehicles. Safety Risk: Trailer lights that don't work could make the vehicle less visible and cause following drivers not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a loss of trailer brakes could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the ITRM software. Alternatively, you may schedule an appointment to have the update performed at a Ford dealership.



Visual system

2025260 9 May 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display or to freeze when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the SYNC software. Alternatively, you may schedule an appointment to have the update performed at a Ford dealership.

Brakes

2025259 9 May 2025

Issue: On certain vehicles, the front brake lines may have been bent during engine installation. As a result, the brake lines could become damaged by contact with the engine air cleaner outlet pipe. This could lead to a brake fluid leak and cause reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the front brake lines and/or the air cleaner outlet pipe.

Seats and restraints

2023341 9 Jun 2023

Issue: On certain vehicles, the owner's manual doesn't include instructions for how to remove or adjust the head restraint for the centre seating positions. Canadian regulations require this information be included in the owner's manual. Safety Risk: Missing instructions for how to remove or adjust head restraints could increase the risk of injury in a crash. Corrective Actions: Ford will notify owners by mail and provide you with an owner's manual insert with instructions for how to remove and adjust the centre seat head restraints.

Listed for the model year, not checked against your VIN. Ford confirms which apply.

Check your VIN with Ford Canada or call a Ford dealer with your VIN.

www.ford.ca/support/recalls/

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$59,995^[5], \$498 over the median of \$59,497^[4].



Lowest ask	\$50,888
Middle half	\$56,971 – \$63,745
Median ask	\$59,497
This car	\$59,995

Same model year · 4 live listings · as of 27 Oct 2026

OTHER 2023 FORD EXPEDITION LISTINGS ^[5]

Toronto, ON · 102,200 km	\$50,888
Vernon, BC · 22,897 km	\$74,995
Espanola, ON · 97,726 km	\$54,474
St-Eustache, QC · 90,606 km	\$54,987
North Bay, ON · 97,726 km	\$54,474
Toronto, ON · 102,200 km	\$50,888

§4 EVENTS

2023

Model year 2023^[1]

Assembly plant Jefferson County, Kentucky, United States



9 Jun 2023	Transport Canada recall 2023341 ^[2] Issued for the model year · Seats and restraints
9 May 2025	Transport Canada recall 2025260 ^[2] Issued for the model year · Visual system
9 May 2025	Transport Canada recall 2025259 ^[2] Issued for the model year · Brakes
20 Feb 2026	Transport Canada recall 2026079 ^[2] Issued for the model year · Lights and instruments
1 Apr 2026	Transport Canada recall 2026161 ^[2] Issued for the model year · Visual system
9 Jun 2026	Transport Canada recall 2026279 ^[2] Issued for the model year · Other
26 Oct 2026	Listed for sale, Miramichi, NB ^[5] Towne Ford Sales and Service Limited · asking \$59,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

