

2019 Ford Expedition Limited

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**1FMJU2AT4KEA54044**

WMI 1-3

Ford Motor Company

DESCRIPTOR 4-8

Expedition · 3.5 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

Jefferson County

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2019	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Expedition	Drive	4WD
Trim	Limited	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Jefferson County, Kentucky, United States

§2 OBLIGATIONS ^[2]cardog.app/tools/recalls/ford/expedition/2019

9 recalls listed by Transport Canada for this model year

Powertrain 2026311 24 Jun 2026

Issue: On certain vehicles, a problem in the transmission could cause the parking pawl to become damaged. As a result, when the transmission is shifted to Park, the vehicle could move if the parking brake is not applied. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Ford recommends that you should always use the parking brake when you park until the recall repairs are completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module (PCM) software. The dealer will also inspect and, if necessary, replace any damaged transmission components.

Other 2026279 9 Jun 2026

Issue: On certain vehicles, the chrome plating on the center console could bubble and peel. If this happens, sharp edges can be created. Safety Risk: Exposed sharp edges can increase the risk of injury. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the center console.

Seats and restraints 2026257 27 May 2026

Issue: On certain vehicles, there could be a problem with the driver and/or front passenger seatbelt pretensioner(s). As a result, the airbag warning light could turn on, and the seatbelt pretensioners could deploy without a crash. Note: This recall replaces Transport Canada recall nos. 2024-084 and 2025-164. Vehicles that were repaired under those recalls also require this inspection or repair. Safety Risk: Seat belt pretensioners that don't work properly could create an increased risk of injury. Additionally, seat belt pretensioners that deploy without a crash could startle the driver and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the driver and front passenger seatbelt retractors.



Powertrain

2025707 18 Dec 2025

Issue: On certain vehicles, the recall repairs completed by a Ford dealer during recall 20S21 (Transport Canada recall no. 2020-203) may not have been done correctly. As a result, a second repair is required. On certain vehicles, there is a problem with the warnings to tell a driver that the transmission is not in Park. When the ignition is turned off, with the driver door closed, the message and chime to warn that the transmission is not in Park are only active for 3 seconds. Instead, the chime should sound for 10 seconds and the message should display for 30 minutes. As a result, a driver could exit the vehicle without realizing that the transmission is not in Park. If this happens, the vehicle could roll away. Safety Risk: Unintended vehicle movement could increase the risk of injury and/or a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to reprogram the instrument panel cluster.

Seats and restraints

2025164 28 Mar 2025

This recall was replaced by Transport Canada recall no. 2026-257. Issue: On certain vehicles, there could be a problem with the driver and/or front passenger seatbelt pretensioner(s). As a result, the airbag warning light could turn on, and the seatbelt pretensioners could deploy without a crash. Note: This recall is an expansion Transport Canada recall no. 2024-084. Certain vehicles repaired under that recall also require this repair. Safety Risk: Seat belt pretensioners that don't work properly could create an increased risk of injury. Additionally, seat belt pretensioners that deploy without a crash could startle the driver and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver and front passenger seatbelt retractors.

Seats and restraints

2024084 11 Feb 2024

This recall was replaced by Transport Canada recall no. 2026-257. Issue: On certain vehicles, there could be a problem with the driver and/or front passenger seatbelt pretensioner(s). As a result, the airbag warning light could turn on, and the seatbelt pretensioners could deploy without a crash. Safety Risk: Seat belt pretensioners that do not work properly could create an increased risk of injury. Additionally, seat belt pretensioners that deploy without a crash could startle the driver and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver and front passenger seatbelt retractors. Additionally, the dealer will install a heating, ventilation and air conditioning (HVAC) drain tube if necessary.

3 more on the model-year record, cardog.app/tools/recalls/ford/expedition/2019

Listed for the model year, not checked against your VIN. Ford confirms which apply.

Check your VIN with Ford Canada or call a Ford dealer with your VIN.

www.ford.ca/support/recalls/

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$42,500^[5], \$9,502 over the median of \$32,998^[4].



Lowest ask	\$16,995
Middle half	\$31,187 – \$35,937
Median ask	\$32,998
This car	\$42,500

Same model year · 15 live listings · as of 28 Oct 2026

OTHER 2019 FORD EXPEDITION LISTINGS ^[5]

Lethbridge, AB · 209,588 km	\$30,990
Edson, AB · 216,072 km	\$22,999
Bolton, ON · 123,813 km	\$32,998
Ottawa, ON · 147,915 km	\$35,937
Edson, AB · 162,766 km	\$35,704
Chatham, ON · 103,693 km	\$31,384



§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Jefferson County, Kentucky, United States
29 Aug 2019	Transport Canada recall 2019437 ^[2] Issued for the model year · Seats and restraints
11 May 2020	Transport Canada recall 2020203 ^[2] Issued for the model year · Powertrain
9 Jun 2023	Transport Canada recall 2023341 ^[2] Issued for the model year · Seats and restraints
11 Feb 2024	Transport Canada recall 2024084 ^[2] Issued for the model year · Seats and restraints
28 Mar 2025	Transport Canada recall 2025164 ^[2] Issued for the model year · Seats and restraints
18 Dec 2025	Transport Canada recall 2025707 ^[2] Issued for the model year · Powertrain
27 May 2026	Transport Canada recall 2026257 ^[2] Issued for the model year · Seats and restraints
9 Jun 2026	Transport Canada recall 2026279 ^[2] Issued for the model year · Other
24 Jun 2026	Transport Canada recall 2026311 ^[2] Issued for the model year · Powertrain
26 Oct 2026	Listed for sale, North Vancouver, BC ^[5] Cam Clark Ford Lincoln Vancouver · asking \$42,500
28 Oct 2026	Listing last updated ^[5] asking \$42,500

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 15 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

