

Register entry, as of 28 October 2026

Listed for sale

Record ID 117daf405edb

# 2022 Ford Ranger SuperCrew

2.3 L, 4 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**1FT ER4FH 1 N L D32678**

WMI 1-3

Ford Motor Company

DESCRIPTOR 4-8

Ranger · 2.3 L

CHECK 9

Verified

YEAR 10

2022

PLANT 11

Wayne

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |           |        |                                |
|------------|-----------|--------|--------------------------------|
| Model year | 2022      | Engine | 2.3 L, 4 cylinders             |
| Make       | Ford      | Fuel   | Gasoline                       |
| Model      | Ranger    | Drive  | 4WD                            |
| Trim       | SuperCrew | Maker  | FORD MOTOR COMPANY             |
| Body       | Pickup    | Plant  | Wayne, Michigan, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/ford/ranger/2022](https://cardog.app/tools/recalls/ford/ranger/2022)

## 6 recalls listed by Transport Canada for this model year

### Electrical 2026005 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in.

Note: This recall replaces Transport Canada recall no. 2025-554. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

### Electrical 2025554 10 Oct 2025

This recall was replaced by Transport Canada recall no. 2026-005. Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater.

### Visual system 2025360 27 Jun 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the SYNC software.



## Label

2023308 29 May 2023

Issue: On certain vehicles, the tire and loading information label lists the wrong maximum weight of occupants and cargo. Specifically, for Bronco and Super Duty models, the cargo capacity (payload) may have been calculated incorrectly. For the Ranger models, the weight of vehicle options may have been entered incorrectly. As a result, the vehicle could be overloaded. Canadian regulations require companies to print the maximum weight of occupants and cargo on the tire and loading information label. Safety Risk: Incorrect information about the vehicle's weight capacity could lead to overloading and increase the risk of a crash. Corrective Actions: Ford will mail a new tire and loading information label to each owner. If you would like help to install it, you can contact a Ford dealer to have it installed free of charge.

## Fuel system

2022522 16 Sep 2022

Issue: On certain vehicles equipped with a 2.3 L engine, the fuel line connections between the fuel pump and fuel rail may not have been tightened properly. As a result, fuel could leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace the fuel line assembly.

## Structure

2022335 24 Jun 2022

Issue: On certain vehicles, the windshield may not be properly attached. As a result, the glass can become loose and could separate from the vehicle in a crash. Safety Risk: A windshield that detaches in a crash could create an increased risk of injury. Corrective Action: Ford will notify owners by mail and instruct you to take your vehicle to a dealership to remove and reinstall the windshield. The dealer will also recalibrate the front camera, if necessary.

Listed for the model year, not checked against your VIN. Ford confirms which apply.

Check your VIN with Ford Canada or call a Ford dealer with your VIN.

[www.ford.ca/support/recalls/](http://www.ford.ca/support/recalls/)

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$38,888<sup>[5]</sup>, \$6,198 over the median of \$32,690<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$27,977            |
| Middle half | \$30,272 – \$38,194 |
| Median ask  | \$32,690            |
| This car    | \$38,888            |

Same configuration · 11 live listings · as of 28 Oct 2026

## OTHER 2022 FORD RANGER LISTINGS [5]

|                                  |          |
|----------------------------------|----------|
| Pitt Meadows, BC · 90,278 km     | \$30,600 |
| Pembroke, ON · 80,134 km         | \$29,944 |
| Ste-Justine, QC · 79,388 km      | \$38,390 |
| Lower Sackville, NS · 140,633 km | \$30,995 |
| Winnipeg, MB · 117,564 km        | \$32,690 |
| Pitt Meadows, BC · 90,278 km     | \$30,600 |

## §4 EVENTS

2022

Model year 2022<sup>[1]</sup>

Assembly plant Wayne, Michigan, United States



|             |                                                                                              |
|-------------|----------------------------------------------------------------------------------------------|
| 24 Jun 2022 | Transport Canada recall 2022335 <sup>[2]</sup><br>Issued for the model year · Structure      |
| 16 Sep 2022 | Transport Canada recall 2022522 <sup>[2]</sup><br>Issued for the model year · Fuel system    |
| 29 May 2023 | Transport Canada recall 2023308 <sup>[2]</sup><br>Issued for the model year · Label          |
| 27 Jun 2025 | Transport Canada recall 2025360 <sup>[2]</sup><br>Issued for the model year · Visual system  |
| 10 Oct 2025 | Transport Canada recall 2025554 <sup>[2]</sup><br>Issued for the model year · Electrical     |
| 9 Jan 2026  | Transport Canada recall 2026005 <sup>[2]</sup><br>Issued for the model year · Electrical     |
| 26 Oct 2026 | Listed for sale, Ottawa, ON <sup>[5]</sup><br>Myers Kanata Chev Buick GMC. · asking \$38,888 |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$38,888                                       |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 11 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

