Register entry, as of 28 October 2026 Listed for sale Record ID 634cf3b5450f

# 2026 Ford Ranger Lariat

2.7 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1FT | ER4KP | 6 | T | L | E35878 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ford Motor Company | Ranger · 2.7 L | Verified | 2026 | Wayne | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2026 | Engine | 2.7 L, 6 cylinders |
| Make | Ford | Fuel | Gasoline |
| Model | Ranger | Drive | 4WD |
| Trim | Lariat | Maker | FORD MOTOR COMPANY |
| Body | Pickup | Plant | Wayne, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/ranger/2026

**6** recalls listed by Transport Canada for this model year

### Visual system

2026450 22 Sep 2026

Issue: On certain vehicles, the rearview camera image may not display when the transmission is shifted into reverse gear. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects vehicles equipped with a 10.1-inch display screen Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

### Engine

2026411 26 Aug 2026

Issue: On certain vehicles, the engine pistons may not have been manufactured properly. As a result, the pistons may crack and cause the engine to fail. If this happens, there could be a sudden loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 1.5 L or 2.3 L engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the engine.

### Engine

2026258 27 May 2026

Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, the engine could fail and cause a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 2.3 L engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine.

### Seats and restraints

2026211 28 Apr 2026

Issue: On certain vehicles, the pivot bolts in the height adjuster assembly for the front seats may not have been manufactured properly. As a result, the bolt(s) could loosen and detach. If this happens, the seat(s) could move in a crash. Safety Risk: A seat that moves in a crash could increase the risk of injury. Corrective Action: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the height-adjust link(s) and pivot bolts.

### Electrical

2026190 15 Apr 2026

Issue: On certain vehicles, the wiring for the sun visors may not have been manufactured and/or installed properly. As a result, the wiring could become damaged and cause a short circuit or electrical arcing (sparks). Safety Risk: A short circuit or electrical arcing can create the risk of a fire or injury. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the sun visor wiring harness. The dealer will also update the body control module software.

### Lights and instruments

2026079 20 Feb 2026

Issue: On certain vehicles, a software problem with the integrated trailer module (ITRM) may cause the trailer lights not to work when towing. This problem could also cause the trailer brakes not to work on certain vehicles. Note: This problem would cause a "Trailer brake module fault" message to be displayed and turn signal telltale to flash rapidly. This recall also affects certain Super Duty incomplete vehicles. Safety Risk: Trailer lights that don't work could make the vehicle less visible and cause following drivers not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a loss of trailer brakes could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the ITRM software. Alternatively, you may schedule an appointment to have the update performed at a Ford dealership.

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $64,775[5], $829 over the median of $63,946[4].

| | |
|---|---|
| Lowest ask | $52,990 |
| Middle half | $61,971 – $65,459 |
| Median ask | $63,946 |
| This car | $64,775 |

Same configuration · 124 live listings · as of 28 Oct 2026

### OTHER 2026 FORD RANGER LISTINGS [5]

| | |
|---|---|
| Surrey, BC · 0 km | $66,275 |
| Kingston, ON · 8 km | $49,086 |
| New Richmond, QC · 15 km | $55,165 |
| Blainville, QC · 38 km | $49,540 |
| Laval, QC · 10 km | $54,274 |
| Lethbridge, AB · 0 km | $84,723 |

## §4 EVENTS

| | |
|---|---|
| 2026 | Model year 2026[1]<br>Assembly plant Wayne, Michigan, United States |
| 20 Feb 2026 | Transport Canada recall 2026079[2]<br>Issued for the model year · Lights and instruments |
| 15 Apr 2026 | Transport Canada recall 2026190[2]<br>Issued for the model year · Electrical |
| 28 Apr 2026 | Transport Canada recall 2026211[2]<br>Issued for the model year · Seats and restraints |
| 27 May 2026 | Transport Canada recall 2026258[2]<br>Issued for the model year · Engine |
| 26 Aug 2026 | Transport Canada recall 2026411[2]<br>Issued for the model year · Engine |
| 22 Sep 2026 | Transport Canada recall 2026450[2]<br>Issued for the model year · Visual system |
| 26 Oct 2026 | Listed for sale, Sussex, NB[5]<br>Downey Ford Sales Ltd. · asking $64,775 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $64,775 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 124 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.