Register entry, as of 26 October 2026 Listed for sale Record ID 3c4c52e89524

# 2016 Ford F-150

3.5 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1FT | FW1EG | 5 | G | K | D40182 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Ford Motor Company | F-150 · 3.5 L | Verified | 2016 | Kansas City | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2016 | Engine | 3.5 L, 6 cylinders |
| Make | Ford | Fuel | Gasoline |
| Model | F-150 | Drive | 4WD |
| Trim | Not in the decode | Maker | FORD MOTOR COMPANY |
| Body | Pickup | Plant | Kansas City, Missouri, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/f-150/2016

**15** recalls listed by Transport Canada for this model year

### Powertrain

2026189 15 Apr 2026

Issue: On certain trucks, a software problem could cause the transmission to downshift suddenly to second gear. If this happens, there could be a loss of control. Note: This recall only affects trucks equipped with a 6-speed transmission. Safety Risk: A loss of control could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your truck to a dealership to update the powertrain control module software.

### Visual system

2024779 20 Dec 2024

Issue: On certain trucks, the windshield wiper linkage could corrode and seize. If this happens, the windshield wipers may not work. Safety Risk: Windshield wipers that don't work could reduce visibility and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your truck to a dealership to replace the windshield wiper linkage.

### Brakes

2022115 14 Mar 2022

Issue: On certain trucks equipped with a 3.5 L Ecoboost engine, brake fluid could leak from the brake master cylinder into the brake booster. This can cause reduced front brake performance, and the driver may experience increased brake pedal travel and increased pedal effort. Full braking function remains in the rear wheel circuit. Note: Depending on the amount of brake fluid loss, the driver may hear a warning chime and see a red brake warning indicator in the instrument cluster. This is an expansion of Ford recall 20S31 (Transport Canada Recall No. 2020-252). Safety Risk: Reduced front brake performance can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your truck to a dealer to replace the brake master cylinder. The dealer will also replace the brake booster if the brake master cylinder is leaking.

### Brakes

2020252 8 Jun 2020

Issue: On certain trucks, brake fluid could leak from the brake master cylinder front wheel circuit into the brake booster. If this happens, the driver may experience increased brake pedal travel and increased pedal effort. This can cause reduced front brake performance. Full braking function remains in the rear wheel circuit. Note: Depending on the amount of brake fluid loss, the driver may hear a warning chime and see a red brake warning indicator in the instrument cluster. Safety Risk: Reduced front brake performance can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your truck to a Ford or Lincoln dealer to replace the brake master cylinder.

### Electrical

2020069 21 Feb 2020

Issue: On certain trucks with a 3.5-L engine, there could be a problem with the engine block heater cable. The wrong cable may have been installed when your vehicle was repaired under a previous recall. The cable that was installed may not have enough heat protection and could be damaged by high engine temperatures. When plugged in, this could cause a short circuit to occur, resulting in overheated or melted wiring. It could also cause the block heater not to work, and/or it could cause a household circuit breaker to trip. For details of the previous recall, please see Transport Canada recall no. 2019-174 (Ford no. 19S11/19G01). Safety Risk: Overheated or melted wiring could create the risk of a fire. Corrective Actions: Do not use your block heater until the recall inspection and repairs are completed. Ford will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the block heater and cable. Depending on the results of the inspection, the heater element and/or block heater cable will be replaced, as necessary. If the replacement parts are not available, the dealer will disable the engine block heater. Ford will send you another notice when the replacement parts are available, and will ask you to take your vehicle to a dealer to have them installed.

### Electrical

2020023 23 Jan 2020

Issue: On certain trucks, the electric tailgate latch could malfunction. This may cause the tailgate to unlatch on its own. If the tailgate opens while driving, cargo that is not secured could fall out of the truck bed and onto the road. Safety Risk: Cargo that falls from the truck bed could create a road hazard for others. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a Ford or Lincoln dealer to modify the tailgate/frame wiring harnesses and will install a new tailgate handle release switch.

9 more on the model-year record, cardog.app/tools/recalls/ford/f-150/2016

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 14 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $26,500[5], $3,501 over the median of $22,999[4].

| | |
|---|---|
| Lowest ask | $13,495 |
| Middle half | $17,988 – $24,911 |
| Median ask | $22,999 |
| This car | $26,500 |

Same configuration · 17 live listings · as of 26 Oct 2026

### OTHER 2016 FORD F-150 LISTINGS [5]

| | |
|---|---|
| Oakville, ON · 386,365 km | $10,998 |
| Stettler, AB · 344,953 km | $14,995 |
| Lethbridge, AB · 173,636 km | $28,608 |
| Winnipeg, MB · 167,240 km | $33,000 |
| Mirabel, QC · 101,155 km | $21,900 |
| Lethbridge, AB · 173,636 km | $28,608 |

## §4 EVENTS

| | |
|---|---|
| 2016 | Model year 2016[1]<br>Assembly plant Kansas City, Missouri, United States |
| 22 Feb 2016 | Transport Canada recall 2016089[2]<br>Issued for the model year · Accessories |
| 28 Jun 2016 | Transport Canada recall 2016329[2]<br>Issued for the model year · Seats and restraints |
| 30 Aug 2017 | Transport Canada recall 2017413[2]<br>Issued for the model year · Seats and restraints |
| 18 Oct 2017 | Transport Canada recall 2017502[2]<br>Issued for the model year · Structure |
| 30 Nov 2017 | Transport Canada recall 2017593[2]<br>Issued for the model year · Seats and restraints |
| 4 Sep 2018 | Transport Canada recall 2018470[2]<br>Issued for the model year · Seats and restraints |
| 20 Dec 2018 | Transport Canada recall 2018718[2]<br>Issued for the model year · Electrical |
| 10 Apr 2019 | Transport Canada recall 2019174[2]<br>Issued for the model year · Electrical |
| 21 Aug 2019 | Transport Canada recall 2019420[2]<br>Issued for the model year · Other |
| 23 Jan 2020 | Transport Canada recall 2020023[2]<br>Issued for the model year · Electrical |
| 21 Feb 2020 | Transport Canada recall 2020069[2]<br>Issued for the model year · Electrical |
| 8 Jun 2020 | Transport Canada recall 2020252[2]<br>Issued for the model year · Brakes |
| 14 Mar 2022 | Transport Canada recall 2022115[2]<br>Issued for the model year · Brakes |
| 20 Dec 2024 | Transport Canada recall 2024779[2]<br>Issued for the model year · Visual system |
| 15 Apr 2026 | Transport Canada recall 2026189[2]<br>Issued for the model year · Powertrain |
| 25 Oct 2026 | Listed for sale, St. Catharines, ON[5]<br>CMH AUTO SUPERSTORE · asking $26,500 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $26,500 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 17 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.