Register entry, as of 28 October 2026 Listed for sale Record ID 998d7e1bd1bb

2011 Ford F-150

3.5 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FT	FW1ET	9	B	K	E11809
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Ford Motor Company	F-150 · 3.5 L	Verified	2011	Kansas City	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	F-150	Drive	4WD
Trim	Not in the decode	Maker	FORD MOTOR COMPANY
Body	Pickup	Plant	Kansas City, Missouri, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/f-150/2011

6 recalls listed by Transport Canada for this model year

Powertrain — 2019065 — 12 Feb 2019

Issue: On some trucks, a sensor problem may cause the transmission to suddenly downshift to first gear. This could cause the rear wheels to suddenly slow and potentially create a loss of stability. Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the Powertrain Control Module reprogrammed.

Brakes — 2017246 — 8 May 2017

On certain vehicles equipped with 3.5L V6 GTDI EcoBoost engines, the electric vacuum pump (EVP) may fail due to moisture entry through the engine vacuum harness. Failure of the EVP may result in reduced brake assist immediately after first start up, and depending on the driver's reaction, may result in extended stopping distance which may increase the potential for a low-speed collision causing injury and/or damage to property. Correction: Dealers will replace the EVP and vacuum harness.

Powertrain — 2016183 — 26 Apr 2016

Certain vehicles equipped with a 6-speed automatic transmission may experience an intermittent loss of the Transmission Output-shaft Speed Sensor (OSS) signal to the Power Control Module. This could potentially cause an unintended downshift into first gear, which depending on vehicle speed at the time of the downshift, may cause the rear tires to slide or lock up until the vehicle slows. This may result in a loss of vehicle control without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will reprogram the Powertrain Control Module with updated software.

Powertrain

2012149 1 May 2012

Certain vehicles may have been equipped with an incorrectly manufactured Transmission Range Sensor. In some instances, when the shift lever is placed in the "R" position, signal may not be provided to the electronic transmission range indicator "PRNDL" for "R" illumination and/or for backup lamp activation. Should the backup lamps fail to illuminate, the driver's intentions to reverse may not be conveyed clearly to other motorists and/or pedestrians, which could result in property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the Transmission Range Sensor.

Powertrain

2011426 7 Dec 2011

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 102 - Transmission Control Functions. The Brake Transmission Shift Interlock (BTSI) switch may have been incorrectly manufactured and could fail. This would allow the transmission gear shift lever to be moved out of the PARK position without depressing the brake pedal. Depending which gear the driver selects, the vehicle could begin to move forward or backward immediately. This movement could result in property damage, or cause the vehicle to strike a bystander, potentially resulting in personal injury. Correction: Dealers will inspect and, if necessary, replace the BTSI switch.

Electrical

2010463 23 Dec 2010

On certain vehicles, the Body Control Module (BCM) may develop an internal short. If an electrical short occurs, an overheating condition may result in a vehicle fire causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the Body Control Module.

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $11,499[5], $248 under the median of $11,747[4].

Lowest ask	$5,800
Middle half	$9,999 – $12,999
Median ask	$11,747
This car	$11,499

Same model year · 30 live listings · as of 28 Oct 2026

OTHER 2011 FORD F-150 LISTINGS [5]

Laval, QC · 223,000 km	$6,799
Brooks, AB · 146,525 km	$18,099
Hamilton, ON · 114,797 km	$10,500
Toronto, ON · 170,000 km	$12,999
Beloeil, QC · 239,386 km	$11,995
Duncan, BC · 364,222 km	$5,999

§4 EVENTS

2011 Model year 2011[1]
Assembly plant Kansas City, Missouri, United States

23 Dec 2010	Transport Canada recall 2010463[2] Issued for the model year · Electrical
7 Dec 2011	Transport Canada recall 2011426[2] Issued for the model year · Powertrain
1 May 2012	Transport Canada recall 2012149[2] Issued for the model year · Powertrain
26 Apr 2016	Transport Canada recall 2016183[2] Issued for the model year · Powertrain
8 May 2017	Transport Canada recall 2017246[2] Issued for the model year · Brakes
12 Feb 2019	Transport Canada recall 2019065[2] Issued for the model year · Powertrain
26 Oct 2026	Listed for sale, Laval, QC[5] autosdeal.ca · asking $11,499
27 Oct 2026	Listing last updated[5] asking $11,499

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 30 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.