

Register entry, as of 27 October 2026

Listed for sale

Record ID 50cb34c87755

# 2013 Chevrolet Sonic LS

1.8 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**1G1 JB5EH 4 D 4 225538**

WMI 1-3

Chevrolet · GENERAL MOT...

DESCRIPTOR 4-8

Sonic · 1.8 L

CHECK 9

Verified

YEAR 10

2013

PLANT 11

Orion

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |           |        |                                |
|------------|-----------|--------|--------------------------------|
| Model year | 2013      | Engine | 1.8 L, 4 cylinders             |
| Make       | Chevrolet | Fuel   | Gasoline                       |
| Model      | Sonic     | Drive  | Not in the decode              |
| Trim       | LS        | Maker  | GENERAL MOTORS LLC             |
| Body       | Sedan     | Plant  | Orion, Michigan, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/chevrolet/sonic/2013](https://cardog.app/tools/recalls/chevrolet/sonic/2013)

## 7 recalls listed by Transport Canada for this model year

### Airbag 2023412 27 Jul 2023

Issue: On certain vehicles, the driver-front airbag inflator could rupture when the airbag deploys in a crash. If this happens, the airbag may not properly inflate and fragments could be propelled toward vehicle occupants. Safety Risk: An airbag inflator that ruptures can create a risk of injury or death. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-front airbag module.

### Lights and instruments 2017051 3 Feb 2017

Certain vehicles may fail to comply with the requirements of Canada Motor Vehicle Safety Standard 108 - Lighting System and Retroreflective Devices. The headlamp high-beam lens is not marked with the bulb type, contrary to the requirements of the standard. Correction: An manufacturing change has been undertaken to prevent this non-compliance condition from continuing. No corrective recall action is required as the non-compliance condition is deemed to be non-safety related.

### Electrical 2016191 28 Apr 2016

Certain vehicles equipped with a "Bring Your Own Media" (BYOM) radio may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 114 - Theft Protection and Rollaway Protection. The radio software may fail to provide an audible warning/reminder chime that meets the requirements of the standard if the ignition key is left in the off position and the driver delays opening the driver's door for more than 10 minutes, or opens and closes the door several times. The loss of an audible warning when a key is left in the ignition may increase the risk of vehicle theft. Correction: Dealers will reprogram the radio with corrected operating software.



**Accessories**

2014274 3 Jul 2014

On certain vehicles, insulation on the engine block heater power cord may become damaged if the cord is handled during very cold days (temperatures below -25C). This could create an electrical shock hazard, which could result in personal injury. Correction: Dealers will replace the block heater cord.

**Lights and instruments**

2013356 16 Oct 2013

On certain vehicles, the brake lamps could flash intermittently without the brake pedal being depressed. This would convey a confusing message to following road users who, in turn, may not react in a timely manner when the driver does apply the brakes. As such, this could result in a crash causing property damage and/or personal injury. Correction: Dealers will reprogram the Body Control Module. Note: This recall supersedes 2013-176.

**Fuel system**

2013334 27 Sep 2013

On certain vehicles, a fuel tank support strap bracket may have been welded incorrectly and could separate. This could potentially result in damage to the fuel tank and fuel leakage. Fuel leakage, in the presence of an ignition source, could result in a fire causing injury and/or property damage. Correction: Dealers will inspect the bracket and replace if necessary.

1 more on the model-year record, [cardog.app/tools/recalls/chevrolet/sonic/2013](http://cardog.app/tools/recalls/chevrolet/sonic/2013)

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.  
Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.  
[www.chevrolet.ca/en/ownercenter/recalls](http://www.chevrolet.ca/en/ownercenter/recalls)

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE** <sup>[4]</sup>

This car asks \$3,950<sup>[5]</sup>, \$728 over the median of \$3,222<sup>[4]</sup>.



|             |                   |
|-------------|-------------------|
| Lowest ask  | \$2,450           |
| Middle half | \$2,484 – \$4,462 |
| Median ask  | \$3,222           |
| This car    | \$3,950           |

Same model year · 4 live listings · as of 27 Oct 2026

**OTHER 2013 CHEVROLET SONIC LISTINGS** <sup>[5]</sup>

|                               |         |
|-------------------------------|---------|
| Mississauga, ON · 134,527 km  | \$2,495 |
| Charlesbourg, QC · 179,631 km | \$2,450 |
| Mississauga, ON · 134,527 km  | \$2,495 |
| Toronto, ON · 144,270 km      | \$5,999 |

**§4 EVENTS**

|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 2013        | Model year 2013 <sup>[1]</sup><br>Assembly plant Orion, Michigan, United States          |
| 17 Sep 2012 | Transport Canada recall 2012304 <sup>[2]</sup><br>Issued for the model year · Electrical |



|             |                                                                                                      |
|-------------|------------------------------------------------------------------------------------------------------|
| 27 Sep 2013 | Transport Canada recall 2013334 <sup>[2]</sup><br>Issued for the model year · Fuel system            |
| 16 Oct 2013 | Transport Canada recall 2013356 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 3 Jul 2014  | Transport Canada recall 2014274 <sup>[2]</sup><br>Issued for the model year · Accessories            |
| 28 Apr 2016 | Transport Canada recall 2016191 <sup>[2]</sup><br>Issued for the model year · Electrical             |
| 3 Feb 2017  | Transport Canada recall 2017051 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 27 Jul 2023 | Transport Canada recall 2023412 <sup>[2]</sup><br>Issued for the model year · Airbag                 |
| 5 Sep 2026  | Listed for sale, Charlesbourg, QC <sup>[5]</sup><br>Automobiles Desjardins · asking \$3,950          |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$3,950                                                |

## §5 DOCUMENTS

Window sticker      This VIN reads as model year 1983 or 2013, before our coverage for this manufacturer.

## SOURCES

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                 |
| [3] NHTSA recall records (United States), listed for the model year |                                                                              |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

