Register entry, as of 28 October 2026 Listed for sale Record ID 2d65d701bac1

# 2014 Chevrolet Cruze 1LT

1.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1G1 | PC5SB | 3 | E | 7 | 411076 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Chevrolet · GENERAL MOT… | Cruze · 1.4 L | Verified | 2014 | Lordstown | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2014 | Engine | 1.4 L, 4 cylinders |
| Make | Chevrolet | Fuel | Gasoline |
| Model | Cruze | Drive | Not in the decode |
| Trim | 1LT | Maker | GENERAL MOTORS LLC |
| Body | Sedan | Plant | Lordstown, Ohio, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/cruze/2014

**8** recalls listed by Transport Canada for this model year

### Airbag

2025615 6 Nov 2025

Issue: On certain vehicles, the inflator for the side curtain airbag could rupture at the inflator weld joint and cause the side curtain airbag to inflate without a crash. Note: This is an expansion of Transport Canada recall nos. 2023-520 and 2023-693. Certain vehicles that were repaired under those recalls, also require this repair. Safety Risk: A side curtain airbag that inflates without a crash could create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and/or right-side curtain airbag(s).

### Airbag

2023693 21 Dec 2023

Issue: On certain vehicles, the inflator for the side curtain airbag could rupture at the inflator weld joint and cause the side curtain airbag to inflate without a crash. Note: This is an expansion of Transport Canada recall no. 2023-520. Safety Risk: A side curtain airbag that inflates without a crash could create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and/or right-side curtain airbag(s).

### Airbag

2023520 20 Sep 2023

Issue: On certain vehicles, the inflator for the side curtain airbag could rupture at the inflator weld joint and cause the side curtain airbag to inflate without a crash. Safety Risk: A side curtain airbag that inflates without a crash could create a risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and/or right-side curtain airbag(s).

### Accessories

2014274 3 Jul 2014

On certain vehicles, insulation on the engine block heater power cord may become damaged if the cord is handled during very cold days (temperatures below -25C). This could create an electrical shock hazard, which could result in personal injury. Correction: Dealers will replace the block heater cord.

### Airbag

2014250 26 Jun 2014

On certain vehicles, the driver's (frontal) airbag inflator was built with an incorrect part which could cause the inflator to rupture during a deployment. In a crash, this may cause airbag components to separate, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. In some cases, the airbag may not inflate. Failure of the driver airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the driver's (frontal) airbag.

### Powertrain

2014100 31 Mar 2014

On certain vehicles, the passenger side halfshaft could fracture and separate. If this were to occur while the vehicle is being driven, it could result in a loss of motive power. If this were to occur while the vehicle is parked on an incline without the parking brake applied, it could result in unintended vehicle movement. Both situations could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace affected halfshafts. Note: This recall supersedes recalls 2013323. Some vehicles that were inspected and/or repaired under the previous recall will need to be re-inspected and repaired if necessary.

2 more on the model-year record, cardog.app/tools/recalls/chevrolet/cruze/2014

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $6,995[5], the median[4].

| | |
|---|---|
| Lowest ask | $2,999 |
| Middle half | $5,124 – $7,775 |
| Median ask | $6,995 |
| This car | $6,995 |

Same configuration · 27 live listings · as of 28 Oct 2026

### OTHER 2014 CHEVROLET CRUZE LISTINGS [5]

| | |
|---|---|
| Sundridge, ON · 113,267 km | $6,371 |
| Orangeville, ON · 113,267 km | $6,371 |
| Kingston, ON · 199,517 km | $5,990 |
| Orangeville, ON · 113,267 km | $6,371 |
| Orangeville, ON · 113,267 km | $6,371 |
| 100 Mile House, BC · 236,419 km | $2,999 |

## §4 EVENTS

| | |
|---|---|
| 2014 | Model year 2014[1]<br>Assembly plant Lordstown, Ohio, United States |
| 25 Sep 2013 | Transport Canada recall 2013323[2]<br>Issued for the model year · Powertrain |
| 25 Feb 2014 | Transport Canada recall 2014054[2]<br>Issued for the model year · Powertrain |
| 31 Mar 2014 | Transport Canada recall 2014100[2]<br>Issued for the model year · Powertrain |
| 26 Jun 2014 | Transport Canada recall 2014250[2]<br>Issued for the model year · Airbag |
| 3 Jul 2014 | Transport Canada recall 2014274[2]<br>Issued for the model year · Accessories |
| 20 Sep 2023 | Transport Canada recall 2023520[2]<br>Issued for the model year · Airbag |
| 21 Dec 2023 | Transport Canada recall 2023693[2]<br>Issued for the model year · Airbag |
| 6 Nov 2025 | Transport Canada recall 2025615[2]<br>Issued for the model year · Airbag |
| 22 Aug 2026 | Listed for sale, London, ON[5]<br>5 Star Dealers Inc. · asking $6,995 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $6,995 |

## §5 DOCUMENTS

Window sticker — This VIN reads as model year 1984 or 2014, before our coverage for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 27 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.