Register entry, as of 28 October 2026 Listed for sale Record ID 0589b5b41a44

2013 Chevrolet Cruze 2LT

1.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G1	PE5SB	8	D	7	323746
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Cruze · 1.4 L	Verified	2013	Lordstown	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	1.4 L, 4 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Cruze	Drive	Not in the decode
Trim	2LT	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Lordstown, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/cruze/2013

6 recalls listed by Transport Canada for this model year

Steering

2015303 6 Jul 2015

On certain vehicles, the inner tie rod attachment to the steering gear may not have been tightened to specification. With this condition, the tie rod can separate from the steering gear without warning, which could result in a loss of steering control, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the entire steering gear assembly.

Accessories

2014274 3 Jul 2014

On certain vehicles, insulation on the engine block heater power cord may become damaged if the cord is handled during very cold days (temperatures below -25C). This could create an electrical shock hazard, which could result in personal injury. Correction: Dealers will replace the block heater cord.

Airbag

2014250 26 Jun 2014

On certain vehicles, the driver's (frontal) airbag inflator was built with an incorrect part which could cause the inflator to rupture during a deployment. In a crash, this may cause airbag components to separate, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. In some cases, the airbag may not inflate. Failure of the driver airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the driver's (frontal) airbag.

Powertrain

2014100 31 Mar 2014

On certain vehicles, the passenger side halfshaft could fracture and separate. If this were to occur while the vehicle is being driven, it could result in a loss of motive power. If this were to occur while the vehicle is parked on an incline without the parking brake applied, it could result in unintended vehicle movement. Both situations could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace affected halfshafts. Note: This recall supersedes recalls 2013323. Some vehicles that were inspected and/or repaired under the previous recall will need to be re-inspected and repaired if necessary.

Seats and restraints

2014016 21 Jan 2014

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 202 - Head Restraints. If subjected to load in the highest adjustment position, the rear seat head restraints may move to the next lower adjustment position, being displaced in excess of what is allowable in the standard. Correction: No corrective recall action is required as this technical non-compliance is deemed to be non-safety related.

Powertrain

2013323 25 Sep 2013

On certain vehicles equipped with manual transmissions, the passenger side halfshaft could fracture and separate. If this were to occur while the vehicle is being driven, it could result in a loss of motive power. If this were to occur while the vehicle is parked on an incline without the parking brake applied, it could result in unintended vehicle movement. Both situations could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace affected halfshafts.

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,995[5], $748 over the median of $7,247[4].

Lowest ask	$2,495
Middle half	$4,991 – $7,995
Median ask	$7,247
This car	$7,995

Same model year · 18 live listings · as of 28 Oct 2026

OTHER 2013 CHEVROLET CRUZE LISTINGS [5]

Whitby, ON · 96,937 km	$1,622
Chatham, ON · 195,003 km	$7,520
Lac-Etchemin, QC · 110,600 km	$6,995
Blenheim, ON · 195,001 km	$7,520
London, ON · 66,318 km	$9,995
London, ON · 138,506 km	$6,995

§4 EVENTS

2013 Model year 2013[1]
Assembly plant Lordstown, Ohio, United States

25 Sep 2013	Transport Canada recall 2013323[2] Issued for the model year · Powertrain
21 Jan 2014	Transport Canada recall 2014016[2] Issued for the model year · Seats and restraints
31 Mar 2014	Transport Canada recall 2014100[2] Issued for the model year · Powertrain
26 Jun 2014	Transport Canada recall 2014250[2] Issued for the model year · Airbag
3 Jul 2014	Transport Canada recall 2014274[2] Issued for the model year · Accessories
6 Jul 2015	Transport Canada recall 2015303[2] Issued for the model year · Steering
24 Nov 2025	Listed for sale, Oshawa, ON[5] Moon Motors · asking $7,995
27 Oct 2026	Listing last updated[5] asking $7,995

§5 DOCUMENTS

Window sticker — This VIN reads as model year 1983 or 2013, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 18 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.