Register entry, as of 28 October 2026 Listed for sale Record ID 33a1b8c41daf

# 2011 Chevrolet Cruze LT

1.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1G1 | PG5S9 | 0 | B | 7 | 129118 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Chevrolet · GENERAL MOT… | Cruze · 1.4 L | Verified | 2011 | Lordstown | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2011 | Engine | 1.4 L, 4 cylinders |
| Make | Chevrolet | Fuel | Gasoline |
| Model | Cruze | Drive | Not in the decode |
| Trim | LT | Maker | GENERAL MOTORS LLC |
| Body | Sedan | Plant | Lordstown, Ohio, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/cruze/2011

**7** recalls listed by Transport Canada for this model year

### Accessories

2014274 3 Jul 2014

On certain vehicles, insulation on the engine block heater power cord may become damaged if the cord is handled during very cold days (temperatures below -25C). This could create an electrical shock hazard, which could result in personal injury. Correction: Dealers will replace the block heater cord.

### Brakes

2013282 15 Aug 2013

On certain vehicles equipped with a 1.4L DOHC gasoline turbo engine and a 6T40 automatic transmission, the electric vacuum pump (which provides supplemental vacuum under certain operating conditions) may not function as designed. This could result in an intermittent reduction or loss of brake power assist, requiring greater brake pedal effort to slow or stop the vehicle. This could increase stopping distances, which may result in a crash causing property damage and/or personal injury. Correction: Dealers will replace a microswitch in the power brake vacuum pipe assembly.

### Structure

2012188 22 Jun 2012

On certain vehicles, welds may have been omitted from the fuel tank mounting brackets during the vehicle manufacturing process. This could allow fuel leakage to occur as a result of a severe side impact crash. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, secure the fuel tank brackets using fasteners.

### Other

2012187 22 Jun 2012

On certain vehicles, oil spilt as a result of improper engine oil change procedures could contact hot engine or exhaust components, as well as the engine shield, which could cause the shield to ignite and burn. In addition, on vehicles equipped with a manual transmission, continuing to drive with a completely worn clutch may cause hydraulic fluid to be expelled from the clutch housing vent hole. In some instances, the fluid could be burning as it exits the vent hole. If the burning fluid contacts the engine shield, this too could cause the shield to ignite and burn. These issues could cause an engine compartment fire which could result in property damage and/or personal injury. Correction: Dealers will modify the engine shield to prevent fluid from contacting the shield.

### Steering

2011187 5 May 2011

On certain vehicles, the bolt attaching the intermediate steering shaft to the steering gear input shaft may not have been properly installed during vehicle assembly. This could allow the joint to separate, which would result in the loss of steering function. A loss of steering control could result in a crash causing property damage and/or personal injury. Correction: Dealers will inspect and, if required, repair the intermediate shaft/steering gear assembly to ensure the bolt is fully seated and the shaft is properly assembled.

### Other

2011186 5 May 2011

On certain vehicles, the automatic transmission shift linkage may not have been installed correctly during vehicle assembly. As such, the shift lever indicator may not accurately reflect the actual transmission gear selection. This could allow the driver to move the shifter to PARK and remove the ignition key, even if the transmission gear is not in the PARK position. Should the vehicle roll away, whether attended or not, it could strike another vehicle, stationary object, or a bystander, causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, adjust the transmission shift linkage.

1 more on the model-year record, cardog.app/tools/recalls/chevrolet/cruze/2011

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $9,880[5], $4,859 over the median of $5,021[4].

| | |
|---|---|
| Lowest ask | $1,888 |
| Middle half | $3,724 – $5,892 |
| Median ask | $5,021 |
| This car | $9,880 |

Same model year · 15 live listings · as of 28 Oct 2026

### OTHER 2011 CHEVROLET CRUZE LISTINGS [5]

| | |
|---|---|
| Wawa, ON · 166,000 km | $6,566 |
| Sault Ste Marie, ON · 166,000 km | $5,995 |
| Ottawa, ON · 150,171 km | $5,499 |
| Boischatel, QC · 133,901 km | $2,800 |
| Saskatoon, SK · 250,392 km | $6,398 |
| Hamilton, ON · 118,000 km | $6,995 |

## §4 EVENTS

| | |
|---|---|
| 2011 | Model year 2011[1]<br>Assembly plant Lordstown, Ohio, United States |
| 4 Apr 2011 | Transport Canada recall 2011149[2]<br>Issued for the model year · Steering |
| 5 May 2011 | Transport Canada recall 2011187[2]<br>Issued for the model year · Steering |
| 5 May 2011 | Transport Canada recall 2011186[2]<br>Issued for the model year · Other |
| 22 Jun 2012 | Transport Canada recall 2012188[2]<br>Issued for the model year · Structure |
| 22 Jun 2012 | Transport Canada recall 2012187[2]<br>Issued for the model year · Other |
| 15 Aug 2013 | Transport Canada recall 2013282[2]<br>Issued for the model year · Brakes |
| 3 Jul 2014 | Transport Canada recall 2014274[2]<br>Issued for the model year · Accessories |
| 26 Oct 2026 | Listed for sale, Surrey, BC[5]<br>King George Nissan · asking $9,880 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | This VIN reads as model year 1981 or 2011, before our coverage for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 15 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.