Register entry, as of 29 October 2026 Listed for sale Record ID 1d3c4a952ec9

2020 Chevrolet Corvette Preferred 2LT

6.2 L, 8 cylinders · RWD · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G1	Y72D4	6	L	5	109389
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Corvette · 6.2 L	Verified	2020	Bowling Green	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	6.2 L, 8 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Corvette	Drive	RWD
Trim	Preferred 2LT	Maker	GENERAL MOTORS LLC
Body	Coupe	Plant	Bowling Green, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/corvette/2020

4 recalls listed by Transport Canada for this model year

Lights and instruments

2024060 1 Feb 2024

Issue: On certain vehicles, a software problem could cause the lower beam headlamps not to turn on as it becomes dark outside if the multi-function switch is in the "OFF" or "PARKING LAMP" position. This could also cause the daytime running lamps (DRLs) to turn off when the vehicle is moving. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps and/or DRLs that don't turn on could reduce visibility, make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module (BCM)software.

Brakes

2020452 24 Sep 2020

Issue: On certain vehicles, a sensor in the electronic brake boost system may have a bad connection. Under certain driving conditions, this could cause a loss of brake assist. If this happens, there would be a sudden increase in brake pedal force required to slow or stop the vehicle. Safety Risk: Reduced brake performance can cause extended stopping distances and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the electronic brake boost module.

Structure

2020384 18 Aug 2020

Issue: If the front trunk release button on the key fob is accidentally pressed while the vehicle is parked, the front trunk lid can open. If a driver ignores the visual and audible warnings, the vehicle could be driven with a front trunk that is not latched closed. If this happens, wind force could cause the hood to open suddenly while driving at higher speeds. Safety Risk: If the hood opens while driving, it could block the driver's view and increase the risk of a crash. Corrective Actions: General Motors will send a wireless over-the-air update to each vehicle. This will allow you to update the Body Control Module software without having to bring the vehicle to a dealership. The update will limit the vehicle's speed when the hood is not completely closed and latched. The update will also modify the hood release on the key fob and the interior hood release buttons to require a longer press time. Alternatively, you may schedule an appointment to have the update performed by a dealer. General Motors will also mail a copy of this recall notice to all owners.

Other

2020363 6 Aug 2020

Issue: On certain vehicles, the trunk release button that is located inside the front trunk compartment may not work properly. Specifically, ten minutes after the vehicle is powered off, the release may not work. This could prevent a person that is trapped inside the trunk from opening it. Safety Risk: If a person is closed inside the trunk compartment, they may not be able to get out. This could create a risk of injury. Corrective Actions: General Motors will send a wireless over-the-air update to each vehicle. This will allow you to update the Body Control Module software without having to bring the vehicle to a dealership. Alternatively, you may schedule an appointment to have the update performed by a dealer. General Motors will also mail a copy of this recall notice to all owners.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
www.chevrolet.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $79,809[5], $1,173 under the median of $80,982[4].

Lowest ask	$72,998
Middle half	$79,079 – $82,121
Median ask	$80,982
This car	$79,809

Same model year · 12 live listings · as of 29 Oct 2026

OTHER 2020 CHEVROLET CORVETTE LISTINGS [5]

Calgary, AB · 26,258 km	$79,888
Woodbridge, ON · 26,258 km	$79,888
Granby, QC · 17,000 km	$81,985
Barrie, ON · 27,228 km	$79,980
Surrey, BC · 12,500 km	$87,997
Mississauga, ON · 18,057 km	$76,888

§4 EVENTS

2020	Model year 2020[1] Assembly plant Bowling Green, Kentucky, United States
6 Aug 2020	Transport Canada recall 2020363[2] Issued for the model year · Other
18 Aug 2020	Transport Canada recall 2020384[2] Issued for the model year · Structure
24 Sep 2020	Transport Canada recall 2020452[2] Issued for the model year · Brakes
1 Feb 2024	Transport Canada recall 2024060[2] Issued for the model year · Lights and instruments

25 Oct 2026	Listed for sale, Saskatoon, SK[5] Saskatoon Motor Products · asking $79,809
29 Oct 2026	Listing last updated[5] asking $79,809

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 12 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.