Register entry, as of 29 October 2026 Listed for sale Record ID 99b482f79107

2025 Chevrolet Corvette Standard 1LT

6.2 L, 8 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G1	YA2D4	9	S	5	110651
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Corvette · 6.2 L	Verified	2025	Bowling Green	Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	6.2 L, 8 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Corvette	Drive	Not in the decode
Trim	Standard 1LT	Maker	GENERAL MOTORS LLC
Body	Coupe	Plant	Bowling Green, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/corvette/2025

2 recalls listed by Transport Canada for this model year

Lights and instruments

2026165 2 Apr 2026

Issue: On certain vehicles, a software problem could cause the turn signal telltale to flash at the same speed as when a rear turn signal bulb fails. As a result, you may not notice when a rear turn signal bulb is not working. Canadian regulations require a change in the turn signal flash rate when a bulb fails. Safety Risk: A turn signal telltale that doesn't work properly could cause you to be unaware when a turn signal bulb fails. Turn signals that don't work may cause a person not to recognize when a driver intends to turn or change lanes. This could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the exterior lighting control module software. Alternatively, you may schedule an appointment to have the update performed at a GM dealership.

Fuel system

2025429 21 Aug 2025

Issue: On certain vehicles, fuel could spill in the fuel filler pocket when refueling. As a result, fuel could leak onto the left-side radiator and fan assembly. If this happens, the fuel could contact hot surfaces in the engine compartment. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to install a shield to divert spilled fuel.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
www.chevrolet.ca/en/ownercenter/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $87,995[5], $3,107 over the median of $84,888[4].

Lowest ask	$79,810
Middle half	$80,442 – $87,420
Median ask	$84,888
This car	$87,995

Same configuration · 11 live listings · as of 29 Oct 2026

OTHER 2025 CHEVROLET CORVETTE LISTINGS [5]

Orangeville, ON · 1,985 km	$139,890
Edmonton, AB · 2,156 km	$183,999
Winnipeg, MB · 2,156 km	$159,999
Regina, SK · 2,156 km	$159,999
Winnipeg, MB · 2,156 km	$159,999
Saint-Jean-Sur-Richelieu, QC · 7,573 km	$94,911

§4 EVENTS

2025	Model year 2025[1] Assembly plant Bowling Green, Kentucky, United States
21 Aug 2025	Transport Canada recall 2025429[2] Issued for the model year · Fuel system
2 Apr 2026	Transport Canada recall 2026165[2] Issued for the model year · Lights and instruments
28 Oct 2026	Listed for sale, Brampton, ON[5] Policaro BMW · asking $87,995

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 11 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.