Register entry, as of 5 November 2026 Listed for sale Record ID 08350c26cbc0

# 2014 Chevrolet Corvette LT1

6.2 L, 8 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1G1 | YA3D7 | 1 | E | 5 | 126136 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Chevrolet · GENERAL MOT… | Corvette · 6.2 L | Verified | 2014 | Bowling Green | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2014 | Engine | 6.2 L, 8 cylinders |
| Make | Chevrolet | Fuel | Gasoline |
| Model | Corvette | Drive | Not in the decode |
| Trim | LT1 | Maker | GENERAL MOTORS LLC |
| Body | Convertible | Plant | Bowling Green, Kentucky, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/corvette/2014

**4** recalls listed by Transport Canada for this model year

### Airbag — 2016439 — 9 Sep 2016

On certain vehicles, the sensing and diagnostic module (SDM), which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain circumstances. Failure of frontal airbags and seatbelt pretensioners to deploy in a crash (when warranted) could increase the risk of injury. Correction: Dealers will reflash the SDM with new software. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software. Note: This recall affects 2014-2017 model year Sierra LD/Silverado LD models and 2015-2016 model year Sierra HD/Silverado HD model vehicles.

### Suspension — 2014253 — 27 Jun 2014

On certain vehicles, an improper weld on the rear shock absorbers may lead to separation of the shock absorber tube from the shock absorber clevis bracket. If such a separation was to occur, a sudden change of vehicle handling behaviour would result that may startle drivers, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace both rear shock absorbers.

### Airbag — 2014240 — 19 Jun 2014

Certain vehicles equipped with optional sport seats may pose a greater risk of neck injury for small children who are unbelted, out-of-position, and leaning against the side airbag in the event of a crash involving a side airbag deployment. Note: Drivers should not allow a small child to sit in the passenger seat until recall repairs are completed. Correction: Dealers will replace the passenger side airbag.

### Airbag

2014215 6 Jun 2014

On certain vehicles, an internal fault in the Sensing and Diagnostic Module may set a diagnostic trouble code, illuminating the airbag warning lamp and disabling the airbags and seatbelt pretensioners. The occupant sensing passenger airbag light would also not illuminate. This could increase the risk of injury in a crash. Correction: Dealers will replace the Sensing and Diagnostic Module.

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $49,800[5], $5,149 under the median of $54,949[4].




| | |
|---|---|
| Lowest ask | $49,800 |
| Middle half | $52,875 – $56,724 |
| Median ask | $54,949 |
| This car | $49,800 |

Same model year · 4 live listings · as of 5 Nov 2026

## §4 EVENTS

| | |
|---|---|
| 2014 | Model year 2014[1]<br>Assembly plant Bowling Green, Kentucky, United States |
| 6 Jun 2014 | Transport Canada recall 2014215[2]<br>Issued for the model year · Airbag |
| 19 Jun 2014 | Transport Canada recall 2014240[2]<br>Issued for the model year · Airbag |
| 27 Jun 2014 | Transport Canada recall 2014253[2]<br>Issued for the model year · Suspension |
| 9 Sep 2016 | Transport Canada recall 2016439[2]<br>Issued for the model year · Airbag |
| 4 Mar 2026 | Listed for sale, Burnaby, BC[5]<br>KNN AUTO Wholesale Limited · asking $49,800 |
| 5 Nov 2026 | Listing last updated[5]<br>asking $49,800 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | This VIN reads as model year 1984 or 2014, before our coverage for this manufacturer. |

## SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 4 live listings, as of 5 Nov 2026

[5] Live public dealer listings on Cardog, as of 5 Nov 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.