Register entry, as of 29 October 2026 Listed for sale Record ID 9723514a1752

2015 Chevrolet Corvette Stingray 2LT w/Z51

6.2 L, 8 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G1	YJ2D7	4	F	5	109536
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Corvette · 6.2 L	Verified	2015	Bowling Green	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	6.2 L, 8 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Corvette	Drive	Not in the decode
Trim	Stingray 2LT w/Z51	Maker	GENERAL MOTORS LLC
Body	Coupe	Plant	Bowling Green, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/corvette/2015

5 recalls listed by Transport Canada for this model year

Airbag

2017342 10 Jul 2017

On certain vehicles, the sensing and diagnostic module (SDM), which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain circumstances. Failure of frontal airbags and seatbelt pretensioners to deploy in a crash (when warranted) could increase the risk of injury. Correction: Dealers will reflash the SDM with new software. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software.

Airbag

2016439 9 Sep 2016

On certain vehicles, the sensing and diagnostic module (SDM), which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain circumstances. Failure of frontal airbags and seatbelt pretensioners to deploy in a crash (when warranted) could increase the risk of injury. Correction: Dealers will reflash the SDM with new software. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software. Note: This recall affects 2014-2017 model year Sierra LD/Silverado LD models and 2015-2016 model year Sierra HD/Silverado HD model vehicles.

Suspension

2015023 22 Jan 2015

On certain vehicles, the right rear toe link outer ball joint may not have been properly fastened to the knuckle. This may result in rear suspension noise, particularly when travelling around corners or over bumps or potholes. Over time, if the vehicle is continually operated with this condition, the toe link could separate from the knuckle, causing sudden vehicle instability and increasing the risk of a crash causing personal injury or property damage. Dealers will inspect and replace any damaged parts as necessary. If no damage is noted, the dealer will reassemble the toe link with a new fastener and tighten to specification.

Airbag

2014407 18 Sep 2014

On certain vehicles, a defect in the driver frontal airbag could allow the airbag to separate from its backing plate upon deployment, increasing the risk of injury to the seat occupant in a crash where airbag deployment is warranted. Correction: Dealers will replace the airbag.

Brakes

2014405 18 Sep 2014

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 135 - Brake Systems. One of the parking brake cables may not have been installed correctly, which would result in the parking brake being operational on one rear wheel only, causing a reduction in parking brake performance and causing the vehicle to fail to meet the requirements of the standard. This could result in unintended vehicle movement, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will inspect, and if necessary, re-install the park brake cable.

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $49,900[5], $10,095 under the median of $59,995[4].

Lowest ask	$45,788
Middle half	$55,747 – $61,948
Median ask	$59,995
This car	$49,900

Same model year · 11 live listings · as of 29 Oct 2026

OTHER 2015 CHEVROLET CORVETTE LISTINGS [5]

Woodbridge, ON · 19,300 km	$58,995
Rouyn Noranda, QC · 92,500 km	$59,995
Lacombe, AB · 60,137 km	$59,888
Brampton, ON · 117,887 km	$45,788
Gananoque, ON · 8,241 km	$8,908,995

§4 EVENTS

2015	Model year 2015[1] Assembly plant Bowling Green, Kentucky, United States
18 Sep 2014	Transport Canada recall 2014407[2] Issued for the model year · Airbag
18 Sep 2014	Transport Canada recall 2014405[2] Issued for the model year · Brakes
22 Jan 2015	Transport Canada recall 2015023[2] Issued for the model year · Suspension

9 Sep 2016	Transport Canada recall 2016439[2] Issued for the model year · Airbag
10 Jul 2017	Transport Canada recall 2017342[2] Issued for the model year · Airbag
28 Oct 2026	Listed for sale, Edmonton, AB[5] Lakewood Chevrolet · asking $49,900

§5 DOCUMENTS

Window sticker — This VIN reads as model year 1985 or 2015, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 11 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.